



report date: 2024-03-29

General information

Make	CITROEN
Model	NEMO 610 LX HDI
Colour	Red
Year of manufacture	2010
Top speed	94 mph
0 - 60 mph	16.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	70 BHP
Max. torque	160 Nm at 1.750 rpm
Engine capacity	1.399 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-10-18
Pictures	20
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-11-13
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	12
Total items failed	16

MOT #16	2023-11-13 13:34
MOT test number	947274624049
Result	✓ Passed
Next expiry date	2024-11-13
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #15	2022-11-14 16:32
MOT test number	835971533598
Result	✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Coil spring corroded (5.3.1 (b) (i))

**MOT #14**

2022-11-14 12:05

MOT test number

887497470002

Result**✗ Failed****Fail** Offside Rear Stop lamp(s) adversely affected by the operation of another lamp (4.3.3 (b))**Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Offside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))**Fail** Nearside Rear Stop lamp(s) adversely affected by the operation of another lamp (4.3.3 (b))**Fail** Nearside Rear Position lamp not working (4.2.1 (a) (ii))**Fail** Nearside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))**MOT #13**

2021-10-04 11:08

MOT test number

862605780246

Result**✓ Passed****MOT #12**

2021-10-01 15:24

MOT test number

465463156552

Result**✗ Failed****Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**Fail** Offside Rear Stop lamp(s) adversely affected by the operation of another lamp (4.3.3 (b))**Fail** Tyre tread depth below requirements of 1.6mm both front (5.2.3 (e))**Fail** Offside Rear Position lamp adversely affected by the operation of another lamp (4.2.3 (c))

**MOT #11** 2020-11-02 16:40**MOT test number** 732972546582**Result** ✓ Passed**Advice** Rear shock top bushes perishing**MOT #10** 2019-11-01 10:47**MOT test number** 534976263777**Result** ✓ Passed**MOT #9** 2018-10-12 10:47**MOT test number** 379224179666**Result** ✓ Passed**MOT #8** 2018-10-12 10:47**MOT test number** 985742699751**Result** ✗ Failed**Pass with rectification** Nearside Rear Position lamp has a product on the lens or light source which shows white light to the rear (4.2.3 (b) (ii))**Pass with rectification** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #7** 2017-11-02 09:46**MOT test number** 131345024915**Result** ✓ Passed**MOT #6** 2016-10-31 09:04**MOT test number** 120416013864**Result** ✓ Passed**MOT #5** 2015-11-02 12:39**MOT test number** 395637922679**Result** ✓ Passed

**MOT #4** 2014-11-04 14:22**MOT test number** 736968604397**Result** ✓ Passed**MOT #3** 2014-11-04 14:22**MOT test number** 465748304322**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too high (1.8)**Pass with rectification** Offside Headlamp aim too high (1.8)**MOT #2** 2014-02-10 10:58**MOT test number** 509991244089**Result** ✓ Passed**MOT #1** 2014-02-07 17:29**MOT test number** 159168634449**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
13 November 2024

Tax status	Valid until 1 March
------------	---------------------

Days left	305
-----------	-----

MOT expiry date	13 November 2024
-----------------	------------------

Full MOT history	See MOT history
------------------	---------------------------------



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-07-09
Last registration	2023-11-13
Complete history	See info



Registration #1	2010-07-09	22 mi
Registration #2	2014-02-07	33.312 mi
Registration #3	2014-02-10	33.313 mi
Registration #4	2014-11-04	46.858 mi
Registration #5	2015-11-02	52.460 mi
Registration #6	2016-10-31	55.649 mi
Registration #7	2017-11-02	65.636 mi
Registration #8	2018-10-12	77.022 mi
Registration #9	2018-10-12	77.022 mi
Registration #10	2019-05-29	78.277 mi
Registration #11	2019-05-29	78.277 mi
Registration #12	2019-05-29	78.277 mi
Registration #13	2019-05-29	78.277 mi
Registration #14	2019-05-29	78.277 mi
Registration #15	2019-05-29	78.277 mi
Registration #16	2019-05-29	78.277 mi
Registration #17	2019-05-29	78.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	59%
Children	74%
Pedestrian	55%
Safety systems	29%
Overall rating	58%
Video	see crash video



Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	FD982601830