



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	CELICA VVTI BLUE
Colour	Blue
Year of manufacture	2005
Top speed	127 mph
0 - 60 mph	8.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	172 Nm at 4.200 rpm
Engine capacity	1.794 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	45.6 mpg
Consumption combined	36.7 mpg
CO2 emission	185 g/km
CO2 label	I









Internet history

Entry 1

Date	2022-02-21
Pictures	8
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-10-10
MOT pass rate	80 %
MOT passed	16
Failed MOT tests	4
Total advice items	18
Total items failed	4

MOT #20	2023-10-11 11:02
MOT test number	291399470769
Result	✓ Passed
Next expiry date	2024-10-10
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
Advice	Rear Suspension component corroded
Advice	Rear Service brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))

**MOT #19** 2023-09-27 09:44**MOT test number** 327277511083**Result** ✗ Failed

- Advice** Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- MAJOR** Oil leaking excessively from engine (8.4.1 (a) (i))
- MAJOR** Emissions unable to be completed Due to oil leak (8.2.1.2 (d))
- MAJOR** Rear fog lamp not working (4.5.1 (a) (ii))
- MAJOR** Offside Headlamp aim too low and too far to the right. (4.1.2 (a))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear Service brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))
- MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Advice** Rear Suspension component corroded

MOT #18 2022-09-24 15:27**MOT test number** 246590443548**Result** ✓ Passed

- Advice** Headlamp has a product on the lens but not seriously reducing light output Both (4.1.4 (b))
- Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Exhaust noisy (8.1.1 (a))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #17 2021-02-23 10:27**MOT test number** 818936903238**Result** ✓ Passed



MOT #16	2020-03-17 09:03
MOT test number	734166040847
Result	✓ Passed
MOT #15	2019-03-05 10:32
MOT test number	257036924998
Result	✓ Passed
MOT #14	2018-03-19 13:41
MOT test number	807090221788
Result	✓ Passed
MOT #13	2017-02-23 11:33
MOT test number	327389337892
Result	✓ Passed
MOT #12	2016-03-17 09:25
MOT test number	463973463724
Result	✓ Passed
MOT #11	2015-02-26 09:22
MOT test number	377897855005
Result	✓ Passed
MOT #10	2014-02-27 09:39
MOT test number	649328754006
Result	✓ Passed
MOT #9	2013-03-21 08:34
MOT test number	399350283062
Result	✓ Passed

**MOT #8** 2013-03-21 08:34**MOT test number** 329570883018**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp aim too far to the right (1.8)**MOT #7** 2012-03-14 12:05**MOT test number** 758754272081**Result** ✓ Passed**MOT #6** 2011-03-12 10:32**MOT test number** 695821671098**Result** ✓ Passed**MOT #5** 2010-03-19 10:56**MOT test number** 242598170093**Result** ✓ Passed**MOT #4** 2010-03-13 09:57**MOT test number** 284312470078**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #3** 2009-03-21 11:24**MOT test number** 110100589474**Result** ✓ Passed



MOT #2	2009-03-14 10:57
MOT test number	770333379088
Result	✗ Failed
Fail	Offside Rear brake disc excessively scored (3.5.1h)
Fail	Nearside Rear brake disc excessively scored (3.5.1h)

MOT #1	2008-03-18 11:52
MOT test number	731368078021
Result	✓ Passed



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	GU05XEK
Plate since	2019-03-29
Current registration	GU05XEK
Plate since	2019-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2005-03-22
Last registration	2023-10-11
Complete history	See info



Registration #1	2005-03-22	18 mi
Registration #2	2008-03-18	35.517 mi
Registration #3	2009-03-14	43.763 mi
Registration #4	2009-03-21	43.796 mi
Registration #5	2010-03-13	51.467 mi
Registration #6	2010-03-19	51.615 mi
Registration #7	2011-03-12	61.351 mi
Registration #8	2012-03-14	67.103 mi
Registration #9	2013-03-21	75.024 mi
Registration #10	2014-02-27	49.243 mi
Registration #11	2015-02-26	87.212 mi
Registration #12	2016-03-22	95.337 mi
Registration #13	2017-03-22	103.337 mi
Registration #14	2018-03-22	111.337 mi
Registration #15	2019-03-22	119.337 mi
Registration #16	2020-03-22	127.337 mi
Registration #17	2021-03-22	135.337 mi
Registration #18	2022-03-22	143.337 mi
Registration #19	2023-03-22	151.337 mi
Registration #20	2024-03-22	159.337 mi
Registration #21	2025-03-22	167.337 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1735 mm
Height	1315 mm
Length	4350 mm
Wheel base	2600 mm
Kerb weight	1145 kg
Max. allowed weight	1565 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	1ZZ2317949