



report date: 2024-03-29

## General information

Make	NISSAN
Model	NOTE DCI ACENTA PREMIUM
Colour	Silver
Year of manufacture	2014
Top speed	111 mph
0 - 60 mph	11.5 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	90 BHP
Max. torque	200 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	65.7 mpg
Consumption extra urban	88.3 mpg
Consumption combined	78.5 mpg
CO2 emission	90 g/km
CO2 label	A







Internet history

Entry 1

Date	2021-06-17
Pictures	24
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-08-10
MOT pass rate	58 %
MOT passed	7
Failed MOT tests	5
Total advice items	19
Total items failed	23

MOT #12	2023-08-11 12:16
MOT test number	975433207282
Result	✓ Passed
Next expiry date	2024-08-10

MOT #11	2023-08-11 08:25
MOT test number	568307323469
Result	✗ Failed
Fail	Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
Fail	Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))
Fail	Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Fail	Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
Fail	Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #10	2022-07-27 12:32
MOT test number	703557718854
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #9 2022-07-22 12:42

MOT test number 608172073040

Result		✗ Failed
Fail	Nearside Front Brake pipe excessively corroded (1.1.11 (c))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail	Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))	
Fail	Offside Front Brake pipe excessively corroded (1.1.11 (c))	
Fail	Fuel tank exhaust shield missing where fitted as original equipment creating a risk of fire (6.1.3 (e))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #8 2021-08-07 11:24

MOT test number 918909547305

Result		✓ Passed
--------	--	----------

**MOT #7**

2021-08-06 10:35

**MOT test number**

734654442290

**Result****✗ Failed**

- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Heatshields loose
- Fail** Nearside Front Wheel bearing has excessive play (5.1.3 (a) (i))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

**MOT #6**

2020-06-26 16:37

**MOT test number**

351291874790

**Result****✓ Passed**

- Advice** Brake disc worn, pitted or scored, but not seriously weakened Front inner faces (1.1.14 (a) (ii))
- Advice** Front tyres wearing on outer edges
- Advice** Suspension arm pin or bush worn but not resulting in excessive movement Both front (5.3.4 (a) (i))
- Advice** Engine covers and under trays fitted obscuring some testable items

**MOT #5** 2020-06-26 16:37**MOT test number** 328002219832**Result** ✗ Failed**Advice** Suspension arm pin or bush worn but not resulting in excessive movement Both front (5.3.4 (a) (i))**Advice** Front tyres wearing on outer edges**Advice** Brake disc worn, pitted or scored, but not seriously weakened Front inner faces (1.1.14 (a) (ii))**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**Advice** Engine covers and under trays fitted obscuring some testable items**MOT #4** 2019-03-23 14:46**MOT test number** 124943548648**Result** ✓ Passed**MOT #3** 2019-03-23 12:04**MOT test number** 754391577664**Result** ✗ Failed**Fail** Nearside Front Position lamp not working (4.2.1 (a))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Fail** Offside Rear fog lamp not working (4.5.1 (a) (ii))**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #2** 2017-12-19 09:32**MOT test number** 880443301559**Result** ✓ Passed



MOT #12017-07-04 10:44

MOT test number160266695263

Result

✓ Passed

Advice

Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice

Nearside Front Brake pad(s) wearing thin (3.5.1g)

Advice

Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice

Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice

Offside Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
10 August 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	93
<b>MOT expiry date</b>	10 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable





Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-07-04
Last registration	2023-08-11
Complete history	<a href="#">See info</a>



Registration #1	2014-07-04	23 mi
Registration #2	2017-07-04	22.242 mi
Registration #3	2017-12-19	25.297 mi
Registration #4	2019-03-23	36.246 mi
Registration #5	2019-03-23	36.246 mi
Registration #6	2020-06-26	46.888 mi
Registration #7	2020-06-26	46.888 mi
Registration #8	2020-06-26	46.888 mi
Registration #9	2020-06-26	46.888 mi
Registration #10	2020-06-26	46.888 mi
Registration #11	2020-06-26	46.888 mi
Registration #12	2020-06-26	46.888 mi
Registration #13	2020-06-26	46.888 mi
Registration #14	2020-06-26	46.888 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	86%
Children	82%
Pedestrian	58%
Safety systems	70%
Overall rating	78%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1695 mm
Height	1530 mm
Length	4100 mm
Wheel base	2600 mm
Kerb weight	1129 kg
Max. allowed weight	1615 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	D349644