





report date: 2024-03-28

General information

Make	CITROEN
Model	DS3 E-HDI DSTYLE PLUS
Colour	White
Year of manufacture	2013
Top speed	113 mph
0 - 60 mph	12.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	85.6 mpg
Consumption combined	76.4 mpg
CO2 emission	98 g/km
CO2 label	A



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-01-29 3

Pictures

Listing price View report







source: autoonline.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

	~		
10/1/	1	hic	tory
- 1010	,, ,	1115	IUIV
	<i>-</i> .		

MOT expiry date	2024-11-30
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	19
Total items failed	1

MOT #12	2023-11-11 11:01
MOT test number	649761381195
Result	✓ Passed
Next expiry date	2024-11-30
Advice Offside front tyre close to legal limit	
Advice Offside rear brake disc slightly corroded	

MOT #11		2022-11-28 10:54
MOT test	number	269808800720
Result		✓ Passed
Advice	Nearside Front Tyre slightly damaged (5.2.3 (d) (ii))	
Advice	Nearside front tyre worn close to wear bars	
Advice	Offside Rear Brake disc worn, but not excessively inner face (1.1.14 (a) (i))	
Advice	Nearside Rear Brake disc worn, but not excessively inner face (1.1.14 (a) (i))	
Advice	Offside Rear Tyre slightly damaged (5.2.3 (d) (ii))	
Advice	Exhaust bracket before tail box missing	

MOT #10	2021-12-01 11:15
MOT test number	943653611095
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #9 2021-01-09 12:33

MOT test number 661906252034

Result ✓ Passed

MOT #8 2020-03-10 15:10

MOT test number 804357640483

Result

Passed

Advice Rear Exhaust mounting defective (6.1.2 (a))

Advice Nearside Front Tyre worn close to legal limit/worn on edge 2.6mm bold on inner edge (5.2.3 (e))

MOT #7 2020-03-10 11:40

MOT test number 989497182157

Result X Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge 2.6mm bold on inner edge (5.2.3 (e))

Advice Rear Exhaust mounting defective (6.1.2 (a))

MAJOR Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #6 2019-03-06 16:49

MOT test number 757982271084

Result

Passed

MOT #5 2018-06-04 13:30

MOT test number 628396613086

Result
✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #4 2018-06-04 12:04

MOT test number 377995352860

Result X Failed

MAJOR Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice Rear exhaust lose

MAJOR Nearside Front Position lamp not working (4.2.1 (a))

MAJOR Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #3 2017-06-16 15:15

MOT test number 523424178439

Result
✓ Passed

Advice Offside Front Tyre worn close to the legal limit 2mm + edge wear (4.1.E.1)

MOT #2 2017-06-16 14:25

MOT test number 988363615988

Result × Failed

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit 2mm + edge wear (4.1.E.1)

MOT #1 2016-06-03 15:29

MOT test number 344748778215

CarCheck.co.uk page 5/12



BG13XUS report date: 2024-03-28

Tax & MOT check





Expires: 30 November 2024

Tax status	Valid until 1 December
Days left	217
MOT expiry date	30 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



factor scincore

BG13XUS

report date: 2024-03-28

More info >

Owner history For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this CITROEN had different number plates.

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-06-27
Last registration	2023-11-11
Complete history	See info



Registration #1	2013-06-27	9 mi
Registration #2	2016-06-03	24.705 mi
Registration #3	2017-06-16	37.475 mi
Registration #4	2017-06-16	37.475 mi
Registration #5	2018-06-04	49.769 mi
Registration #6	2018-06-04	49.769 mi
Registration #7	2019-03-06	56.332 mi
Registration #8		11.177 es
Registration #9		11.777 es
Registration #10		11.177 es
Registration #11		11.777 mi
Registration #12		11.117 es
Registration #13		11.777 es

7075.75.75

More info >

77.777 86

CarCheck.co.uk page 11/12



BG13XUS
report date: 2024-03-28

Safety ratings

NCAP rating	****
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1728 mm
Height	1524 mm
Length	3941 mm
Wheel base	2464 mm
Kerb weight	1085 kg
Max. allowed weight	1602 kg

Additional information

Fuel tank capacity	48 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	JBFM3067047

CarCheck.co.uk page 12/12