



ST56EEV

report date: 2024-03-29

General information

Make	FIAT
Model	PUNTO ACTIVE
Colour	Black
Year of manufacture	-
Top speed	96 mph
0 - 60 mph	14.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	65 BHP
Max. torque	102 Nm at 5.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	57.6 mpg
Consumption combined	47.9 mpg



LABEL UNKNOWN



Internet history

Entry 2

Date	2021-06-04
Pictures	2
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 1

Date	2021-05-28
Pictures	2
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT #22	2023-06-20 13:49
MOT test number	934708488036
Result	✓ Passed
Next expiry date	2024-06-19

MOT #21	2022-06-17 10:58
MOT test number	241171187600
Result	✓ Passed

**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #20	2022-06-14 08:29
MOT test number	350538389721

Result	✗ Failed
--------	----------

**DANGEROUS** Offside Front Inner Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

**DANGEROUS** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

**MAJOR** Offside Headlamp insecure (4.1.1 (c))

**MAJOR** Nearside Front Coil spring corroded so that its cross sectional area is reduced and seriously weakened (5.3.1 (b) (i))

**Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MAJOR** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**MAJOR** Offside Front Coil spring corroded so that its cross sectional area is reduced and seriously weakened (5.3.1 (b) (i))

MOT #19	2021-01-22 10:16
MOT test number	276421922726
Result	✓ Passed

**MOT #18** 2021-01-22 10:16**MOT test number** 795904830926**Result** ✗ Failed**Pass with rectification** Nearside Rear Position lamp not working (4.2.1 (a) (ii))**MOT #17** 2020-01-17 11:11**MOT test number** 631542830136**Result** ✓ Passed**Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**MOT #16** 2020-01-17 09:24**MOT test number** 649486172173**Result** ✗ Failed**MAJOR** Offside Front Suspension arm corroded and seriously weakened (5.3.3 (b) (i))**Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**MAJOR** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #15** 2019-02-07 17:11**MOT test number** 958022420662**Result** ✓ Passed**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #14** 2019-02-07 17:11**MOT test number** 157836664859**Result** ✗ Failed**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #13**

2018-03-23 15:58

**MOT test number**

870125657197

**Result**

✓ Passed

- Advice** Offside Front coil spring worn (2.4.C.1b)
- Advice** Front Anti-roll bar has slight play in a ball joint both x2 (2.4.G.2)
- Advice** Nearside Front coil spring corroded (2.4.C.1b)
- Advice** Rear coil spring corroded both (2.4.C.1b)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened both x2 (3.5.1i)

**MOT #12**

2017-03-27 12:41

**MOT test number**

720660651379

**Result**

✓ Passed

- Advice** Nearside Front coil spring worn (2.4.C.1b)
- Advice** Offside Rear coil spring worn (2.4.C.1b)
- Advice** Nearside Rear coil spring worn (2.4.C.1b)

**MOT #11**

2016-03-24 13:30

**MOT test number**

120127196793

**Result**

✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #10** 2015-03-30 17:28**MOT test number** 195289485045**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #9** 2014-07-25 16:52**MOT test number** 648706104273**Result** ✓ Passed**Notice** Nearside front tyre has cut in sidewall not deep enough to show cords**Notice** Nearsude rear tyre sidewall cracking**Notice** Offside rear tyre sidewall cracking**Notice** Radiator shows signs of a leak**MOT #8** 2013-07-17 16:12**MOT test number** 259048793191**Result** ✓ Passed**MOT #7** 2013-07-17 10:26**MOT test number** 688938393173**Result** ✗ Failed**Fail** Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**MOT #6** 2012-07-13 16:37**MOT test number** 656955392129**Result** ✓ Passed

**MOT #5** 2012-07-13 13:33**MOT test number** 865545492150**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Fail** Offside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**MOT #4** 2011-07-15 12:07**MOT test number** 255826891433**Result** ✓ Passed**MOT #3** 2011-07-15 12:07**MOT test number** 327166091168**Result** ✗ Failed**Pass with rectification** Offside Front Tyre(s) incorrect because different size tyres are fitted on the same axle. (4.1.A.1a)**MOT #2** 2010-01-15 16:20**MOT test number** 874645110000**Result** ✓ Passed**MOT #1** 2010-01-15 11:03**MOT test number** 122685210029**Result** ✗ Failed**Fail** Nearside Front coil spring fractured (2.4.C.1a)**Fail** Nearside Front Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2)**Fail** Offside Front coil spring fractured (2.4.C.1a)



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2006-09-28
Last registration	2023-06-20
Complete history	<a href="#">See info</a>



Registration #1	2006-09-28	10 mi
Registration #2	2010-01-15	8.486 mi
Registration #3	2010-01-15	8.486 mi
Registration #4	2011-07-15	10.844 mi
Registration #5	2012-07-13	11.502 mi
Registration #6	2012-07-13	11.502 mi
Registration #7	2013-07-17	14.919 mi
Registration #8	2013-07-17	14.919 mi
Registration #9	2014-07-25	17.376 mi
Registration #10	2015-03-30	17.889 mi
Registration #11	2016-03-24	25.884 mi
Registration #12	2017-03-27	33.370 mi
Registration #13	2018-03-27	33.370 mi
Registration #14	2018-03-27	33.370 mi
Registration #15	2018-03-27	33.370 mi
Registration #16	2018-03-27	33.370 mi
Registration #17	2018-03-27	33.370 mi
Registration #18	2018-03-27	33.370 mi
Registration #19	2018-03-27	33.370 mi
Registration #20	2018-03-27	33.370 mi
Registration #21	2018-03-27	33.370 mi
Registration #22	2018-03-27	33.370 mi
Registration #23	2018-03-27	33.370 mi
Registration #24	2018-03-27	33.370 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1030 kg
Max. allowed weight	2490 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Engine number	3388181
---------------	---------