





## General information

Make	VAUXHALL
Model	MERIVA S AC
Colour	Red
Year of manufacture	2013
Top speed	110 mph
0 - 60 mph	13.9 seconds
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	99 BHP
Max. torque	130 Nm at 4.000 rpm
Engine capacity	1.398 cc
Cylinders	4
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	140 g/km
CO2 label	E







## Internet history

Entry 1

Date Pictures 2021-08-11

5

Listing price

View report



source: cargurus.co.uk



# MOT history

MOT expiry date	2024-08-09
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	12
Total items failed	4

MOT #13	2023-08-09 09:42
MOT test number	898163969139
Result	✓ Passed
Next expiry date 2024-08-0	
Advice Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))	

MOT #12		2023-08-09 09:42
MOT test number		537095252749
Result		🗙 Failed
Advice Front Brake disc	worn, pitted or scored, but not seriously	weakened both (1.1.14 (a) (ii))
Pass with rectification	Rear Registration plate lamp does not i	lluminate simultaneously with the
position lamps (4.7.2 (a))		

MOT #11	2022-08-10 10:19
MOT test number	151425259910
Result	✓ Passed

MOT #10		2022-08-10 10:19
MOT test number		127032675870
Result		🗙 Failed
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))	



MOT #9		2022-08-09 13:56
MOT test numbe	er	709472100628
Result		🗙 Failed
Advice Offsic	de Rear Tyre slightly damaged (5.2.3 (d) (ii))	
Advice Rear	Brake disc worn, but not excessively (1.1.14 (a) (i))	
DANGEROUS	Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
DANGEROUS	Tyre tread depth below requirements of 1.6mm Both Front (5.2.3 (e))	

MOT #8	2021-08-09 14:09
MOT test number	497835252191
Result	✓ Passed

MOT #7	2020-10-23 12:04
MOT test number	350719527685
Result	✓ Passed
Advice Door lock sign always ON on the dashboard	

МОТ #6	2020-10-22 15:44
MOT test number	764078149730
Result	🗙 Failed
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
<b>DANGEROUS</b> Offside Rear Tyre has a tear, caused by separation or partial failure of(d) (ii))	f its structure (5.2.3
Advice Door lock sign always ON on the dashboard	

MOT #5	2019-10-15 09:05
MOT test number	432990777521
Result	✓ Passed

WD630J0 report date: 2024-03-29





MOT #4		2018-10-20 10:00
MOT test number		939065989266
Result		✓ Passed
Advice Offside Front Ty	re worn close to legal limit/worn on edge (5.2.3 (e))	
MOT #3		2017-10-19 08:24
MOT test number		242391556887
Result		Passed
MOT #2		2017-10-19 08:24
MOT test number		118027185894
Result		🗙 Failed
Pass with rectification	Offside Headlamp aim too low (1.8)	
Pass with rectification	Nearside Headlamp aim too low (1.8)	
MOT #1		2016-10-24 08:29
MOT test number		483792129203
Result		✓ Passed

\_\_\_\_\_

Advice

Nearside Rear light lens slightly damaged



Tax & MOT check

√ Taxed	√ МОТ
Tax due: 1 September 2024	Expires: 9 August 2024
Tax status	Valid until 1 September
Days left	124
MOT expiry date	9 August 2024
Full MOT history	<u>See MOT history</u>

# Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-





## Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	L AMP
Туре	
Damage 2	AMPLE
Date	4
Category	AMPL
Туре	

#### Extra VAUXHALL salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





## Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





# Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

**********	
AND	
**********	
NUMBER OF CONTRACTOR OF CONTRA	
	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





## Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-12-09
Last registration	2023-08-09
Complete history	See info



Registration #1	2013-12-09	15 mi
Registration #2	2016-10-24	24.560 mi
Registration #3	2017-10-19	29.980 mi
Registration #4	2017-10-19	29.980 mi
Registration #5	2018-10-20	36.058 mi
Registration #6	2019-10-15	41.944 mi
Registration #7	2020-10-22	46.240 mi
Registration #8	2020-10-23	46.240 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 est
Registration #15		11.777 mi





# Safety ratings

NCAP rating	****
Adult	89%
Children	77%
Pedestrian	55%
Safety systems	86%
Overall rating	80%
Video	see crash video



Dimensions & weight	
Width	1812 mm
Height	1615 mm
Length	4288 mm
Wheel base	2644 mm
Kerb weight	1301 kg
Max. allowed weight	1905 kg
Additional information	
Fuel tank capacity	70
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5