



report date: 2024-03-29

General information

Make	FORD
Model	FIESTA EDGE
Colour	Black
Year of manufacture	2010
Top speed	104 mph
0 - 60 mph	13.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	81 BHP
Max. torque	114 Nm at 4.200 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	62.8 mpg
Consumption combined	50.4 mpg
CO2 emission	129 g/km
CO2 label	D






Internet history

Entry 1

Date	2021-02-17
Pictures	11
Listing price	<a href="#">View report</a>



source: yesauto.com



## MOT history

MOT expiry date	2025-01-08
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	11
Total items failed	21

MOT #19	2024-01-09 14:38
MOT test number	281060323043
Result	✓ Passed
Next expiry date	2025-01-08

MOT #18	2024-01-09 14:38
MOT test number	354711985449
Result	✗ Failed
Pass with rectification	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
Pass with rectification	Nearside Rear Direction indicator incorrect colour (4.4.3 (a))

MOT #17	2023-03-24 11:31
MOT test number	202481339316
Result	✓ Passed
Advice	Nearside Front Coil spring corroded (5.3.1 (b) (i))
Advice	Brake pedal wearing smooth (1.1.2 (c))

**MOT #16** 2023-03-23 17:28**MOT test number** 225454191399**Result** ✗ Failed**Fail** Emissions unable to be completed (8.2.1.2 (d))**Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))**Advice** Brake pedal wearing smooth (1.1.2 (c))**MOT #15** 2022-04-05 11:59**MOT test number** 867068803576**Result** ✓ Passed**Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #14** 2021-04-06 14:00**MOT test number** 763064055925**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #13** 2020-09-25 10:30**MOT test number** 515018675200**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12** 2020-09-24 16:27**MOT test number** 922054529745**Result** ✗ Failed

- Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Fail** Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Fail** Nearside Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**MOT #11** 2019-09-05 13:25**MOT test number** 330092669921**Result** ✓ Passed**MOT #10** 2019-08-30 15:17**MOT test number** 893304275102**Result** ✗ Failed

- Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Fail** Nearside Rear Sub-frame pin or bush excessively worn (5.3.4 (a) (i))
- Fail** Offside Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Fail** Offside Rear Sub-frame pin or bush excessively worn (5.3.4 (a) (i))

**MOT #9** 2018-09-26 13:00**MOT test number** 920449033415**Result** ✓ Passed**Advice** Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))**MOT #8** 2018-09-25 16:21**MOT test number** 639732399920**Result** ✗ Failed**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))**MOT #7** 2017-09-27 13:54**MOT test number** 384386459886**Result** ✓ Passed**MOT #6** 2017-09-27 07:40**MOT test number** 648502408180**Result** ✗ Failed**Fail** Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #5** 2016-09-19 11:43**MOT test number** 939336019867**Result** ✓ Passed



MOT #4	2015-09-19 08:58
MOT test number	762017735433
Result	✓ Passed
MOT #3	2014-09-20 10:26
MOT test number	248173364202
Result	✓ Passed
MOT #2	2014-09-20 10:26
MOT test number	305133564497
Result	✗ Failed
<div>Pass with rectification</div> Nearside Front Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)	
<div>Pass with rectification</div> Front Headlamp aim too low (1.8)	
MOT #1	2013-09-28 11:37
MOT test number	547041373206
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
8 January 2025

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	246
<b>MOT expiry date</b>	8 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	D
<b>Single payment (12 months)</b>	£ 150,00,-
<b>Single six month payment</b>	£ 82,50,-
<b>Total payable by 12 monthly instalments</b>	£ 157,50,-





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>YD60UUC</b>
Plate since	2024-03-29
Current registration	<b>YD60UUC</b>
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-09-30
Last registration	2024-01-09
Complete history	<a href="#">See info</a>



Registration #1	2010-09-30	26 mi
Registration #2	2013-09-28	17.985 mi
Registration #3	2014-09-20	24.524 mi
Registration #4	2015-09-19	30.815 mi
Registration #5	2016-09-19	37.921 mi
Registration #6	2017-09-27	45.125 mi
Registration #7	2017-09-27	45.125 mi
Registration #8	2018-09-25	50.629 mi
Registration #9	2018-09-26	50.629 mi
Registration #10	2019-08-30	54.974 mi
Registration #11	2019-08-30	54.974 mi
Registration #12	2019-08-30	54.974 mi
Registration #13	2019-08-30	54.974 mi
Registration #14	2019-08-30	54.974 mi
Registration #15	2019-08-30	54.974 mi
Registration #16	2019-08-30	54.974 mi
Registration #17	2019-08-30	54.974 mi
Registration #18	2019-08-30	54.974 mi
Registration #19	2019-08-30	54.974 mi
Registration #20	2019-08-30	54.974 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1973 mm
Height	1481 mm
Length	3950 mm
Wheel base	2489 mm
Kerb weight	1041 kg
Max. allowed weight	1490 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	AU64848