



Mercedes-Benz




report date: 2024-03-28

General information

Make	MERCEDES
Model	E E320 CDI AVANTGARDE
Colour	Black
Year of manufacture	2007
Top speed	155 mph
0 - 60 mph	6.8 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	221 BHP
Max. torque	510 Nm at 2.800 rpm
Engine capacity	2.987 cc
Cylinders	6
Fuel type	Diesel
Consumption city	26.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	37.2 mpg
CO2 emission	202 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-02-02
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-02-19
MOT pass rate	70 %
MOT passed	16
Failed MOT tests	7
Total advice items	29
Total items failed	11

MOT #23	2024-01-24 10:18
MOT test number	891658367012
Result	✓ Passed
Next expiry date	2025-02-19

MOT #22	2023-01-26 12:06
MOT test number	412685383792
Result	✓ Passed
Advice	Offside Play in steering rack inner joint(s)

MOT #21	2023-01-26 10:29
MOT test number	289190900215
Result	✗ Failed
Advice	Offside Play in steering rack inner joint(s)
Fail	Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))

**MOT #20** 2022-02-03 09:53**MOT test number** 769347381721**Result** ✓ Passed**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Rear Brake pipe corroded, covered in grease or other material Both (1.1.11 (c))**Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))**Advice** Under trays fitted**MOT #19** 2021-02-20 10:05**MOT test number** 209089938880**Result** ✓ Passed**MOT #18** 2021-02-20 10:05**MOT test number** 157133933803**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**MOT #17** 2020-01-27 13:10**MOT test number** 730365690474**Result** ✓ Passed**MOT #16** 2020-01-24 12:31**MOT test number** 337353610393**Result** ✗ Failed**Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Nearside Front Suspension arm ball joint excessively worn rear (5.3.4 (a) (i))

**MOT #15** 2019-01-24 17:26**MOT test number** 931578105692**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #14** 2018-01-23 14:48**MOT test number** 171172502903**Result** ✓ Passed**MOT #13** 2017-06-16 08:49**MOT test number** 191459230062**Result** ✓ Passed**Advice** Nearside Front Front wheel bearing has slight play (2.5.A.3c)**Advice** Offside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt front arm (2.4.G.2)**MOT #12** 2016-06-17 09:32**MOT test number** 960068987830**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear child seat fitted not allowing full inspection of seat belt**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #11** 2016-06-13 15:12**MOT test number** 980828456660**Result** ✗ Failed**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Nearside Rear child seat fitted not allowing full inspection of seat belt**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #10** 2015-05-06 15:54**MOT test number** 775226425181**Result** ✓ Passed**MOT #9** 2015-05-06 15:16**MOT test number** 769246725176**Result** ✗ Failed**Fail** Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #8** 2014-04-26 09:54**MOT test number** 148716814176**Result** ✓ Passed

**MOT #7** 2013-05-04 11:11**MOT test number** 255284423430**Result** ✓ Passed**Advice** Offside Front Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Glow plug light on**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Front wipers smearing**MOT #6** 2012-04-07 10:27**MOT test number** 697088692067**Result** ✓ Passed**MOT #5** 2011-04-30 11:10**MOT test number** 627650621166**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2011-04-30 11:10**MOT test number** 856520321116**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim too high (1.8)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Front Headlamp aim too high (1.8)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #3	2010-05-07 13:02
MOT test number	190037820138
Result	✗ Failed
Pass with rectification	Front registration plate missing (6.3.1a)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #2	2010-05-07 13:02
MOT test number	992147220150
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2010-01-19 14:01
MOT test number	312619410056
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
19 February 2025

Tax status	Valid until 1 October
Days left	155
MOT expiry date	19 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history


Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-01-31
Last registration	2024-01-24
Complete history	See info



Registration #1	2007-01-31	24 mi
Registration #2	2010-01-19	27.912 mi
Registration #3	2010-05-07	29.030 mi
Registration #4	2011-04-30	41.411 mi
Registration #5	2012-04-07	56.643 mi
Registration #6	2013-05-04	70.626 mi
Registration #7	2014-04-26	80.618 mi
Registration #8	2015-05-06	90.621 mi
Registration #9	2016-06-13	101.177 mi
Registration #10	2016-06-17	101.210 mi
Registration #11	2017-06-16	110.311 mi
Registration #12	2018-06-16	120.311 mi
Registration #13	2019-06-16	130.311 mi
Registration #14	2020-06-16	140.311 mi
Registration #15	2021-06-16	150.311 mi
Registration #16	2022-06-16	160.311 mi
Registration #17	2023-06-16	170.311 mi
Registration #18	2024-06-16	180.311 mi
Registration #19	2025-06-16	190.311 mi
Registration #20	2026-06-16	200.311 mi
Registration #21	2027-06-16	210.311 mi
Registration #22	2028-06-16	220.311 mi

More info >



Dimensions & weight

Width	1990 mm
Height	1450 mm
Length	4818 mm
Wheel base	2833 mm
Kerb weight	1740 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	64292040448817