




report date: 2024-03-29

General information

Make	NISSAN
Model	MICRA IG-T N-CONNECTA
Colour	Red
Year of manufacture	2017
Top speed	109 mph
0 - 60 mph	12.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	140 Nm at 2.250 rpm
Engine capacity	898 cc
Cylinders	3
Fuel type	Petrol
Consumption city	50.4 mpg
Consumption extra urban	76.3 mpg
Consumption combined	64.2 mpg
CO2 emission	99 g/km
CO2 label	A






Internet history

Entry 1

Date	2021-01-22
Pictures	29
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2024-12-19
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	7
Total items failed	5

MOT #7 2023-12-20 14:24

MOT test number 930868554507

Result ✓ Passed

Next expiry date 2024-12-19

- Minor** Nearside Front Windscreen damaged but not adversely affecting driver's view stone impact (3.2 (a) (i))
- Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Minor** Front Windscreen wiper blade defective Both blades slight smearing (3.4 (b) (i))

MOT #6 2022-11-25 10:57

MOT test number 198590227254

Result ✓ Passed

MOT #5 2022-11-23 12:22

MOT test number 173225520946

Result ✗ Failed

- Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge worn very badly on edge and low (5.2.3 (e))
- Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))



MOT #4 2021-11-17 14:38

MOT test number 506894518794

Result ✔ Passed

Advice Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement 'D' bush (5.3.4 (a) (i))

Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

Advice Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement 'D' bush (5.3.4 (a) (i))

MOT #3 2020-11-04 09:43

MOT test number 920531547361

Result ✔ Passed

MOT #2 2020-10-29 10:23

MOT test number 228807966785

Result ✘ Failed

Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #1 2020-03-23 11:57

MOT test number 460914875507

Result ✔ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 January 2025

✓
MOT

Expires:
19 December 2024

Tax status	Valid until 1 January
Days left	247
MOT expiry date	19 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable




Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

[More info >](#)



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	LK17MVX
Plate since	2024-03-29
Current registration	LK17MVX
Plate since	2024-03-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled. If not, and you buy this NISSAN then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-03-28
Last registration	2023-12-20
Complete history	See info



Registration #1	2017-03-28	17 mi
Registration #2	2020-03-23	50.831 mi
Registration #3	2020-10-29	54.604 mi
Registration #4	2020-11-04	54.606 mi
Registration #5	2020-03-23	50.831 mi
Registration #6	2020-03-23	50.831 mi
Registration #7	2020-03-23	50.831 mi
Registration #8	2020-03-23	50.831 mi
Registration #9	2020-03-23	50.831 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	79%
Pedestrian	79%
Safety systems	72%
Overall rating	82%
Video	see crash video



Dimensions & weight

Width	1743 mm
Height	1455 mm
Length	3999 mm
Wheel base	2525 mm
Kerb weight	1068 kg
Max. allowed weight	1530 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

