



report date: 2024-03-29

General information

Make	HONDA
Model	ACCORD I-VTEC ES GT
Colour	Silver
Year of manufacture	2009
Top speed	132 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	154 BHP
Max. torque	192 Nm at 4.100 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.8 mpg
Consumption extra urban	47.9 mpg
Consumption combined	38.7 mpg
CO2 emission	175 g/km
CO2 label	H





Internet history

Entry 3

Date	2024-03-13
Pictures	1
Listing price	View report

□

source: [autoonline.co.uk](#)

Entry 2

Date	2024-03-09
Pictures	13
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-01-31
Pictures	1
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-02-22
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	27
Total items failed	5

MOT #14	2024-02-13 15:52
MOT test number	996276549010
Result	✓ Passed
Next expiry date	2025-02-22
Advice	Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

**MOT #13**

2024-02-12 16:47

MOT test number

266621351503

Result

✗ Failed

- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Fail** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))
- Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Fail** Offside Rear Parking brake inoperative on one side (1.4.1 (a))
- Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

MOT #12

2023-02-17 10:22

MOT test number

880595403549

Result

✓ Passed

- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #11

2022-02-17 09:52

MOT test number

815744947322

Result

✓ Passed

MOT #10

2021-02-23 13:43

MOT test number

484076714621

Result

✓ Passed

- Advice** Park Brake Near Max Travel

**MOT #9** 2019-11-05 14:51**MOT test number** 677073677134**Result** ✓ Passed**Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**Advice** Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #8** 2018-11-09 10:01**MOT test number** 400748250712**Result** ✓ Passed**MOT #7** 2017-11-14 08:56**MOT test number** 874203971887**Result** ✓ Passed**MOT #6** 2016-11-10 09:05**MOT test number** 932113325236**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2015-11-02 09:19**MOT test number** 235789290555**Result** ✓ Passed

**MOT #4** 2014-11-07 10:31**MOT test number** 889041014355**Result** ✓ Passed**Notice** Cut in nearside front tyre outer sidewall. Not deep enough to reach inner cords though.**MOT #3** 2013-11-06 13:09**MOT test number** 509370613347**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Both rear tyres worn on the inner edges.**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2012-11-16 14:47**MOT test number** 356621022342**Result** ✓ Passed**Notice** O/s/f tyre worn on pattern (inner edge)**MOT #1** 2012-11-16 14:47**MOT test number** 468751622407**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too high (1.8)**Pass with rectification** Nearside Headlamp aim too high (1.8)**Notice** O/s/f tyre worn on pattern (inner edge)



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
22 February 2025

Tax status	Valid until 1 March
Days left	306
MOT expiry date	22 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	 
Plate since	2024-03-29
Current registration	 
Plate since	2024-03-29

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-11-29
Last registration	2024-02-13
Complete history	See info



Registration #1	2009-11-29	6 mi
Registration #2	2012-11-16	25.859 mi
Registration #3	2013-11-06	35.180 mi
Registration #4	2014-11-07	44.911 mi
Registration #5	2015-11-02	50.308 mi
Registration #6	2016-11-10	57.971 mi
Registration #7	2017-11-14	67.111 mi
Registration #8	2018-11-09	75.451 mi
Registration #9	2019-11-05	84.306 mi
Registration #10	2020-11-02	93.157 mi
Registration #11	2021-11-02	102.008 mi
Registration #12	2022-11-02	110.859 mi
Registration #13	2023-11-02	119.710 mi
Registration #14	2024-02-13	128.561 mi
Registration #15	2024-02-13	137.412 mi
Registration #16	2024-02-13	146.263 mi
Registration #17	2024-02-13	155.114 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	86%
Children	79%
Pedestrian	54%
Safety systems	86%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1840 mm
Height	1440 mm
Length	4740 mm
Wheel base	2705 mm
Kerb weight	1432 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	R20A31201528