



HYUNDAI




report date: 2024-10-06

General information

Make	HYUNDAI
Model	SONATA CDX
Colour	Silver
Year of manufacture	2005
Top speed	126 mph
0 - 60 mph	10.4 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	160 BHP
Max. torque	219 Nm at 4.250 rpm
Engine capacity	2.359 cc
Cylinders	4
Fuel type	Petrol
Consumption city	23.0 mpg
Consumption extra urban	40.4 mpg
Consumption combined	32.1 mpg
CO2 emission	210 g/km
CO2 label	K





## Internet history

### Entry 1

Date	2024-07-17
Pictures	35
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](http://cargurus.co.uk)



MOT history

MOT expiry date	2025-07-15
MOT pass rate	77 %
MOT passed	17
Failed MOT tests	5
Total advice items	14
Total items failed	9

MOT #22	2024-07-16 15:49
MOT test number	240214972492
Result	✓ Passed
Next expiry date	2025-07-15

MOT #21	2023-10-11 13:59
MOT test number	999633474107
Result	✓ Passed
<b>Minor</b>	Battery insecure but not likely to fall from carrier (4.13 (a) (i))
<b>Advice</b>	Front Shock absorbers has a reduced damping effect both (5.3.2 (d))

MOT #20	2022-10-13 16:00
MOT test number	151656856081
Result	✓ Passed
<b>Advice</b>	Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
<b>Minor</b>	Battery insecure but not likely to fall from carrier (4.13 (a) (i))
<b>Advice</b>	Rear Suspension arm corroded but not seriously weakened both (5.3.3 (b) (i))



**MOT #19** 2022-10-13 16:00

**MOT test number** 281330488498

**Result** ✗ Failed

- Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))
- Advice** Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
- Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Rear Suspension arm corroded but not seriously weakened both (5.3.3 (b) (i))

**MOT #18** 2021-10-18 11:58

**MOT test number** 139148349532

**Result** ✓ Passed

- Advice** Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

**MOT #17** 2021-10-14 12:37

**MOT test number** 202085305102

**Result** ✗ Failed

- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Offside Outer Integral body structure corroded to the extent that the rigidity of the assembly is significantly reduced sill (6.1.1 (c) (i))
- Advice** Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

**MOT #16** 2020-10-20 09:40

**MOT test number** 261154484410

**Result** ✓ Passed



**MOT #15** 2020-10-16 08:46

**MOT test number** 413414595563

**Result** ✗ Failed

- Fail** Front Tyre tread depth below requirements of 1.6mm both (5.2.3 (e))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

**MOT #14** 2019-10-18 09:12

**MOT test number** 646401843570

**Result** ✓ Passed

**MOT #13** 2019-10-18 09:12

**MOT test number** 252317897103

**Result** ✗ Failed

- Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Pass with rectification** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Pass with rectification** Central Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #12** 2018-10-16 08:35

**MOT test number** 435877638106

**Result** ✓ Passed

**MOT #11** 2017-10-13 11:45

**MOT test number** 141784969179

**Result** ✓ Passed

- Advice** Rear Tyre worn close to the legal limit both (4.1.E.1)



**MOT #10** 2016-10-20 11:25

**MOT test number** 107911247668

**Result** ✓ Passed

**MOT #9** 2015-05-05 11:40

**MOT test number** 638755625137

**Result** ✓ Passed

**Notice** Nearside rear tyre slightly deteriorated

**MOT #8** 2014-04-29 11:43

**MOT test number** 528479314102

**Result** ✓ Passed

**MOT #7** 2013-05-02 11:34

**MOT test number** 458432623179

**Result** ✓ Passed

**MOT #6** 2012-05-01 11:56

**MOT test number** 997302822169

**Result** ✓ Passed

**MOT #5** 2012-05-01 11:56

**MOT test number** 575362722122

**Result** ✗ Failed

**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)

**MOT #4** 2011-04-19 11:44

**MOT test number** 708419901111

**Result** ✓ Passed



**MOT #3** 2010-04-28 11:50

**MOT test number** 410038010111

**Result** ✓ Passed

**MOT #2** 2009-05-01 12:41

**MOT test number** 841991529152

**Result** ✓ Passed

**MOT #1** 2008-04-29 09:31

**MOT test number** 784020528196

**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 July 2025

✓  
**MOT**

**Expires:**  
15 July 2025

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	234
<b>MOT expiry date</b>	15 July 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-






Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



**Vehicle valuation**

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

<b>Trade retail value</b>	£ 19,999
<b>Auction value</b>	£ 19,999
<b>Average private trade value</b>	£ 19,999

**More info** >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	VK05PNN
Plate since	2019-09-29
Current registration	VK05PNN
Plate since	2019-09-29

More info >



**Finance check**

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.


<b>Finance company</b>	XXXXXXXX XX
<b>Date of agreement</b>	XXXXXXXX XX
<b>Agreement type</b>	XXXXXXXX XX
<b>Agreement term</b>	XXXXXXXX XX
<b>Agreement number</b>	XXXXXXXX XX
<b>Contact info</b>	XXXXXXXX XX

**More info** >



Mileage check

<b>Odometer</b>	In miles
<b>Mileage registrations</b>	23
<b>First mileage registration</b>	2005-04-29
<b>Last registration</b>	2024-07-16
<b>Complete history</b>	<a href="#">See info</a>



<b>Registration #1</b>	2005-04-29	19 mi
<b>Registration #2</b>	2008-04-29	8.327 mi
<b>Registration #3</b>	2009-05-01	10.617 mi
<b>Registration #4</b>	2010-04-28	12.612 mi
<b>Registration #5</b>	2011-04-19	16.382 mi
<b>Registration #6</b>	2012-05-01	19.203 mi
<b>Registration #7</b>	2013-05-02	20.724 mi
<b>Registration #8</b>	2014-04-29	21.966 mi
<b>Registration #9</b>	2015-05-05	23.158 mi
<b>Registration #10</b>	2016-10-20	23.275 mi
<b>Registration #11</b>	2017-10-13	38.418 mi
<b>Registration #12</b>	2018-10-16	48.662 mi
<b>Registration #13</b>	2019-05-01	55.277 mi
<b>Registration #14</b>	2020-05-01	61.277 mi
<b>Registration #15</b>	2021-05-01	67.277 mi
<b>Registration #16</b>	2022-05-01	73.277 mi
<b>Registration #17</b>	2023-05-01	79.277 mi
<b>Registration #18</b>	2024-05-01	85.277 mi
<b>Registration #19</b>	2024-05-01	91.277 mi
<b>Registration #20</b>	2024-05-01	97.277 mi
<b>Registration #21</b>	2024-05-01	103.277 mi
<b>Registration #22</b>	2024-05-01	109.277 mi
<b>Registration #23</b>	2024-05-01	115.277 mi

[More info >](#)



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1832 mm
Height	1475 mm
Length	4800 mm
Wheel base	2730 mm
Kerb weight	1546 kg
Max. allowed weight	2030 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5
Engine number	G4KC5094077