



RENAULT



report date: 2024-03-29

General information

Make	RENAULT
Model	SCENIC DYNAMIQUE VVT 111 SCENIC
Colour	Gold
Year of manufacture	-
Top speed	112 mph
0 - 60 mph	12.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	111 BHP
Max. torque	150 Nm at 4.250 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	44.8 mpg
Consumption combined	37.2 mpg



**MOT history**

MOT #18	2020-08-04 09:42
MOT test number	549438555178
Result	✓ Passed
Next expiry date	2021-08-03
Advice	Offside Rear All direction indicators slightly discoloured (4.4.3 (a))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear All direction indicators slightly discoloured (4.4.3 (a))

MOT #17	2020-07-23 14:43
MOT test number	399753330435
Result	✗ Failed
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Fail	Offside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))
Fail	Nearside Rear Outer Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Advice	Nearside Rear All direction indicators slightly discoloured (4.4.3 (a))
Fail	Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Fail	Offside Front Inner Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
Fail	Offside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Front Windscreen washer not working (3.5 (a))
Fail	Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Advice	Offside Rear All direction indicators slightly discoloured (4.4.3 (a))

**MOT #16**

2019-09-11 15:49

MOT test number

945973481347

Result

✓ Passed

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Play in steering rack inner joint(s)
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #15

2019-09-11 15:49

MOT test number

359160769055

Result

✗ Failed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Pass with rectification** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Nearside Front Play in steering rack inner joint(s)
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))



MOT #14

2018-09-13 15:00

MOT test number

421106703758

Result

✓ Passed

- Advice

Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))
- Advice

Oil leak, but not excessive (8.4.1 (a) (i))
- Advice

Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice

Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice

Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))
- Advice

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice

Nearside Front Play in steering rack inner joint(s)
- Advice

Oil leak, but not excessive (8.4.1 (a) (i))
- Advice

Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #13**

2018-09-12 14:25

MOT test number

418080317037

Result**✗ Failed**

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Play in steering rack inner joint(s)
- Advice** Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))
- Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))
- Fail** Bonnet cannot be secured in the closed position (3.1 (b) (i))

MOT #12

2017-04-04 13:17

MOT test number

885454028903

Result**✓ Passed**

- Advice** Offside Front Outer Brake pad(s) wearing thin (3.5.1g)

**MOT #11**

2017-04-04 11:14

MOT test number

525700327553

Result

✗ Failed

Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Front Outer Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #10**

2016-02-18 17:00

MOT test number

970940925418

Result

✓ Passed

Advice Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Slight play in steering rack inner joints**Advice** Offside Rear wheel bearing has slight play (2.6.2)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #9**

2016-01-26 10:56

MOT test number

495071390237

Result**✗ Failed****Advice** Offside Rear wheel bearing has slight play (2.6.2)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Slight play in inner steering rack joints**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Suspension arm has excessive play in a ball joint (2.4.G.2)**MOT #8**

2015-01-27 13:07

MOT test number

367097025030

Result**✓ Passed****Notice** Engine oil leak**Notice** Both inner track rod ball joints worn**MOT #7**

2015-01-27 13:07

MOT test number

387117925045

Result**✗ Failed****Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Notice** Engine oil leak**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Notice** Both inner track rod ball joints worn

**MOT #6** 2014-01-29 15:48**MOT test number** 505459224080**Result** ✓ Passed**Advice** Offside Inner Ball joint has slight play (2.2.B.1f)**Notice** Engine oil leak**MOT #5** 2014-01-29 10:22**MOT test number** 728299524011**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Front and rear wipers**Advice** Offside Inner Ball joint has slight play (2.2.B.1f)**Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Engine oil leak**MOT #4** 2013-01-21 15:46**MOT test number** 596761023089**Result** ✓ Passed**MOT #3** 2013-01-15 18:19**MOT test number** 118915413045**Result** ✗ Failed**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Fail** Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d)



MOT #2	2012-01-30 09:47
MOT test number	419110532019
Result	✓ Passed

MOT #1	2011-01-04 11:45
MOT test number	417634401086
Result	✓ Passed



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	YX57LVB
Plate since	2019-03-29
Current registration	YX57LVB
Plate since	2019-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.


Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-10-26
Last registration	2020-08-04
Complete history	See info



Registration #1	2007-10-26	12 mi
Registration #2	2011-01-04	25.948 mi
Registration #3	2012-01-30	32.731 mi
Registration #4	2013-01-15	51.124 mi
Registration #5	2013-01-21	51.316 mi
Registration #6	2014-01-29	71.253 mi
Registration #7	2014-01-29	71.253 mi
Registration #8	2015-01-27	88.592 mi
Registration #9	2016-01-26	106.647 mi
Registration #10	2016-01-26	106.647 mi
Registration #11	2016-01-26	106.647 mi
Registration #12	2016-01-26	106.647 mi
Registration #13	2016-01-26	106.647 mi
Registration #14	2016-01-26	106.647 mi
Registration #15	2016-01-26	106.647 mi
Registration #16	2016-01-26	106.647 mi
Registration #17	2016-01-26	106.647 mi
Registration #18	2016-01-26	106.647 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2087 mm
Height	1701 mm
Length	4259 mm
Wheel base	2685 mm
Kerb weight	1320 kg
Max. allowed weight	1925 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D042546