





report date: 2024-03-28

#### General information

Make	FIAT
Model	PANDA POP
Colour	White
Year of manufacture	2010
Top speed	99 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 6.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	44.1 mpg
Consumption extra urban	65.7 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-05-21

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history	ΜO	Γh	nist	orv	
-------------	----	----	------	-----	--

MOT expiry date	2024-08-16
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	10
Total items failed	9

MOT #14		2023-08-04 10:03
MOT test	number	976158141169
Result		✓ Passed
Next expi	ry date	2024-08-16
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Nearside Rear Lower Coil spring mounting corroded but not seriously weak	ened (5.3.1 (b) (i))
Advice	Rear exhaust silencer deteriorated	
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Offside Rear Lower Coil spring mounting corroded but not seriously weaker	ned (5.3.1 (b) (i))

MOT #13	2022-08-17 14:37
MOT test number	610076714947
Result	✓ Passed
Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))  Advice Rear silencer corroding.	

MOT #12	2021-07-15 12:03
MOT test number	780646647309
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #	11	2021-07-13 08:08
MOT te	st number	189197318955
Result		<b>×</b> Failed
Fail	Offside Rear Direction indicator incorrect colour (4.4.3 (a))	
Fail	Offside Rear Shock absorbers has an excessively worn bush (5.3.2 (c))	
Fail	Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))	
Fail	Nearside Rear Direction indicator incorrect colour (4.4.3 (a))	
Fail	Nearside Rear Shock absorbers has an excessively worn bush (5.3.2 (c))	
Fail	Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))	
Fail	Nearside Side repeater not working (4.4.1 (a) (ii))	

MOT #10	2020-08-10 08:13
MOT test number	798652771736
Result	✓ Passed
MOT #9	2019-08-05 14:19
MOT test number	858861790172
Result	✓ Passed
MOT #8	2019-08-05 08:14
MOT test number	820354445124
Result	<b>×</b> Failed
Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))	

MOT #7	2018-08-13 14:45
MOT test number	357954910597
Result	<b>✓</b> Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #6	2018-08-13 09:02
MOT test number	164759520201
Result	<b>×</b> Failed
Fail Emissions not tested rear box holed and blowing (8.2.1.2 (d))	

MOT #5		2017-08-10 10:53
MOT test	number	174472343249
Result		✓ Passed
MOT #4		2016-08-11 09:00
MOT test	number	820537164556
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #3	2015-08-11 12:19
MOT test number	485742887072
Result	<b>✓</b> Passed
MOT #2	2014-08-07 09:11
MOT test number	579089614269
Result	<b>✓</b> Passed
MOT #1	2013-08-07 09:25
MOT test number	189719913288
Result	<b>✓</b> Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

#### Tax & MOT check



Tax status	Valid until 1 July
Days left	64
MOT expiry date	16 August 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

#### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

	1415	0 1	· h	ict	0 0	
U	wr	ıer	n	ารเ	or	۱

For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report I	
***************************************	
	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	NIE UK
Plate since	******
Current registration	NIE AND INC.
Flate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

#### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-08-12
Last registration	2023-08-04
Complete history	See info



Registration #1	2010-08-12	17 mi
Registration #2	2013-08-07	18.115 mi
Registration #3	2014-08-07	22.285 mi
Registration #4	2015-08-11	27.165 mi
Registration #5	2016-08-11	30.908 mi
Registration #6	2017-08-10	35.161 mi
Registration #7	2018-08-13	39.338 mi
Registration #8	2018-08-13	39.338 mi
_		
Registration #9		77.777 es
Registration #9 Registration #10		1.77 44
		11.777 ea 11.777 ea 11.777 ea
Registration #10		11.777 ea 11.777 ea 11.777 ea
Registration #10 Registration #11		11,777 ea 11,777 ea 11,777 ea 11,777 ea
Registration #10 Registration #11 Registration #12		11,777 ea 11,777 ea 11,777 ea 11,777 ea
Registration #10 Registration #11 Registration #12 Registration #13		11,777 ea 11,777 ea 11,777 ea 11,777 ea 11,777 ea

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

## Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

## Safety ratings

NCAP rating	****
Video	see crash video



## Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	865 kg
Max. allowed weight	1305 kg

#### Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/1

Number of axles 2

**Engine number** 5582676