



LSIIOKX

report date: 2024-03-28

General information

| | |
|---------------------|----------------|
| Make | MAZDA |
| Model | MX-5 I MIYAKO |
| Colour | Silver |
| Year of manufacture | 2011 |
| Top speed | 123 mph |
| 0 - 60 mph | 9.9 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 124 BHP |
| Max. torque | 167 Nm at 4.500 rpm |
| Engine capacity | 1.798 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 28.8 mpg |
| Consumption extra urban | 50.4 mpg |
| Consumption combined | 39.8 mpg |
| CO2 emission | 167 g/km |
| CO2 label | H |





MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2021-03-22 |
| MOT pass rate | 100 % |
| MOT passed | 7 |
| Failed MOT tests | 0 |
| Total advice items | 3 |
| Total items failed | 0 |

| | |
|------------------|--|
| MOT #7 | 2020-03-23 09:03 |
| MOT test number | 155568958354 |
| Result | ✓ Passed |
| Next expiry date | 2021-03-22 |
| Advice | Offside Front Anti-roll bar linkage damaged but not seriously weakened (5.3.3 (b) (i)) |

| | |
|-----------------|------------------|
| MOT #6 | 2019-05-20 08:20 |
| MOT test number | 970302241040 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #5 | 2018-05-19 10:29 |
| MOT test number | 552604009519 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #4 | 2017-05-22 08:01 |
| MOT test number | 366497834246 |
| Result | ✓ Passed |



| | |
|-----------------|--|
| MOT #3 | 2016-05-28 08:22 |
| MOT test number | 777606465039 |
| Result | ✓ Passed |
| Advice | Offside Wiper blade split |
| Advice | Front Brake pad(s) wearing thin (3.5.1g) |

| | |
|-----------------|------------------|
| MOT #2 | 2015-05-29 09:19 |
| MOT test number | 645239245183 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #1 | 2014-04-24 13:35 |
| MOT test number | 348104014151 |
| Result | ✓ Passed |



Tax & MOT check

✕
Untaxed

Tax expired:
22 February 2021

✕
MOT

Expired:
22 March 2021

| | |
|------------------|---------------------------------|
| Tax status | Expired at 22 February 2021 |
| Days left | 1161 days too late |
| MOT expiry date | 22 March 2021 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|---|------------|
| Vehicle class | 48 |
| Band | H |
| Single payment (12 months) | £ 290,00,- |
| Single six month payment | £ 159,50,- |
| Total payable by 12 monthly instalments | £ 304,50,- |



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this MAZDA had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | LS110KX |
| Plate since | 2019-09-28 |
| Current registration | LS110KX |
| Plate since | 2019-09-28 |

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 8 |
| First mileage registration | 2011-05-30 |
| Last registration | 2020-03-23 |
| Complete history | See info |



| | | |
|-----------------|------------|-----------|
| Registration #1 | 2011-05-30 | 9 mi |
| Registration #2 | 2014-04-24 | 17.712 mi |
| Registration #3 | 2015-05-29 | 26.619 mi |
| Registration #4 | 2016-05-28 | 34.311 mi |
| Registration #5 | 2019-03-20 | 35.377 mi |
| Registration #6 | 2019-03-20 | 35.377 mi |
| Registration #7 | 2019-03-20 | 35.377 mi |
| Registration #8 | 2019-03-20 | 35.377 mi |

More info >



Safety ratings

| | |
|-------------|---------------------------------|
| NCAP rating | ★★★★☆ |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1720 mm |
| Height | 1245 mm |
| Length | 4020 mm |
| Wheel base | 2330 mm |
| Kerb weight | 1150 kg |
| Max. allowed weight | 1375 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 50 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 2 |
| Number of seats | 2 |
| Engine number | L8 10210276 |