





report date: 2024-03-29

General information

| Make | MINI |
|---------------------|----------------|
| Model | ONE COOPER |
| Colour | Red |
| Year of manufacture | 2018 |
| Top speed | 130 mph |
| 0 - 60 mph | 8.0 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 134 BHP |
|-------------------------|---------------------|
| Max. torque | 220 Nm at 4.200 rpm |
| Engine capacity | 1.499 сс |
| Cylinders | 3 |
| Fuel type | Petrol |
| Consumption city | 41.5 mpg |
| Consumption extra urban | 62.8 mpg |
| Consumption combined | 52.3 mpg |
| CO2 emission | 122 g/km |
| CO2 label | D |



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

Date 2022-03-01

Pictures 46

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

| NAC | \Т | بہا: حا | L |
|-----|----|---------|------|
| MC | ノレ | nis | tory |

| MOT expiry date | 2024-10-18 |
|--------------------|------------|
| MOT pass rate | 75 % |
| MOT passed | 3 |
| Failed MOT tests | 1 |
| Total advice items | 6 |
| Total items failed | 1 |

| MOT #4 | 2023-10-14 09:44 |
|------------------|------------------|
| MOT test number | 231085429071 |
| Result | ✓ Passed |
| Next expiry date | 2024-10-18 |

| MOT #3 | | 2022-09-30 15:32 |
|----------|---|------------------|
| MOT test | number | 872273077119 |
| Result | | ✓ Passed |
| Advice | Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2. | 3 (d) (i)) |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |

| MOT #2 | | 2022-09-30 11:33 |
|--|--|------------------|
| MOT test | number | 863321700066 |
| Result | | 🗙 Failed |
| Advice | Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 | 3 (d) (i)) |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Fail Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) | | |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #1 2021-10-08 13:36
MOT test number 876100052687

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



| Tax status | Valid until 1 April |
|------------------|---------------------|
| Days left | 336 |
| MOT expiry date | 18 October 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|-------------------------------|------------|
| Band | G |
| First licence fee (12 months) | £ 210,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |
| Premium rate (12 months) | £ 570,00,- |

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner history

| For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report | |
|---|-------------|
| *************************************** | |
| *************************************** | |
| *************************************** | |
| ********* | |
| *************************************** | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this MINI had different number plates. | |
| Number of plates | |
| Current registration | ZIS UK |
| Plate since | |
| Current registration | IIK SIE |
| Plate since | |
| | More info > |

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 6 |
| First mileage registration | 2018-10-19 |
| Last registration | 2023-10-14 |
| Complete history | See info |



| Registration #1 | 2018-10-19 | 10 mi |
|-----------------|------------|-----------|
| Registration #2 | 2021-10-08 | 9.774 mi |
| Registration #3 | | 11.777 ea |
| Registration #4 | | 71.777 66 |
| Registration #5 | | 11.777 mi |
| Pogistration #6 | | |

Registration #6

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| 50482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 79% |
| Children | 73% |
| Pedestrian | 66% |
| Safety systems | 56% |
| Overall rating | 71% |
| Video | see crash video |



Dimensions & weight

| Width | 1932 mm |
|---------------------|---------|
| Height | 1414 mm |
| Length | 3821 mm |
| Wheel base | 249 mm |
| Kerb weight | 1135 kg |
| Max. allowed weight | 1565 kg |

Additional information

| Fuel tank capacity | 40 | |
|-----------------------------------|------------------|-------|
| Fuel delivery | Direct Injection | |
| Number of doors | 3 | |
| Number of seats CarCheck.co.uk | 4 page | 11/11 |