



PEUGEOT



ENIILSX

report date: 2024-03-28

General information

Make	PEUGEOT
Model	207 HDI ALLURE
Colour	Blue
Year of manufacture	2011
Top speed	114 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	92 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	52.3 mpg
Consumption extra urban	76.4 mpg
Consumption combined	65.7 mpg
CO2 emission	113 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-02-03
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-11-02
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	40
Total items failed	21

MOT #17	2023-10-13 14:46
MOT test number	886780423466
Result	✓ Passed
Next expiry date	2024-11-02
Advice	Offside Front Upper Shock absorber mount slight wear
Advice	Bonnet stay missing
Advice	Nearside Rear Outer axle bush slight wear

MOT #16	2023-10-06 07:32
MOT test number	879660797388
Result	✗ Failed
Fail	Offside Rear fog lamp not working (4.5.1 (a) (ii))
Advice	Nearside Rear Outer axle bush slight wear
Fail	Nearside Rear Brake lever has insufficient reserve travel (1.1.2 (a))
Fail	Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Advice	Bonnet stay missing
Advice	Offside Front Upper Shock absorber mount slight wear
Fail	Oil leaking excessively from engine (8.4.1 (a) (i))



<b>MOT #15</b>	2022-10-26 13:01
<b>MOT test number</b>	525448302108
<b>Result</b>	✓ Passed
<b>Advice</b>	Oil leak, but not excessive (8.4.1 (a) (i))
<b>Advice</b>	Nearside Rear Child Seat fitted not allowing full inspection of adult belt

<b>MOT #14</b>	2022-10-20 08:05
<b>MOT test number</b>	906089144478
<b>Result</b>	✗ Failed
<b>Advice</b>	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
<b>Fail</b>	Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
<b>Advice</b>	Oil leak, but not excessive (8.4.1 (a) (i))
<b>Fail</b>	Offside Front Brake hose excessively stretched fouling anti roll bar link (1.1.12 (b) (ii))
<b>Fail</b>	Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
<b>Fail</b>	Offside Rear Direction indicator incorrect colour (4.4.3 (a))
<b>Fail</b>	Offside Front Coil spring with an unsafe modification fouling inner wheel arch (5.3.1 (d) (i))
<b>Fail</b>	Offside Front Shock absorbers damaged to the extent that it does not function Mounted incorrectly (5.3.2 (b))
<b>Fail</b>	Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

<b>MOT #13</b>	2021-10-14 08:10
<b>MOT test number</b>	458268661336
<b>Result</b>	✓ Passed
<b>Advice</b>	Rear Direction indicator slightly discoloured both sides (4.4.3 (a))
<b>Advice</b>	Child Seat fitted not allowing full inspection of adult belt
<b>Advice</b>	Rear Exhaust mounting defective (6.1.2 (a))

**MOT #12** 2021-10-14 08:10**MOT test number** 951120200929**Result** ✗ Failed**Advice** Rear Exhaust mounting defective (6.1.2 (a))**Pass with rectification** Offside Stop lamp(s) not working replaced bulb (4.3.1 (a) (ii))**Advice** Rear Direction indicator slightly discoloured both sides (4.4.3 (a))**Advice** Child Seat fitted not allowing full inspection of adult belt**MOT #11** 2020-11-03 17:00**MOT test number** 233770883883**Result** ✓ Passed**MOT #10** 2020-01-04 13:42**MOT test number** 696761299010**Result** ✓ Passed**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Nearside Front Outer Tyre slightly damaged (5.2.3 (d) (ii))**Advice** Offside Rear Adult seat belt not checked**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Service/inspection light on**Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Outer sill damaged

**MOT #9**

2019-12-30 15:05

**MOT test number**

698503434738

**Result****✗ Failed**

- Advice** Nearside Front External mirror unit damaged/broken
- Fail** Nearside Front Side repeater missing (4.4.1 (a) (ii))
- Advice** Nearside Outer sill damaged
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Front Outer Tyre slightly damaged (5.2.3 (d) (ii))
- Advice** Offside Rear Adult seat belt not checked
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Service/inspection light on
- Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #8**

2019-01-04 16:43

**MOT test number**

919998081688

**Result****✓ Passed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #7** 2019-01-03 15:01**MOT test number** 667872478609**Result** ✗ Failed**Fail** Headlamp aim too low and too far to the right. (4.1.2 (a))**Advice** Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Headlamp aim too far to the left (4.1.2 (a))**Fail** Exhaust system insecure (6.1.2 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Engine mounting bracket damaged or deteriorated resulting in excessive movement (6.1.8 (a) (i))**MOT #6** 2018-01-04 12:05**MOT test number** 491840907914**Result** ✓ Passed**MOT #5** 2017-01-02 16:27**MOT test number** 250980068954**Result** ✓ Passed**MOT #4** 2016-01-07 15:36**MOT test number** 295735876886**Result** ✓ Passed**Advice** Nearside Rear nail in tyre



MOT #3	2015-01-07 14:48
MOT test number	929947205083
Result	✓ Passed
MOT #2	2014-06-11 13:05
MOT test number	947202364111
Result	✓ Passed
MOT #1	2014-06-11 13:05
MOT test number	877092264122
Result	✗ Failed
Pass with rectification	Windscreen washer provides insufficient washer liquid (8.2.3)
Pass with rectification	Nearside Front Headlamp not working on dipped beam (1.7.5a)





Tax & MOT check

X

Untaxed

Tax expired:  
3 April 2024

✓

MOT

Expires:  
2 November 2024

Tax status	Expired at 3 April 2024
Days left	25 days too late
MOT expiry date	2 November 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	EN11LSX
Plate since	2019-09-28
Current registration	EN11LSX
Plate since	2019-09-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-07-22
Last registration	2023-10-13
Complete history	<a href="#">See info</a>



Registration #1	2011-07-22	6 mi
Registration #2	2014-06-11	31.883 mi
Registration #3	2015-01-07	35.853 mi
Registration #4	2016-01-07	41.528 mi
Registration #5	2017-01-02	47.799 mi
Registration #6	2018-01-04	54.230 mi
Registration #7	2019-01-03	61.805 mi
Registration #8	2019-01-04	61.830 mi
Registration #9	2019-12-30	64.399 mi
Registration #10	2020-01-01	64.399 mi
Registration #11	2020-01-01	64.399 mi
Registration #12	2020-01-01	64.399 mi
Registration #13	2020-01-01	64.399 mi
Registration #14	2020-01-01	64.399 mi
Registration #15	2020-01-01	64.399 mi
Registration #16	2020-01-01	64.399 mi
Registration #17	2020-01-01	64.399 mi
Registration #18	2020-01-01	64.399 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1972 mm
Height	1502 mm
Length	4030 mm
Wheel base	2540 mm
Kerb weight	1328 kg
Max. allowed weight	1718 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	JBDL0034735