



ML58VCT

report date: 2024-03-29

General information

Make	FIAT
Model	GRANDE PUNTO ACTIVE
Colour	Black
Year of manufacture	-
Top speed	103 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-06
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)



## MOT history

MOT #15	2022-08-01 10:11
MOT test number	523789597054
Result	✓ Passed
Next expiry date	2023-08-02

MOT #14	2022-08-01 10:08
MOT test number	390291356158
Result	✗ Failed
<b>MAJOR</b> Nearside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))	

MOT #13	2021-08-03 10:43
MOT test number	445568054601
Result	✓ Passed

MOT #12	2021-08-03 08:46
MOT test number	236620150993
Result	✗ Failed
<b>MAJOR</b> Front Position lamp not working (4.2.1 (a) (ii))	
<b>MAJOR</b> Front Registration plate inscription illegible (0.1 (b))	
<b>MAJOR</b> Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))	

MOT #11	2017-12-28 14:10
MOT test number	210688313798
Result	✓ Passed
<b>Advice</b> Rear Seat belt attachment fitting slightly deteriorated centre and offside (5.2.3)	
<b>Advice</b> Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
<b>Advice</b> Front Tyre worn close to the legal limit both (4.1.E.1)	

**MOT #10**

2017-12-28 11:28

**MOT test number**

920925345542

**Result****✗ Failed****Advice** Front Tyre worn close to the legal limit both (4.1.E.1)**Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Seat belt attachment fitting slightly deteriorated centre and offside (5.2.3)**MOT #9**

2016-11-28 13:05

**MOT test number**

379159362340

**Result****✓ Passed****Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Central Rear Seat belt attachment fitting slightly deteriorated (5.2.3)**MOT #8**

2016-11-28 13:05

**MOT test number**

420969230056

**Result****✗ Failed****Advice** Central Rear Seat belt attachment fitting slightly deteriorated (5.2.3)**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #7**

2015-12-07 12:44

**MOT test number**

857009567991

**Result****✓ Passed****Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

**MOT #6** 2014-12-08 12:11**MOT test number** 796662144311**Result** ✓ Passed**Advice** Offside Rear Seat belt damaged but not affecting the operation of the belt (5.2.2a)**MOT #5** 2013-12-12 18:07**MOT test number** 966516343324**Result** ✓ Passed**MOT #4** 2013-12-12 18:07**MOT test number** 306446643314**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low and too far to the left. (1.8)**MOT #3** 2012-12-18 11:49**MOT test number** 419623452336**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Rear centre seat belt buckle casing damaged recommend replacement**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Nail in nearside rear tyre**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #2 2012-12-18 10:53

MOT test number 988403952394

Result ✗ Failed

**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Notice** Rear centre seat belt buckle casing damaged recommend replacement

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

**Fail** Brake pedal anti-slip provision missing (3.3.A.1b)

**Notice** Nail in nearside rear tyre

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2011-12-06 15:08

MOT test number 787280541323

Result ✓ Passed


**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2008-12-18
Last registration	2022-08-01
Complete history	<a href="#">See info</a>



Registration #1	2008-12-18	20 mi
Registration #2	2011-12-06	25.373 mi
Registration #3	2012-12-18	31.949 mi
Registration #4	2012-12-18	31.949 mi
Registration #5	2013-12-12	39.750 mi
Registration #6	2014-12-08	45.183 mi
Registration #7	2015-12-07	51.947 mi
Registration #8	2016-11-28	57.798 mi
Registration #9	2016-11-28	57.798 mi
Registration #10	2016-11-28	57.798 mi
Registration #11	2016-11-28	57.798 mi
Registration #12	2016-11-28	57.798 mi
Registration #13	2016-11-28	57.798 mi
Registration #14	2016-11-28	57.798 mi
Registration #15	2016-11-28	57.798 mi
Registration #16	2016-11-28	57.798 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1025 kg
Max. allowed weight	1585 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	4708035