



report date: 2024-03-28

General information

Make	CITROEN
Model	DS3 PURETECH DSTYLE PLUS S/S
Colour	Black
Year of manufacture	2015
Top speed	118 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	205 Nm at 1.500 rpm
Engine capacity	1.200 cc
Cylinders	3
Fuel type	Petrol
Consumption city	47.9 mpg
Consumption extra urban	70.6 mpg
Consumption combined	60.1 mpg
CO2 emission	104 g/km
CO2 label	B






Internet history

Entry 1

Date	2022-04-02
Pictures	14
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2025-04-24
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	57
Total items failed	2

MOT #11	2024-04-25 09:08
MOT test number	253112339599
Result	✓ Passed
Next expiry date	2025-04-24
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Direction indicator slightly discoloured (4.4.3 (a))
Advice	Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Offside Rear tail light lens broken

MOT #10	2023-03-13 15:32
MOT test number	968755181460
Result	✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #9**

2023-03-13 12:27

**MOT test number**

410988457741

**Result****✗ Failed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- MAJOR** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

**MOT #8**

2022-03-09 16:59

**MOT test number**

129149575953

**Result****✓ Passed**

- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor** Offside Front Windscreen damaged but not adversely affecting driver's view upper and lower (3.2 (a) (i))
- Advice** Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))

**MOT #7**

2022-03-09 08:55

**MOT test number**

293411525637

**Result****✗ Failed****Pass with rectification** Nearside Front Headlamp aim too low (4.1.2 (a))**MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**DANGEROUS** Offside Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Offside Rear Service brake excessively binding (1.2.1 (f))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))**Minor** Offside Front Windscreen damaged but not adversely affecting driver's view upper and lower (3.2 (a) (i))

**MOT #6**

2021-03-04 17:33

**MOT test number**

675132041430

**Result**

✓ Passed

- Advice** Nearside Front Tyre slightly damaged Outer sidewall (5.2.3 (d) (ii))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Front Road wheel slightly distorted Both sides (5.2.2 (c) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both sides (1.1.14 (a) (ii))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Both sides (5.3.4 (a) (i))

**MOT #5**

2021-03-04 17:33

**MOT test number**

728032806408

**Result**

✗ Failed

- Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Both sides (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both sides (1.1.14 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Front Road wheel slightly distorted Both sides (5.2.2 (c) (ii))
- Advice** Nearside Front Tyre slightly damaged Outer sidewall (5.2.3 (d) (ii))

**MOT #4** 2020-03-04 11:38**MOT test number** 110933575097**Result** ✓ Passed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #3** 2019-03-06 16:58**MOT test number** 761110723958**Result** ✓ Passed

- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords Side wall (5.2.3 (d) (i))

**MOT #2** 2019-03-06 11:01**MOT test number** 735551816401**Result** ✗ Failed

- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords Side wall (5.2.3 (d) (i))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))

**MOT #1** 2018-03-14 15:20**MOT test number** 458071366895**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
24 April 2025

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	32
<b>MOT expiry date</b>	24 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-





Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>SH15VAF</b>
Plate since	2015-05-29
Current registration	<b>SH15VAF</b>
Plate since	2015-05-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2015-06-30
Last registration	2024-04-25
Complete history	<a href="#">See info</a>



Registration #1	2015-06-30	23 mi
Registration #2	2018-03-14	31.235 mi
Registration #3	2019-03-06	36.718 mi
Registration #4	2019-03-06	36.718 mi
Registration #5	2020-03-04	45.506 mi
Registration #6	2021-03-04	51.400 mi
Registration #7	2021-03-04	51.400 mi
Registration #8	2022-03-04	51.400 mi
Registration #9	2022-03-04	51.400 mi
Registration #10	2022-03-04	51.400 mi
Registration #11	2022-03-04	51.400 mi
Registration #12	2022-03-04	51.400 mi
Registration #13	2022-03-04	51.400 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1708 mm
Height	1460 mm
Length	3948 mm
Wheel base	2464 mm
Kerb weight	1070 kg
Max. allowed weight	1578 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	XV120084253