



RENAULT




report date: 2024-03-29

General information

Make	RENAULT
Model	MEGANE DYNAMIQUE TOMTOM ENERGY DCI S/S
Colour	Brown
Year of manufacture	2012
Top speed	118 mph
0 - 60 mph	12.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	260 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	72.4 mpg
Consumption extra urban	88.3 mpg
Consumption combined	80.7 mpg
CO2 emission	109 g/km
CO2 label	B





Internet history

Entry 2

Date	2021-07-25
Pictures	11
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

Entry 1

Date	2021-06-12
Pictures	11
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-08
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	21
Total items failed	23

MOT #14	2023-10-26 09:04
MOT test number	562821029939
Result	✓ Passed
Next expiry date	2024-11-08
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #13	2022-11-09 13:01
MOT test number	538192225531
Result	✓ Passed
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear exhaust heatshield loose
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12**

2022-11-07 13:43

**MOT test number**

309646048978

**Result**

✗ Failed

- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Nearside Front Inner Tyre has a cut in excess of the requirements deep enough to reach the ply or cords sidewall (5.2.3 (d) (i))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))
- Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Advice** Rear exhaust heatshield loose

**MOT #11**

2021-10-27 15:54

**MOT test number**

323015220138

**Result**

✓ Passed

- Minor** Nearside Side repeater lens defective which has no effect on emitted light Missing (4.4.1 (b) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10**

2021-10-27 12:04

**MOT test number**

846874948413

**Result****✗ Failed**

- Fail** Offside Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Headlamp aim too high (4.1.2 (a))
- Fail** Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Fail** Nearside Front Tyre not fitted in accordance with side wall instructions (5.2.3 (i))
- Minor** Nearside Side repeater lens defective which has no effect on emitted light Missing (4.4.1 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Rear Brakes imbalanced across an axle (1.2.1 (b) (i))
- Fail** Front Position lamp not working X 2 (4.2.1 (a) (ii))
- Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #9**

2020-11-03 13:42

**MOT test number**

931586562890

**Result****✓ Passed**

- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #8**

2020-11-03 12:50

**MOT test number**

484207300691

**Result****✗ Failed**

- Fail** Driver's seat moving inadvertently (6.2.5 (b) (ii))
- Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Offside Rear fog lamp not working (4.5.1 (a) (ii))

**MOT #7** 2019-10-31 18:51**MOT test number** 623117757980**Result** ✓ Passed**MOT #6** 2019-10-31 14:20**MOT test number** 883066081080**Result** ✗ Failed

- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

**MOT #5** 2018-10-30 11:23**MOT test number** 654066122949**Result** ✓ Passed**MOT #4** 2018-10-29 08:41**MOT test number** 301796752211**Result** ✗ Failed

- Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Windscreen washer not working (3.5 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



<b>MOT #3</b>	2017-10-04 16:12
---------------	------------------

<b>MOT test number</b>	201988009184
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

- Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Advice** Under shield fitted to vehicle so there is a restricted a view of some testable items.
- Advice** Nearside Rear Nail in tyre
- Advice** Both wipers are slightly smearing at ends but still clearing screen.

<b>MOT #2</b>	2016-09-24 10:44
---------------	------------------

<b>MOT test number</b>	644683956717
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #1</b>	2015-10-06 16:37
---------------	------------------

<b>MOT test number</b>	391276833992
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
8 November 2024

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	247
<b>MOT expiry date</b>	8 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-





Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	FINANCE
Date of agreement	2024-03-29	2024-03-29
Agreement type	RENAULT	FINANCE
Agreement term	RENAULT	FINANCE
Agreement number	RENAULT	FINANCE
Contact info	RENAULT	FINANCE

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2012-09-27
Last registration	2023-10-26
Complete history	<a href="#">See info</a>



Registration #1	2012-09-27	24 mi
Registration #2	2015-10-06	61.486 mi
Registration #3	2016-09-24	79.246 mi
Registration #4	2017-10-04	109.761 mi
Registration #5	2018-10-29	133.217 mi
Registration #6	2018-10-30	133.217 mi
Registration #7	2019-10-31	145.291 mi
Registration #8	2019-10-31	145.291 mi
Registration #9	2020-11-03	163.573 mi
Registration #10	2020-10-29	163.573 mi
Registration #11	2020-10-29	163.573 mi
Registration #12	2020-10-29	163.573 mi
Registration #13	2020-10-29	163.573 mi
Registration #14	2020-10-29	163.573 mi
Registration #15	2020-10-29	163.573 mi
Registration #16	2020-10-29	163.573 mi
Registration #17	2020-10-29	163.573 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1804 mm
Height	1423 mm
Length	4299 mm
Wheel base	2640 mm
Kerb weight	1205 kg
Max. allowed weight	1805 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	D087813