



report date: 2024-03-28

General information

Make	VAUXHALL
Model	COMBO 2000 L1H1 CDTi
Colour	White
Year of manufacture	2015
Top speed	97 mph
0 - 60 mph	15.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	67.3 mpg
Consumption combined	56.5 mpg
CO2 emission	133 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-02-27
Pictures	19
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2025-03-12
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	10
Total items failed	7

MOT #9	2024-03-13 11:36
MOT test number	880069252293
Result	✓ Passed
Next expiry date	2025-03-12

MOT #8	2023-02-17 16:10
MOT test number	841487405364
Result	✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (nearside and offside) (1.1.14 (a) (ii))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #7**

2023-02-15 15:10

MOT test number

545567447993

Result**✗ Failed****Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (nearside and offside) (1.1.14 (a) (ii))**Fail** Offside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))**MOT #6**

2022-02-16 16:42

MOT test number

366569013117

Result**✓ Passed****Minor** Central Windscreen damaged but not adversely affecting driver's view (stone chip) (3.2 (a) (i))**MOT #5**

2022-02-16 11:34

MOT test number

283175980474

Result**✗ Failed****Minor** Central Windscreen damaged but not adversely affecting driver's view (stone chip) (3.2 (a) (i))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #4**

2021-02-10 15:36

MOT test number

496748740131

Result**✓ Passed****Minor** Nearside Window damaged but not adversely affecting driver's view (3.2 (a) (i))



MOT #3	2021-02-09 11:59
MOT test number	429115798417
Result	✗ Failed
Minor	Nearside Window damaged but not adversely affecting driver's view (3.2 (a) (i))
Fail	Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #2	2020-03-06 09:43
MOT test number	733600373581
Result	✓ Passed

MOT #1	2019-03-15 11:22
MOT test number	173135531564
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
12 March 2025

Tax status	Valid until 1 March
Days left	306
MOT expiry date	12 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Number of owners	1
Current owner since	2019-09-29
Previous owner since	2019-09-29
Number of owners	1
Current owner since	2019-09-29
Previous owner since	2019-09-29

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 DP65KHL
Plate since	2019-09-29
Current registration	 DP65KHL
Plate since	2019-09-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-12-31
Last registration	2024-03-13
Complete history	See info



Registration #1	2015-12-31	26 mi
Registration #2	2019-03-15	12.158 mi
Registration #3	2020-03-06	55.175 mi
Registration #4	2021-02-09	66.242 mi
Registration #5	2021-02-10	66.308 mi
Registration #6	2022-03-20	75.277 mi
Registration #7	2022-03-20	75.277 mi
Registration #8	2022-03-20	75.277 mi
Registration #9	2022-03-20	75.277 mi
Registration #10	2022-03-20	75.277 mi
Registration #11	2024-03-13	75.277 mi

More info >



Dimensions & weight

Width	2119 mm
Height	1845 mm
Length	4390 mm
Kerb weight	1270 kg
Max. allowed weight	2040 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	263A20005688130 LN9