





report date: 2024-03-29

### General information

Make	FIAT
Model	PUNTO ACTIVE
Colour	Blue
Year of manufacture	2007
Top speed	96 mph
0 - 60 mph	14.5 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	64 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	139 g/km
CO2 label	E



CarCheck.co.uk page 1/14



report date: 2024-03-29

## Internet history


#### Entry 1


Date 2021-06-03


Pictures 11

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-29

## MOT history

MOT expiry date	2025-01-30
MOT pass rate	83 %
MOT passed	15
Failed MOT tests	3
Total advice items	29
Total items failed	7

MOT #18	2024-01-24 09:09
MOT test number	590249325304
Result	✓ Passed
Next expiry date	2025-01-30
Advice Nearside Front Lower Suspension arm pin or bush worn but no rear bush (5.3.4 (a) (i))	ot resulting in excessive movement
Advice Nearside Rear Subframe mounting prescribed area is corroded sill (5.3.6 (a) (i))	d but not considered excessive inner
Advice Offside Front Lower Suspension arm pin or bush worn but not rear bush (5.3.4 (a) (i))	resulting in excessive movement
Advice Offside Rear Subframe mounting prescribed area is corroded by sill (5.3.6 (a) (i))	but not considered excessive inner

MOT #17		2023-01-03 14:13
MOT test	number	569546046515
Result		✓ Passed
Advice Rear Suspension component corroded but not seriously weakened (5.3.3 (b) (i))		
Advice	Advice Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
Advice (i))	Offside Front Suspension arm pin or bush worn but not resulting in excessive mo	ovement (5.3.4 (a)

CarCheck.co.uk page 3/14



(i))

WM56DXY

report date: 2024-03-29

MOT test number

Result

Advice Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Advice Rear Suspension component corroded but not seriously weakened (5.3.3 (b) (i))

Pass with rectification Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)

**MOT #15** 2022-01-20 11:56 **MOT** test number 204920854022 Result ✓ Passed **Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a)) **Advice** Nearside Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive sil (5.3.6 (a) (i)) Advice Offside Rear Tyre worn close to legal limit/worn on edge on limit (5.2.3 (e)) Offside Rear Inner Suspension component mounting prescribed area is corroded but not Advice considered excessive sil (5.3.6 (a) (i)) Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i)) **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge on limit (5.2.3 (e))

MOT #14

MOT test number

Front exhaust becoming corroded

2021-01-13 17:42

547816139396

V Passed

Advice

Front exhaust becoming corroded

CarCheck.co.uk page 4/14



report date: 2024-03-29

MOT test number

Result

Advice Rear Child Seat fitted not allowing full inspection of adult belt

Engine sump corroding/misted in oil

**MOT #12** 2020-01-17 16:52 **MOT** test number 795815321434 Result × Failed Fail Nearside Rear Service brake excessively binding (1.2.1 (f)) Advice Engine sump corroding/misted in oil Advice Rear Child Seat fitted not allowing full inspection of adult belt Parking brake efficiency below requirements (1.4.2 (a) (i)) Fail Fail Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))

 MOT #11
 2019-01-16 15:45

 MOT test number
 597314225365

 Result
 ✓ Passed

 Advice
 Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT test number

Fail Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

Fail Nearside Rear Position lamp adversely affected by the operation of another lamp (4.2.3 (c))

Fail Central Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 5/14



report date: 2024-03-29

MOT #9

MOT test number

512459341149

Result

Advice Temporary fuel cap fitted

MOT #8

MOT test number

Result

Advice

Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

 MOT #7
 2016-01-29 09:22

 MOT test number
 381518188380

 Result
 ✓ Passed

MOT #6

MOT test number

Result

Result

Reat silencer deteriorated

MOT #5

MOT test number

175971834421

Result

Notice Rear exhaust section deteriorated

2014-01-31 09:09

175971834421

✓ Passed

 MOT #4
 2013-01-31 09:45

 MOT test number
 758201533020

 Result
 ✓ Passed

CarCheck.co.uk page 6/14



**Advice** 

WM56DXY

report date: 2024-03-29

MOT #3	2012-01-26 11:44
MOT test number	877066622095
Result	✓ Passed
MOT #2	2011-01-21 10:02
MOT test number	856321321016
Result	✓ Passed
MOT #1	2010-01-30 11:17
MOT test number	593220730045
Result	✓ Passed

Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 7/14



WM56DXY
report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 July
Days left	62
MOT expiry date	30 January 2025
Full MOT history	See MOT history

### Tax calculation

William .	40
Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 8/14



report date: 2024-03-29

#### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-29

### Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report if	
THE STATE OF THE S	
***************************************	
***************************************	
********	
***************************************	
	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	NK SIE
Plate since	
Current registration	NK SILVE
Plate since	
	More info >

CarCheck.co.uk page 11/14



report date: 2024-03-29

#### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-01-30
Last registration	2024-01-24
Complete history	See info



Registration #1	2007-01-30	10 mi
Registration #2	2010-01-30	20.281 mi
Registration #3	2011-01-21	25.374 mi
Registration #4	2012-01-26	32.446 mi
Registration #5	2013-01-31	40.237 mi
Registration #6	2014-01-31	47.513 mi
Registration #7	2015-01-26	52.599 mi
Registration #8	2016-01-29	57.634 mi
Registration #9	2017-01-23	61.993 mi
Registration #10	2018-01-26	66.683 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		91,700 esi
Registration #16		11.777 es
Registration #17		91,700 esi
Registration #18		11.777 es
Registration #19		
11091511 411011 11 25		

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-29

## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1030 kg
Max. allowed weight	1590 kg

## Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 14/14

Number of axles 2
Engine number 4018117