



RENAULT



report date: 2024-03-28

General information

Make	RENAULT
Model	MEGANE DYNAMIQUE DCI 80
Colour	Silver
Year of manufacture	2004
Top speed	106 mph
0 - 60 mph	14.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	80 BHP
Max. torque	185 Nm at 2.000 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	50.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	61.4 mpg
CO2 emission	117 g/km
CO2 label	C






Internet history

Entry 1

Date	2021-06-18
Pictures	4
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2021-06-23
MOT pass rate	54 %
MOT passed	14
Failed MOT tests	12
Total advice items	74
Total items failed	26

MOT #26 2020-06-03 13:17

MOT test number 907898666739

Result ✓ Passed

Next expiry date 2021-06-23

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Minor Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Front Tyre worn close to legal limit/worn on edge Both sides (5.2.3 (e))

Advice Lower Engine mounting damaged but not to excess (6.1.8 (a) (i))

MOT #25 2020-06-03 13:17

MOT test number 513904752464

Result ✗ Failed

Advice Lower Engine mounting damaged but not to excess (6.1.8 (a) (i))

Advice Front Tyre worn close to legal limit/worn on edge Both sides (5.2.3 (e))

Minor Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Pass with rectification Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #24**

2019-06-24 10:00

MOT test number

845023947587

Result

✓ Passed

- Advice** Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Both front stut tops slightly worn (noisy)
- Advice** Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Mil light on
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #23

2019-06-20 11:09

MOT test number

456988732914

Result

✗ Failed

- Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Both front stut tops slightly worn (noisy)
- Advice** Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Nearside Front Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))
- Advice** Mil light on
- Advice** Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))
- Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))



MOT #22

2018-06-23 10:46

MOT test number

803892983202

Result

✓ Passed

- Advice

Play in steering rack inner joint(s)
- Minor

Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice

Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor

Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice

Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))
- Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #21**

2018-06-21 09:49

MOT test number

175172786682

Result

✗ Failed

- Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Play in steering rack inner joint(s)
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))
- Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Minor** Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Fail** Windscreen washer not working (3.5 (a))

MOT #20

2017-06-19 13:31

MOT test number

893742632860

Result

✓ Passed

- Advice** Nearside Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Nearside Front Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)
- Advice** Offside Rear Road wheel slightly damaged (4.2.A.1a)
- Advice** Nearside Front Play in steering rack inner joint(s)

**MOT #19**

2017-06-19 10:51

MOT test number

975146059866

Result**✗ Failed**

Advice Nearside Front Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

Advice Nearside Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Advice Offside Rear Road wheel slightly damaged (4.2.A.1a)

Advice Nearside Front Play in steering rack inner joint(s)

Fail Rear Exhaust system not adequately supported (7.1.1)

MOT #18

2016-06-21 09:36

MOT test number

408382598667

Result**✓ Passed**

Advice Nearside Rear Road wheel slightly damaged (4.2.A.1a)

MOT #17

2016-06-20 09:39

MOT test number

354104049543

Result**✗ Failed**

Fail Offside Rear coil spring broken (2.4.C.1a)

Advice Nearside Rear Road wheel slightly damaged (4.2.A.1a)

Fail Offside Rear Mechanical brake component has restricted free movement (3.5.1k)



MOT #16	2015-06-20 08:32
MOT test number	215081575189
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Notice	Play in steering rack inner joint(s)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Notice	Both rear tyres perished.

MOT #15	2015-06-19 10:25
MOT test number	585800675105
Result	✗ Failed
Notice	Play in steering rack inner joint(s)
Fail	Offside Outer Front constant velocity joint is insecure (2.5.C.1b)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Notice	Both rear tyres perished.
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #14** 2014-09-08 16:04**MOT test number** 755711254270**Result** ✗ Failed**Notice** O/S/R Tyre cracked and perished**Fail** Nearside Headlamp aim too low (1.8)**Fail** Steering lock fails to engage (2.1.4b)**Notice** Knocking noise from steering rack**Fail** Offside Headlamp aim too low (1.8)**MOT #13** 2014-05-27 16:35**MOT test number** 427787644193**Result** ✓ Passed**Notice** Offside rear tyre cracking/perishing.**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #12** 2014-05-19 16:59**MOT test number** 787399334166**Result** ✗ Failed**Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Notice** Offside rear tyre cracking/perishing.**Notice** Engine covers fitted obscuring some components in the engine bay**Fail** Offside Front Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)**Notice** Under-trays fitted obscuring some underside components

**MOT #11** 2013-05-29 14:23**MOT test number** 459089743122**Result** ✓ Passed

- Notice** Offside front tyre cracking/perishing
- Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Under-trays fitted obscuring some underside components
- Notice** Play in steering rack inner joint(s)

MOT #10 2012-06-19 14:52**MOT test number** 246421372111**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #9 2012-06-19 14:52**MOT test number** 927501772114**Result** ✗ Failed

- Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #8 2011-04-18 12:04**MOT test number** 909908101140**Result** ✓ Passed

- Notice** Both front side lights dim in operation

**MOT #7** 2011-04-18 12:04**MOT test number** 616358001187**Result** ✗ Failed**Notice** Both front side lights dim in operation**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #6** 2010-04-29 15:13**MOT test number** 261769010138**Result** ✓ Passed**MOT #5** 2009-04-29 16:47**MOT test number** 643609619125**Result** ✓ Passed**MOT #4** 2009-04-29 09:23**MOT test number** 463229119146**Result** ✗ Failed**Fail** Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Brake disc excessively pitted (3.5.1h)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**MOT #3** 2008-05-09 12:30**MOT test number** 213160938487**Result** ✓ Passed**Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)



MOT #2	2008-05-08 16:37
MOT test number	590269228153
Result	✗ Failed
Fail	Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Advice	Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)

MOT #1	2007-05-02 17:03
MOT test number	113832627128
Result	✓ Passed
Advice	Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)



Tax & MOT check

X

Untaxed

Tax expired:
14 June 2021

X

MOT

Expired:
23 June 2021

Tax status	Expired at 14 June 2021
Days left	1050 days too late
MOT expiry date	23 June 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2004-05-07
Last registration	2020-06-03
Complete history	See info



Registration #1	2004-05-07	24 mi
Registration #2	2007-05-02	45.627 mi
Registration #3	2008-05-08	59.398 mi
Registration #4	2008-05-09	59.414 mi
Registration #5	2009-04-29	66.313 mi
Registration #6	2009-04-29	66.313 mi
Registration #7	2010-04-29	68.595 mi
Registration #8	2011-04-18	70.808 mi
Registration #9	2012-06-19	72.978 mi
Registration #10	2013-05-29	75.703 mi
Registration #11	2014-05-19	77.568 mi
Registration #12	2014-05-27	77.644 mi
Registration #13	2014-09-08	78.265 mi
Registration #14	2015-05-20	78.265 mi
Registration #15	2015-05-20	78.265 mi
Registration #16	2015-05-20	78.265 mi
Registration #17	2015-05-20	78.265 mi
Registration #18	2015-05-20	78.265 mi
Registration #19	2015-05-20	78.265 mi
Registration #20	2015-05-20	78.265 mi
Registration #21	2015-05-20	78.265 mi
Registration #22	2015-05-20	78.265 mi
Registration #23	2015-05-20	78.265 mi
Registration #24	2015-05-20	78.265 mi
Registration #25	2015-05-20	78.265 mi
Registration #26	2015-05-20	78.265 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2026 mm
Height	1458 mm
Length	4209 mm
Wheel base	2625 mm
Kerb weight	1195 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number	D167762