





report date: 2024-03-29

General information

Make	CITROEN
Model	BERLINGO 625 ENTERPRISE L1 BLUEHDI
Colour	White
Year of manufacture	2016
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	112 g/km
CO2 label	С



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-01-29
Pictures 1

Listing price <u>View report</u>



source: autoonline.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-03-01
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	5
Total items failed	11

MOT #8	2024-02-20 08:37
MOT test number	171576183274
Result	✓ Passed
Next expiry date	2025-03-01

2024-02-14 08:45 **MOT #7** 170255019435 **MOT** test number Result × Failed Fail Nearside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i)) Offside Front Coil spring fractured or broken (5.3.1 (b) (i)) Fail Fail Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i)) Fail Nearside Rear Service brake lagging in operation (1.2.1 (d)) Fail Offside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i)) Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the Fail ingress of dirt (6.1.7 (g) (ii))

MOT #6	2023-02-14 12:23
MOT test number	423188294160
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #5 2022-02-15 16:00

MOT test number 611967363246

Advice Nearside Rear Tyre worn close to legal limit/worn on edge outside edge (5.2.3 (e))

Nearside Front Tyre worn close to legal limit/worn on edge worn the outside and inside edge (5.2.3

(e))

Advice

MOT #4 2021-03-02 12:31

MOT test number 111858540069

Result ✓ Passed

MOT #3 2020-10-27 08:46

MOT test number 463440373736

Result
✓ Passed

Advice Offside Rear lense cracked

Minor Nearside Front Drive shaft joint constant velocity boot severely deteriorated damp at rib (6.1.7 (g)

(i))

MOT #2 2019-10-04 08:26

MOT test number 439570951827

Result ✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-29

2019-10-03 08:05 **MOT #1 MOT test number** 505467226799 Result × Failed Fail Central Seat belt not functioning as intended (7.1.2 (c)) Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) Fail Advice Offside Front Tyre worn close to legal limit/worn on edge On limits on inner edge (5.2.3 (e)) Fail Offside Rear Service brake excessively binding (1.2.1 (f)) Nearside Front Tyre tread depth below requirements of 1.6mm On outer edge (5.2.3 (e)) Fail Fail Nearside Rear Service brake excessively binding (1.2.1 (f))

CarCheck.co.uk page 5/12



Tax & MOT check



lax status	valid until 1 March
Days left	305
MOT expiry date	1 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full in		OEN

	More info	>
Plate changes		
See in this check if this CITROEN had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Pinance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info


More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-10-04
Last registration	2024-02-20
Complete history	See info



Registration #1	2016-10-04	14 mi
Registration #2	2019-10-03	47.031 mi
Registration #3	2019-10-04	47.034 mi
Registration #4	2020-10-27	56.720 mi
Registration #5		71.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		111.7777 esp
Registration #9		11.177 es
Registration #10		11.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Safety ratings

NCAP rating	***
Adult	56%
Children	74%
Pedestrian	63%
Safety systems	48%
Overall rating	59%
Video	see crash video

Dimensions & weight

Width	2112 mm
Height	1801 mm
Length	4380 mm
Kerb weight	1309 kg
Max. allowed weight	1960 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	JBHB3123865

CarCheck.co.uk page 12/12