



RENAULT

HV580TU

report date: 2024-03-29

General information

Make	RENAULT
Model	TRAFIC SL27 SPORT DCI L/C P/V
Colour	White
Year of manufacture	-
Top speed	96 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	240 Nm at 1.600 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	28.8 mpg
Consumption extra urban	40.4 mpg
Consumption combined	35.8 mpg





MOT history

MOT #14	2020-08-12 15:52
MOT test number	597341030187
Result	✓ Passed
Next expiry date	2021-08-15
Advice Nearside Front Vehicle structure is corroded but structural rigidity is not significantly reduced sill/jacking point (6.1.1 (c) (i))	
Minor Front Suspension arm ball joint dust cover severely deteriorated both (5.3.4 (b) (i))	

MOT #13	2020-08-12 15:52
MOT test number	242318736781
Result	✗ Failed
Advice Nearside Front Vehicle structure is corroded but structural rigidity is not significantly reduced sill/jacking point (6.1.1 (c) (i))	
Pass with rectification Nearside Stop lamp(s) not working (4.3.1 (a) (ii))	
Minor Front Suspension arm ball joint dust cover severely deteriorated both (5.3.4 (b) (i))	

MOT #12	2019-08-16 15:57
MOT test number	339408834639
Result	✓ Passed
Advice Rear discs worn in inside edge	
Advice Offside Rear Tyre worn close to legal limit/worn on edge and perishing on sidewall (5.2.3 (e))	

MOT #11	2018-04-05 15:37
MOT test number	248618062849
Result	✓ Passed
Advice Oil leak	
Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice Nearside Front Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)	

**MOT #10** 2018-04-05 15:37**MOT test number** 122924199636**Result** ✗ Failed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Pass with rectification** Offside Rear Stop lamp not working (1.2.1b)**Advice** Oil leak**Advice** Nearside Front Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**Pass with rectification** Front Front position lamp(s) not working both (1.1.A.3b)**Pass with rectification** Registration plate lamp not working (1.1.C.1d)**MOT #9** 2016-10-02 11:17**MOT test number** 207872458513**Result** ✓ Passed**Advice** Offside Front Anti-roll bar linkage rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Anti-roll bar linkage rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #8** 2015-10-23 14:09**MOT test number** 145963574251**Result** ✓ Passed**MOT #7** 2014-10-18 09:23**MOT test number** 187241994287**Result** ✓ Passed**MOT #6** 2013-10-16 15:20**MOT test number** 876159983266**Result** ✓ Passed**Notice** SCRATCH MARK NOTICED ACROSS WINDSCREEN

**MOT #5** 2013-10-16 15:16**MOT test number** 979249983260**Result** ✓ Passed**MOT #4** 2012-10-17 16:04**MOT test number** 466111392294**Result** ✓ Passed**MOT #3** 2012-10-17 10:20**MOT test number** 899071492292**Result** ✗ Failed**Fail** Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)**MOT #2** 2011-10-26 16:36**MOT test number** 249799891240**Result** ✓ Passed**MOT #1** 2011-10-21 15:12**MOT test number** 177324791281**Result** ✗ Failed**Notice** SCRATCH TO WINDSCREEN (ZONE A-B)**Notice** CANT OPEN BONNET (CABLE BROKEN)**Fail** Nearside Front Headlamp not working on dipped beam (1.7.5a)**Notice** IMBALANCE TO REAR BRAKES



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT FINANCE
Date of agreement	01/01/2024
Agreement type	FINANCE
Agreement term	36 months
Agreement number	123456789
Contact info	01234 567890

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2008-10-08
Last registration	2020-08-12
Complete history	See info



Registration #1	2008-10-08	24 mi
Registration #2	2011-10-21	76.231 mi
Registration #3	2011-10-26	76.239 mi
Registration #4	2012-10-17	86.170 mi
Registration #5	2012-10-17	86.171 mi
Registration #6	2013-10-16	96.573 mi
Registration #7	2013-10-16	96.573 mi
Registration #8	2014-10-18	108.242 mi
Registration #9	2015-10-18	118.242 mi
Registration #10	2016-10-18	118.242 mi
Registration #11	2017-10-18	118.242 mi
Registration #12	2018-10-18	118.242 mi
Registration #13	2019-10-18	118.242 mi
Registration #14	2020-08-12	118.242 mi
Registration #15	2020-08-12	118.242 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1904 mm
Height	1945 mm
Length	4782 mm
Kerb weight	1678 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Number of axles	2
Engine number	C052885