




report date: 2024-03-29

General information

Make	MAZDA
Model	CX-7 D SPORT TECH
Colour	Silver
Year of manufacture	2010
Top speed	124 mph
0 - 60 mph	11.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	173 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.184 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.0 mpg
Consumption extra urban	42.8 mpg
Consumption combined	37.7 mpg
CO2 emission	199 g/km
CO2 label	J





## Internet history

### Entry 1

Date	2021-12-07
Pictures	20
Listing price	<a href="#">View report</a>



source: autotrader.co.uk





MOT history

MOT expiry date	2022-12-15
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	28
Total items failed	16

MOT #12 2021-12-16 11:40

MOT test number 459248036937

Result ✔ Passed

Next expiry date 2022-12-15

- Advice** Brake hose has slight corrosion to ferrule all (1.1.12 (f) (i))
- Advice** Rear Tyre worn close to legal limit/worn on edge both tyres inner edges (5.2.3 (e))
- Advice** Surface rust underneath on all suspension component + floor area.
- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Rear both sides brake discs back plates corroded.
- Advice** Parking brake lever has slight travel.
- Advice** Front Sub-frame corroded but not seriously weakened & rear (5.3.3 (b) (i))



MOT #11 2021-12-16 11:40

MOT test number 257440790446

Result ✗ Failed

**Advice** Parking brake lever has slight travel.

**Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))

**Advice** Rear Tyre worn close to legal limit/worn on edge both tyres inner edges (5.2.3 (e))

**Advice** Surface rust underneath on all suspension component + floor area.

**Advice** Front Sub-frame corroded but not seriously weakened & rear (5.3.3 (b) (i))

**Advice** Brake hose has slight corrosion to ferrule all (1.1.12 (f) (i))

**Advice** Rear both sides brake discs back plates corroded.

MOT #10 2020-10-15 15:05

MOT test number 898677983869

Result ✓ Passed

MOT #9 2019-04-30 13:54

MOT test number 555601985059

Result ✓ Passed



MOT #8 2018-05-04 14:08

MOT test number 494949611757

Result ✔ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #7 2018-05-03 15:06

MOT test number 568817955509

Result ✘ Failed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Parking brake lever has no reserve travel (3.1.6b)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #6 2017-05-08 10:58

MOT test number 486186461857

Result ✔ Passed



<b>MOT #5</b>	2016-04-25 15:33
<b>MOT test number</b>	176647093672
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Rear Anti-roll bar has slight play in a ball joint (2.4.G.2)

<b>MOT #4</b>	2016-04-25 09:28
<b>MOT test number</b>	309272299344
<b>Result</b>	✗ Failed
<b>Fail</b>	Nearside Windscreen wiper does not clear the windscreen effectively rubber split (8.2.2)
<b>Fail</b>	Nearside Front Tyre has ply or cords exposed (4.1.D.1b)
<b>Advice</b>	Offside Rear Anti-roll bar has slight play in a ball joint (2.4.G.2)
<b>Fail</b>	Offside Windscreen wiper does not clear the windscreen effectively rubber split (8.2.2)
<b>Fail</b>	Offside Front Tyre has ply or cords exposed (4.1.D.1b)
<b>Fail</b>	Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

<b>MOT #3</b>	2014-12-13 14:42
<b>MOT test number</b>	967907244309
<b>Result</b>	✓ Passed
<b>Notice</b>	Engine covers fitted obscuring some components in the engine bay
<b>Notice</b>	Under-trays fitted obscuring some underside components

<b>MOT #2</b>	2013-10-07 14:04
<b>MOT test number</b>	785680883227
<b>Result</b>	✓ Passed



**MOT #1** 2013-10-07 11:41

**MOT test number** 885000283271

**Result** ✗ Failed

**Fail** Nearside Rear rear parking brake recording little or no effort (3.7.B.6a)

**Fail** Offside Front Front position lamp(s) not working (1.1.A.3b)

**Fail** Offside Front Headlamp aim too high (1.8)

**Fail** Parking brake: efficiency below requirements (3.7.B.7)

**Fail** Nearside Front Headlamp aim too high (1.8)




Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



## Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

<b>Trade retail value</b>	£ 19,999
<b>Auction value</b>	£ 19,999
<b>Average private trade value</b>	£ 19,999

[More info >](#)



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	<b>SD60RZG</b>
Plate since	2024-03-29
Current registration	<b>SD60RZG</b>
Plate since	2024-03-29

More info >



**Finance check**

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled. If not, and you buy this MAZDA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this MAZDA is financed.


<b>Finance company</b>	REDACTED
<b>Date of agreement</b>	REDACTED
<b>Agreement type</b>	REDACTED
<b>Agreement term</b>	REDACTED
<b>Agreement number</b>	REDACTED
<b>Contact info</b>	REDACTED

**More info** >



## Mileage check

<b>Odometer</b>	In miles
<b>Mileage registrations</b>	14
<b>First mileage registration</b>	2010-11-01
<b>Last registration</b>	2021-12-16
<b>Complete history</b>	<a href="#">See info</a>



<b>Registration #1</b>	2010-11-01	26 mi
<b>Registration #2</b>	2013-10-07	56.552 mi
<b>Registration #3</b>	2013-10-07	56.552 mi
<b>Registration #4</b>	2014-12-13	65.744 mi
<b>Registration #5</b>	2016-04-25	73.257 mi
<b>Registration #6</b>	2016-04-25	73.257 mi
<b>Registration #7</b>	2017-05-08	79.061 mi
<b>Registration #8</b>	2019-05-08	85.277 mi
<b>Registration #9</b>	2019-05-08	85.277 mi
<b>Registration #10</b>	2019-05-08	85.277 mi
<b>Registration #11</b>	2019-05-08	85.277 mi
<b>Registration #12</b>	2019-05-08	85.277 mi
<b>Registration #13</b>	2019-05-08	85.277 mi
<b>Registration #14</b>	2019-05-08	85.277 mi

**More info** >



## Safety ratings

<b>NCAP rating</b>	★★★★☆
<b>Adult</b>	76%
<b>Children</b>	79%
<b>Pedestrian</b>	43%
<b>Safety systems</b>	71%
<b>Overall rating</b>	70%
<b>Video</b>	<a href="#">see crash video</a>



## Dimensions & weight

<b>Width</b>	1870 mm
<b>Height</b>	1645 mm
<b>Length</b>	4700 mm
<b>Wheel base</b>	2750 mm
<b>Kerb weight</b>	1865 kg
<b>Max. allowed weight</b>	2430 kg

## Additional information

<b>Fuel tank capacity</b>	69 l
<b>Fuel delivery</b>	Direct Injection
<b>Number of doors</b>	5
<b>Number of seats</b>	5
<b>Number of axles</b>	2
<b>Engine number</b>	R2 10267131