



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	IX35 CRDI SE
Colour	White
Year of manufacture	-
Top speed	108 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	260 Nm at 1.250 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	53.3 mpg



LABEL UNKNOWN

**MOT history**

MOT #6	2020-04-24 13:01
MOT test number	474550435562
Result	✓ Passed
Next expiry date	2021-04-23
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #5	2020-04-24 11:36
MOT test number	559163170818
Result	✗ Failed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
MAJOR	Nearside Parking brake inoperative on one side (1.4.1 (a))
DANGEROUS	Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
DANGEROUS	Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
MAJOR	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
MAJOR	Offside Parking brake inoperative on one side (1.4.1 (a))
DANGEROUS	Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #4	2018-11-02 11:49
MOT test number	973692006956
Result	✓ Passed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Minor	Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i))

**MOT #3** 2018-11-02 10:42**MOT test number** 710914926221**Result** ✗ Failed**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #2** 2017-10-31 11:14**MOT test number** 973517146645**Result** ✓ Passed**MOT #1** 2016-10-19 08:41**MOT test number** 538977167834**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2013-11-13
Last registration	2020-04-24
Complete history	See info



Registration #1	2013-11-13	18 mi
Registration #2	2016-10-19	43.938 mi
Registration #3	2017-10-31	62.819 mi
Registration #4	2018-11-02	79.474 mi
Registration #5	2019-05-20	95.377 mi
Registration #6	2019-05-20	95.377 mi
Registration #7	2020-04-24	95.377 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1665 mm
Length	4410 mm
Wheel base	2640 mm
Kerb weight	1537 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4FDDZ211384