



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	FOX 16V URBAN FOX
Colour	Silver
Year of manufacture	2009
Top speed	104 mph
0 - 60 mph	13.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	124 Nm at 2.750 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.1 mpg
Consumption extra urban	49.6 mpg
Consumption combined	42.2 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-10-01
Pictures	39
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-10-07
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	16
Total items failed	11

MOT #19	2023-09-25 14:02
MOT test number	998313226173
Result	✓ Passed
Next expiry date	2024-10-07
Advice	Park leaver near end of travel

MOT #18	2023-09-25 14:02
MOT test number	761105634449
Result	✗ Failed
Pass with rectification	Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Advice	Park leaver near end of travel

MOT #17	2022-10-06 08:12
MOT test number	127714373539
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16	2021-10-08 09:19
MOT test number	821887943484
Result	✓ Passed

**MOT #15** 2021-10-08 09:19**MOT test number** 200629250512**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #14** 2021-02-24 12:47**MOT test number** 332253731214**Result** ✓ Passed**MOT #13** 2021-02-24 12:47**MOT test number** 715606563526**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Pass with rectification** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #12** 2020-02-27 12:34**MOT test number** 217132001612**Result** ✓ Passed**Advice** Offside front has body damage**MOT #11** 2020-02-27 12:34**MOT test number** 186937672966**Result** ✗ Failed**Advice** Offside front has body damage**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))

**MOT #10** 2019-02-28 15:12**MOT test number** 934767866240**Result** ✓ Passed**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #9** 2019-02-28 10:10**MOT test number** 282076547296**Result** ✗ Failed**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #8** 2018-02-23 10:23**MOT test number** 542067930929**Result** ✓ Passed**Advice** Nearside Rear Tyre Perished**Advice** Offside Rear Tyre Perished**MOT #7** 2017-02-24 13:59**MOT test number** 146448685011**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #6** 2017-02-24 13:59**MOT test number** 169741427467**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #5** 2016-02-25 09:49**MOT test number** 173604192764**Result** ✓ Passed**Advice** Offside Front Suspension arm has slight play in a pin/bush (2.4.G.2)**Advice** Nearside Front Suspension arm has slight play in a pin/bush (2.4.G.2)**MOT #4** 2015-02-26 10:00**MOT test number** 648947655077**Result** ✓ Passed**MOT #3** 2014-02-27 12:13**MOT test number** 105018454026**Result** ✓ Passed**Notice** Front tyres worn close to limit**MOT #2** 2013-03-01 17:26**MOT test number** 959550163005**Result** ✓ Passed**MOT #1** 2012-02-04 09:51**MOT test number** 585375632033**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
7 October 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	156
<b>MOT expiry date</b>	7 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>GU09XDM</b>
Plate since	2024-03-29
Current registration	 <b>GU09XDM</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-03-02
Last registration	2023-09-25
Complete history	<a href="#">See info</a>



Registration #1	2009-03-02	22 mi
Registration #2	2012-02-04	6.711 mi
Registration #3	2013-03-01	11.032 mi
Registration #4	2014-02-27	15.086 mi
Registration #5	2015-02-26	19.868 mi
Registration #6	2016-02-25	24.271 mi
Registration #7	2017-02-24	28.248 mi
Registration #8	2017-02-24	28.248 mi
Registration #9	2018-02-23	31.948 mi
Registration #10	2019-02-28	35.876 mi
Registration #11	2019-02-28	35.879 mi
Registration #12	2020-02-27	39.807 mi
Registration #13	2020-02-27	39.810 mi
Registration #14	2021-02-26	43.738 mi
Registration #15	2021-02-26	43.741 mi
Registration #16	2022-02-25	47.669 mi
Registration #17	2022-02-25	47.672 mi
Registration #18	2023-02-24	51.600 mi
Registration #19	2023-02-24	51.603 mi
Registration #20	2024-02-23	55.527 mi
Registration #21	2024-02-23	55.530 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1093 kg
Max. allowed weight	1520 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	BKR 035324