



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	206 LX
Colour	Black
Year of manufacture	-
Top speed	106 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	111 Nm at 2.600 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	42.8 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-23
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT #24	2022-09-16 11:51
MOT test number	517279980699
Result	✓ Passed
Next expiry date	2023-09-15
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
Minor	Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #23	2021-06-23 16:26
MOT test number	385642448820
Result	✓ Passed
Advice	Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #22	2020-10-22 08:36
MOT test number	488656365768
Result	✓ Passed

MOT #21	2019-10-15 14:47
MOT test number	682571097168
Result	✓ Passed
Minor	Headlamp switch does not immediately illuminate all dipped beam headlamps (4.1.3 (a))

**MOT #20** 2019-10-10 09:59**MOT test number** 537817647743**Result** ✗ Failed**Minor** Headlamp switch does not immediately illuminate all dipped beam headlamps (4.1.3 (a))**Fail** Offside Headlamp light intensity severely reduced (4.1.4 (a))**Fail** Nearside Headlamp light intensity severely reduced (4.1.4 (a))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**MOT #19** 2018-10-23 14:16**MOT test number** 595887679589**Result** ✓ Passed**MOT #18** 2018-10-23 08:18**MOT test number** 624003828591**Result** ✗ Failed**Fail** Central Exhaust has a major leak of exhaust gases (6.1.2 (a))**MOT #17** 2017-10-27 11:22**MOT test number** 530727260099**Result** ✓ Passed

**MOT #16**

2017-10-26 09:07

MOT test number

856676330521

Result**✗ Failed**

- Fail** Offside Headlamp has a product on the lens so that the light output is severely reduced (1.7.5a)
- Fail** Front Exhaust has a major leak of exhaust gases (7.1.2)
- Fail** Nearside Headlamp has a product on the lens so that the light output is severely reduced (1.7.5a)
- Fail** Nearside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)
- Fail** Rear Exhaust has a major leak of exhaust gases (7.1.2)

MOT #15

2016-10-26 13:30

MOT test number

978613191177

Result**✓ Passed****MOT #14**

2016-10-26 10:32

MOT test number

940808207732

Result**✗ Failed**

- Fail** Nearside Headlamp has a product on the lens so that the light output is severely reduced (1.7.5a)
- Fail** Offside Headlamp has a product on the lens so that the light output is severely reduced (1.7.5a)
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)

MOT #13

2015-10-30 13:53

MOT test number

481111367596

Result**✓ Passed**

- Advice** Rear wiper faulty

**MOT #12** 2015-10-29 08:37**MOT test number** 180166566270**Result** ✗ Failed**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Rear wiper faulty**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #11** 2014-10-28 09:34**MOT test number** 838191304317**Result** ✓ Passed**MOT #10** 2013-10-29 08:45**MOT test number** 159942003328**Result** ✓ Passed**MOT #9** 2012-10-26 15:49**MOT test number** 466650502475**Result** ✓ Passed**MOT #8** 2011-10-27 10:05**MOT test number** 397040001383**Result** ✓ Passed**MOT #7** 2010-10-27 15:03**MOT test number** 751830300373**Result** ✓ Passed

**MOT #6** 2009-11-02 17:16**MOT test number** 434296009366**Result** ✓ Passed**MOT #5** 2009-10-30 13:25**MOT test number** 141913609314**Result** ✗ Failed**Fail** Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)**Fail** Nearside Rear position lamp(s) excessively deteriorated so that it is not visible from a reasonable distance (1.1.A.3d)**Fail** Nearside Steering rack gaiter split (2.2.D.2d)**MOT #4** 2008-11-01 09:03**MOT test number** 904676208354**Result** ✓ Passed**MOT #3** 2008-10-31 10:00**MOT test number** 603605908317**Result** ✗ Failed**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #2** 2007-11-07 08:56**MOT test number** 870431217313**Result** ✓ Passed**MOT #1** 2006-11-04 11:49**MOT test number** 493658306301**Result** ✓ Passed



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	YX52WVM
Plate since	2019-03-29
Current registration	YX52WVM
Plate since	2019-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2002-11-11
Last registration	2022-09-16
Complete history	See info



Registration #1	2002-11-11	24 mi
Registration #2	2006-11-04	30.462 mi
Registration #3	2007-11-07	34.484 mi
Registration #4	2008-10-31	37.055 mi
Registration #5	2008-11-01	37.055 mi
Registration #6	2009-10-30	39.335 mi
Registration #7	2009-11-02	39.335 mi
Registration #8	2010-10-27	42.733 mi
Registration #9	2011-10-27	43.559 mi
Registration #10	2012-10-26	44.689 mi
Registration #11	2013-10-29	45.674 mi
Registration #12	2014-10-28	47.437 mi
Registration #13	2015-10-29	48.112 mi
Registration #14	2016-10-29	48.112 mi
Registration #15	2017-10-29	48.112 mi
Registration #16	2018-10-29	48.112 mi
Registration #17	2019-10-29	48.112 mi
Registration #18	2020-10-29	48.112 mi
Registration #19	2021-10-29	48.112 mi
Registration #20	2022-09-16	48.112 mi
Registration #21		
Registration #22		
Registration #23		
Registration #24		
Registration #25		
Registration #26		

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1652 mm
Height	1433 mm
Length	3822 mm
Wheel base	2445 mm
Kerb weight	950 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Engine number	FSC43814790