



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	LUPO E
Colour	Green
Year of manufacture	2002
Top speed	94 mph
0 - 60 mph	17.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	50 BHP
Max. torque	86 Nm at 3.000 rpm
Engine capacity	999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	48.7 mpg
CO2 emission	139 g/km
CO2 label	E





MOT history

MOT expiry date	2025-02-04
MOT pass rate	86 %
MOT passed	18
Failed MOT tests	3
Total advice items	16
Total items failed	8

MOT #21	2024-02-05 14:02
MOT test number	441332265017
Result	✓ Passed
Next expiry date	2025-02-04

MOT #20	2024-02-05 10:12
MOT test number	406287555846
Result	✗ Failed
Fail	Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
Fail	Nearside Rear Road wheel badly distorted (5.2.2 (c) (i))
Fail	Offside Front Position lamp not working (4.2.1 (a) (ii))
Fail	Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #19	2023-02-01 14:46
MOT test number	182250864143
Result	✓ Passed

**MOT #18** 2021-03-29 08:35**MOT test number** 678669139795**Result** ✓ Passed**Advice** Cracks to rear tyres**Advice** Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #17** 2021-03-17 12:36**MOT test number** 262464177760**Result** ✗ Failed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Cracks to rear tyres**Advice** Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #16** 2020-01-27 17:56**MOT test number** 720931303679**Result** ✓ Passed**MOT #15** 2018-11-13 09:21**MOT test number** 544270335089**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #14** 2017-11-07 11:05**MOT test number** 351626939271**Result** ✓ Passed

**MOT #13** 2016-11-04 15:54**MOT test number** 241932185331**Result** ✓ Passed**Advice** Suspension components have surface corrosion**MOT #12** 2015-11-05 11:49**MOT test number** 334041382419**Result** ✓ Passed**MOT #11** 2014-10-29 10:48**MOT test number** 906632904342**Result** ✓ Passed**MOT #10** 2013-10-24 11:54**MOT test number** 136417193285**Result** ✓ Passed**MOT #9** 2012-11-01 16:35**MOT test number** 828626602370**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Surface cracking on o/s and n/s front tyre treads**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2011-10-26 10:31**MOT test number** 309469191291**Result** ✓ Passed

**MOT #7** 2010-11-04 11:47**MOT test number** 734578600338**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2009-11-05 14:30**MOT test number** 953629809375**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2008-11-05 12:49**MOT test number** 893120118311**Result** ✓ Passed**MOT #4** 2008-11-05 12:49**MOT test number** 490360718457**Result** ✗ Failed**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**Pass with rectification** Offside Stop lamp not working (1.2.1b)**MOT #3** 2007-10-16 09:42**MOT test number** 581429687200**Result** ✓ Passed



MOT #2	2006-11-02 09:59
MOT test number	880176806394
Result	✓ Passed
Notice	Rear w/blade split
Notice	Oil leak

MOT #1	2005-11-01 14:16
MOT test number	472465005450
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
4 February 2025

Tax status	Valid until 1 September
Days left	124
MOT expiry date	4 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 KN52AED
Plate since	2019-03-29
Current registration	 KN52AED
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2002-10-11
Last registration	2024-02-05
Complete history	See info



Registration #1	2002-10-11	20 mi
Registration #2	2005-11-01	19.283 mi
Registration #3	2006-11-02	25.471 mi
Registration #4	2007-10-16	30.710 mi
Registration #5	2008-11-05	35.922 mi
Registration #6	2009-11-05	40.255 mi
Registration #7	2010-11-04	44.146 mi
Registration #8	2011-10-26	47.812 mi
Registration #9	2012-11-01	50.572 mi
Registration #10	2013-10-24	52.173 mi
Registration #11	2014-10-29	53.437 mi
Registration #12	2015-10-29	55.277 mi
Registration #13	2016-10-29	56.277 mi
Registration #14	2017-10-29	57.277 mi
Registration #15	2018-10-29	58.277 mi
Registration #16	2019-10-29	59.277 mi
Registration #17	2020-10-29	60.277 mi
Registration #18	2021-10-29	61.277 mi
Registration #19	2022-10-29	62.277 mi
Registration #20	2023-10-29	63.277 mi
Registration #21	2024-02-05	64.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1860 mm
Height	1459 mm
Length	3527 mm
Wheel base	2321 mm
Kerb weight	946 kg

Additional information

Fuel tank capacity	34 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Engine number	AUC223504