



report date: 2024-03-28

General information

Make	FIAT
Model	PUNTO ACTIVE
Colour	Black
Year of manufacture	2009
Top speed	103 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.000 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 2


Date	2021-01-29
Pictures	1
Listing price	View report



source: [autoonline.co.uk](#)

Entry 1

Date	2021-01-21
Pictures	31
Listing price	View report



source: [yesauto.com](#)



MOT history

MOT expiry date	2024-11-07
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	30
Total items failed	13

MOT #18	2023-10-28 13:09
MOT test number	153699769870
Result	✓ Passed
Next expiry date	2024-11-07
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Anti-roll bar ball joint has slight play both (5.3.4 (a) (i))

MOT #17	2023-10-26 12:25
MOT test number	840043513752
Result	✗ Failed
Fail	Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
Fail	Central Lower Engine mounting damaged or deteriorated resulting in excessive movement (6.1.8 (a) (i))
Fail	Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))

**MOT #16** 2022-11-08 17:19**MOT test number** 302564488334**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Front Gearbox mounting defective**Advice** Front sub-frame repaired and fully sprayed sealant**MOT #15** 2022-11-07 17:35**MOT test number** 868220235509**Result** ✗ Failed**Advice** Front sub-frame repaired and fully sprayed sealant**Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Front Gearbox mounting defective**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #14** 2022-02-15 08:16**MOT test number** 462987424237**Result** ✓ Passed**MOT #13** 2022-02-14 14:23**MOT test number** 202320599846**Result** ✗ Failed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**MOT #12** 2021-02-06 12:28**MOT test number** 500037815889**Result** ✓ Passed**MOT #11** 2020-03-20 11:49**MOT test number** 203929683765**Result** ✓ Passed**MOT #10** 2019-04-01 07:56**MOT test number** 844791426375**Result** ✓ Passed**Advice** Tyre worn close to legal limit/worn on edge Both front (5.2.3 (e))**MOT #9** 2018-04-19 08:32**MOT test number** 961009950058**Result** ✓ Passed**Advice** Tyre worn close to the legal limit Both front (4.1.E.1)**MOT #8** 2017-04-27 08:46**MOT test number** 905623418109**Result** ✓ Passed**MOT #7** 2016-04-27 13:43**MOT test number** 164436355324**Result** ✓ Passed**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Rear 2x rear tyres perished**Advice** Nearside Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2015-05-01 10:00**MOT test number** 137881325116**Result** ✓ Passed**Advice** Rear registration plate delaminated but not likely to be misread (6.3.1d)**Notice** Both rear tyres deteriorated on side walls**MOT #5** 2015-04-30 11:44**MOT test number** 748490025186**Result** ✗ Failed**Advice** Rear registration plate delaminated but not likely to be misread (6.3.1d)**Notice** Both rear tyres deteriorated on side walls**Fail** Nearside Front Tie bar/rod has excessive play in a ball joint (2.4.G.2)**Fail** Offside Front coil spring broken (2.4.C.1a)**Fail** Offside Front Tie bar/rod has excessive play in a ball joint (2.4.G.2)**MOT #4** 2014-04-29 17:17**MOT test number** 945149214180**Result** ✓ Passed**MOT #3** 2014-04-29 10:50**MOT test number** 178689614149**Result** ✗ Failed**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #2** 2013-03-18 12:06**MOT test number** 117727873096**Result** ✓ Passed

- Advice** Front registration plate delaminated but not likely to be misread (6.3.1d)
- Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside front brake grabbing slightly (3.7.A.2b)
- Advice** Exhaust has a minor leak of exhaust gases (7.1.2)
- Advice** Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)
- Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside front brake grabbing slightly (3.7.A.2b)
- Notice** Slight imbalance on front brakes

MOT #1 2012-03-15 11:52**MOT test number** 425295872020**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
7 November 2024

Tax status	Valid until 1 December
Days left	217
MOT expiry date	7 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-03-17
Last registration	2023-10-28
Complete history	See info



Registration #1	2009-03-17	9 mi
Registration #2	2012-03-15	20.209 mi
Registration #3	2013-03-18	27.525 mi
Registration #4	2014-04-29	36.417 mi
Registration #5	2014-04-29	36.417 mi
Registration #6	2015-04-30	46.128 mi
Registration #7	2015-05-01	46.128 mi
Registration #8	2016-04-27	55.163 mi
Registration #9	2017-04-27	61.528 mi
Registration #10	2018-04-19	67.445 mi
Registration #11	2019-04-01	73.292 mi
Registration #12	2020-04-01	79.139 mi
Registration #13	2021-04-01	85.000 mi
Registration #14	2022-04-01	90.861 mi
Registration #15	2023-04-01	96.722 mi
Registration #16	2023-10-28	102.583 mi
Registration #17	2023-10-28	102.583 mi
Registration #18	2023-10-28	102.583 mi
Registration #19	2023-10-28	102.583 mi
Registration #20	2023-10-28	102.583 mi
Registration #21	2023-10-28	102.583 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	9519694