





report date: 2024-03-29

General information

Make	MINI
Model	COOPER S
Colour	Silver
Year of manufacture	2018
Top speed	146 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	189 BHP	
Max. torque	280 Nm at 1.250 rpm	
Engine capacity	1.998 сс	
Cylinders	4	
Fuel type	Petrol	
Consumption city	37.2 mpg	
Consumption extra urban	61.4 mpg	
Consumption combined	49.6 mpg	
CO2 emission	136 g/km	
CO2 label	Е	



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

Date	2021-09-14
Pictures	1
Listing price	View report



source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT history

MOT expiry date	2024-06-07
MOT pass rate	60 %
MOT passed	3
Failed MOT tests	2
Total advice items	10
Total items failed	5

MOT #5	2023-05-17 15:04
MOT test number	274742747237
Result	✓ Passed
Next expiry date	2024-06-07
Advice Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #4	2022-05-17 09:31
MOT test number	689509383988
Result	✓ Passed

MOT #3	2022-05-17 09:31
MOT test number	294270916718
Result	X Failed

Pass with rectification Nearside Driver's view of the road through the swept area of the windscreen significantly affected by an obstruction wiring from camera not secured (3.1 (a) (ii))

Pass with rectification Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))


Pass with rectification Electrical wiring insecure and connectors likely to become disconnected wires across floor and windscreen (4.11 (a) (ii))

Pass with rectification Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

CarCheck.co.uk page 3/11



report date: 2024-03-29



MOT #1		2021-06-01 10:15
MOT test	number	520219293678
Result		≍ Failed
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened Both (1.	1.14 (a) (ii))
Fail N	earside Front Tyre has a bulge, caused by separation or partial failure of its st	ructure (5.2.3 (d) (ii))

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 September
Days left	124
MOT expiry date	7 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Н
First licence fee (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category



Extra MINI salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

\sim		h:a	+
- CJV	vner	mis	\mathbf{I}

For how long did the current and previous owner(s) have this MINI? How many owners did Check it in the premium report and see all owner registrations. Download the full report \(\frac{1}{2} \)		e?
manners and the same and the sa		

	More info	>
Plate changes		
See in this check if this MINI had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	OK SIE	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-06-08
Last registration	2023-05-17
Complete history	See info



Registration #1	2018-06-08	19 mi
Registration #2	2021-06-01	37.890 mi
Registration #3	2021-06-02	37.890 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	79%
Children	73%
Pedestrian	66%
Safety systems	56%
Overall rating	71%
Video	see crash video



Dimensions & weight

Width	1727 mm
Height	1414 mm
Length	3850 mm
Wheel base	2495 mm
Kerb weight	1235 kg
Max. allowed weight	1640 kg

Additional information

Fuel tank capacity	44 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 11/11

Number of axles 2

Engine number F096H736