



report date: 2024-03-28

General information

Make	CITROEN
Model	XSARA HDI DESIRE 2 PICASSO
Colour	Green
Year of manufacture	2005
Top speed	109 mph
0 - 60 mph	12.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	205 Nm at 1.900 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	61.4 mpg
Consumption combined	51.4 mpg
CO2 emission	147 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-08-09
Pictures	13
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2021-11-25
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	21
Total items failed	10

MOT #19 2020-10-27 12:08

MOT test number 882348715567

Result ✓ Passed

Next expiry date 2021-11-25

Minor Offside Rear Brake pipe inadequately clipped or supported bracket corroded and broken (1.1.11 (d) (i))

Advice Nearside rear brake hose/brake pipe bracket corroded

Advice Rear axle corroded

MOT #18 2019-11-07 11:28

MOT test number 847741544196

Result ✓ Passed

Advice Slight mis -fire on engine

Advice Rear beam axle rusty

MOT #17 2018-10-31 14:41

MOT test number 543957931316

Result ✓ Passed

Advice Rear beam axle rusty

**MOT #16** 2017-11-10 14:11**MOT test number** 998445856279**Result** ✓ Passed**Advice** Rear suspension components rusty**MOT #15** 2017-11-09 12:17**MOT test number** 727444622602**Result** ✗ Failed**Advice** Rear suspension components rusty**Fail** Nearside Front Seat belt anchorage prescribed area is excessively corroded outer sill (5.2.6)**MOT #14** 2016-11-04 13:07**MOT test number** 777163636242**Result** ✓ Passed**Advice** Rear suspension components rusty**MOT #13** 2015-11-11 16:59**MOT test number** 804041980444**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #12** 2015-11-11 12:47**MOT test number** 854166703361**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (1.8)**Advice** Nearside Front Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b)**Pass with rectification** Offside Headlamp aim too low (1.8)**Advice** Offside Front Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #11** 2014-11-18 13:15**MOT test number** 935682024377**Result** ✓ Passed**Advice** Offside Front Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**MOT #10** 2014-11-18 13:15**MOT test number** 535672524342**Result** ✗ Failed**Pass with rectification** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Offside Front Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

**MOT #9** 2013-11-18 10:35**MOT test number** 318202723381**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #8** 2012-11-26 17:31**MOT test number** 147581532329**Result** ✓ Passed**MOT #7** 2012-11-26 15:20**MOT test number** 645411632305**Result** ✗ Failed**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**MOT #6** 2012-07-12 12:03**MOT test number** 107844792172**Result** ✓ Passed**MOT #5** 2012-07-12 12:03**MOT test number** 178214492143**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (1.8)**Pass with rectification** Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b)**Pass with rectification** Offside Headlamp aim too high (1.8)**MOT #4** 2011-07-14 12:11**MOT test number** 297775391109**Result** ✓ Passed



MOT #3	2010-07-13 12:31
MOT test number	944354290152
Result	✓ Passed
MOT #2	2009-07-14 11:49
MOT test number	910025699186
Result	✓ Passed
MOT #1	2008-07-14 16:05
MOT test number	970666398161
Result	✓ Passed
Notice	Spare tyre defective
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	 
Plate since	2024-03-28
Current registration	 
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2005-07-30
Last registration	2020-10-27
Complete history	See info



Registration #1	2005-07-30	11 mi
Registration #2	2008-07-14	21.521 mi
Registration #3	2009-07-14	25.652 mi
Registration #4	2010-07-13	30.596 mi
Registration #5	2011-07-14	34.731 mi
Registration #6	2012-07-12	38.480 mi
Registration #7	2012-11-26	39.473 mi
Registration #8	2012-11-26	39.474 mi
Registration #9	2013-11-18	50.895 mi
Registration #10	2014-11-18	61.561 mi
Registration #11	2015-05-20	75.377 mi
Registration #12	2015-05-20	75.377 mi
Registration #13	2015-05-20	75.377 mi
Registration #14	2015-05-20	75.377 mi
Registration #15	2015-05-20	75.377 mi
Registration #16	2015-05-20	75.377 mi
Registration #17	2015-05-20	75.377 mi
Registration #18	2015-05-20	75.377 mi
Registration #19	2015-05-20	75.377 mi

More info >



Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)

Dimensions & weight

Width	1751 mm
Height	1637 mm
Length	4276 mm
Wheel base	2760 mm
Kerb weight	1300 kg
Max. allowed weight	1850 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	DYUF4010622