



RENAULT



report date: 2024-03-28

General information

Make	RENAULT
Model	TRAFIC LL29 DCI S/R P/V
Colour	Grey
Year of manufacture	2011
Top speed	96 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	290 Nm at 1.600 rpm
Engine capacity	1.996 cc
Cylinders	4
Fuel type	Diesel
Consumption city	33.2 mpg
Consumption extra urban	41.5 mpg
Consumption combined	38.1 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-10-06
Pictures	11
Listing price	View report



source: cargurus.co.uk

**MOT history****MOT expiry date** 2023-11-04**MOT pass rate** 71 %**MOT passed** 10**Failed MOT tests** 4**Total advice items** 26**Total items failed** 3**MOT #14** 2022-11-05 15:23**MOT test number** 283892047067**Result** ✓ Passed**Next expiry date** 2023-11-04**Advice** Tyre worn close to legal limit/worn on edge both side front (5.2.3 (e))**Advice** Slight play in steering joints**Advice** Suspension arm pin or bush worn but not resulting in excessive movement both side front & both side rear (5.3.4 (a) (i))**Advice** Brake disc worn, pitted or scored, but not seriously weakened front & rear (1.1.14 (a) (ii))**Advice** Both side front sills, brake pipe both side, rear axle components all slight corroded**MOT #13** 2022-11-05 15:23**MOT test number** 505339779866**Result** ✗ Failed**Pass with rectification** Position lamp not working (4.2.1 (a) (ii))**Advice** Tyre worn close to legal limit/worn on edge both side front (5.2.3 (e))**Advice** Slight play in steering joints**Advice** Suspension arm pin or bush worn but not resulting in excessive movement both side front & both side rear (5.3.4 (a) (i))**Advice** Brake disc worn, pitted or scored, but not seriously weakened front & rear (1.1.14 (a) (ii))**Advice** Both side front sills, brake pipe both side, rear axle components all slight corroded

**MOT #12** 2021-09-16 08:45**MOT test number** 705934470922**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))**MOT #11** 2021-09-13 16:07**MOT test number** 646209498945**Result** ✗ Failed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))**MAJOR** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #10** 2020-09-29 10:55**MOT test number** 448645468995**Result** ✓ Passed**MOT #9** 2019-09-25 08:56**MOT test number** 552894074613**Result** ✓ Passed**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Offside Track rod end ball joint has slight play (2.1.3 (b) (i))**MOT #8** 2018-09-27 08:33**MOT test number** 418494412995**Result** ✓ Passed**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Nearside Front Suspension component ball joint has slight play (5.3.4 (a) (i))

**MOT #7** 2017-09-27 09:27**MOT test number** 785645650529**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2017-09-22 11:06**MOT test number** 147816006881**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Shock absorber has a serious fluid leak (2.7.3)**MOT #5** 2016-09-24 10:20**MOT test number** 280074290668**Result** ✓ Passed**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**MOT #4** 2015-11-09 13:56**MOT test number** 511812047362**Result** ✓ Passed**Advice** Nearside Front constant velocity joint is slightly worn loose (2.5.C.1b)**Advice** Nearside Front wheel bearing has slight play (2.5.A.3c)**MOT #3** 2014-11-14 14:53**MOT test number** 848608914365**Result** ✓ Passed



MOT #2	2014-02-21 12:24
---------------	------------------

MOT test number	195782154026
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
---------------	---

MOT #1	2014-02-14 17:25
---------------	------------------

MOT test number	367965944030
------------------------	--------------

Result	✗ Failed
---------------	----------

Advice	Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
---------------	---

Fail	Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d)
-------------	--



Tax & MOT check

✕
Untaxed

Tax expired:
31 March 2023

✕
MOT

Expired:
4 November 2023

Tax status	Expired at 31 March 2023
Days left	394 days too late
MOT expiry date	4 November 2023
Full MOT history	See MOT history



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-03-01
Last registration	2022-11-05
Complete history	See info



Registration #1	2011-03-01	8 mi
Registration #2	2014-02-14	64.486 mi
Registration #3	2014-02-21	64.732 mi
Registration #4	2014-11-14	72.588 mi
Registration #5	2015-11-09	96.452 mi
Registration #6	2016-09-24	107.511 mi
Registration #7	2017-09-22	127.626 mi
Registration #8	2017-09-27	127.626 mi
Registration #9	2019-05-29	151.377 mi
Registration #10	2019-05-29	151.377 mi
Registration #11	2019-05-29	151.377 mi
Registration #12	2019-05-29	151.377 mi
Registration #13	2019-05-29	151.377 mi
Registration #14	2019-05-29	151.377 mi
Registration #15	2019-05-29	151.377 mi
Registration #16	2019-05-29	151.377 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1904 mm
Height	1967 mm
Length	5182 mm
Kerb weight	1660 kg
Max. allowed weight	2960 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	C185544