



report date: 2024-03-29

## General information

Make	VOLVO
Model	V50 D DRIVE R-DESIGN
Colour	Blue
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-07-31
Pictures	8
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-09
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	21
Total items failed	1

MOT #15	2023-12-21 12:23
MOT test number	924673400739
Result	✓ Passed
Next expiry date	2025-01-09
Advice	Handbrake 16% just passed test
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Handbrake not fully returning on caliper
Advice	Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #14** 2023-12-14 10:56**MOT test number** 782009928461**Result** ✗ Failed

- Advice** Handbrake 16% just passed test
- Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
- MAJOR** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Handbrake not fully returning on caliper
- MAJOR** Fuel pipe leaking (6.1.3 (b) (i))
- MAJOR** Nearside Rear Upper Position lamp not working (4.2.1 (a) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #13** 2022-12-13 17:28**MOT test number** 944603945312**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12** 2022-12-13 14:03**MOT test number** 403149060593**Result** ✗ Failed

- DANGEROUS** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11** 2021-12-29 10:11**MOT test number** 690271132395**Result** ✓ Passed**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Rear Brake pad(s) wearing thin 2.5mm (1.1.13 (a) (ii))**MOT #10** 2020-12-29 12:03**MOT test number** 987259619110**Result** ✓ Passed**MOT #9** 2019-12-27 15:42**MOT test number** 330612237849**Result** ✓ Passed**MOT #8** 2018-12-27 12:25**MOT test number** 738275139432**Result** ✓ Passed**MOT #7** 2017-12-28 09:38**MOT test number** 404671365800**Result** ✓ Passed**MOT #6** 2016-12-29 11:36**MOT test number** 637584563399**Result** ✓ Passed**MOT #5** 2016-12-29 11:36**MOT test number** 478267963965**Result** ✗ Failed**Pass with rectification** Offside Rear Rear position lamp(s) not working (1.1.A.3b)

**MOT #4** 2015-12-29 09:58**MOT test number** 942081205364**Result** ✓ Passed**MOT #3** 2014-12-29 09:35**MOT test number** 627193864327**Result** ✓ Passed**MOT #2** 2014-01-08 16:03**MOT test number** 288478904000**Result** ✓ Passed**MOT #1** 2013-01-09 13:00**MOT test number** 417449803022**Result** ✓ Passed

**Advice** Nearside Rear Suspension arm rubber bush deteriorated but not resulting in excessive movement  
(2.4.G.2)

**Notice** Windscreen wiper blades smearing slightly

**Advice** Offside Rear Suspension arm rubber bush deteriorated but not resulting in excessive movement  
(2.4.G.2)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
9 January 2025

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	336
<b>MOT expiry date</b>	9 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-01-09
Last registration	2023-12-21
Complete history	<a href="#">See info</a>



Registration #1	2010-01-09	14 mi
Registration #2	2013-01-09	23.595 mi
Registration #3	2014-01-08	31.527 mi
Registration #4	2014-12-29	38.906 mi
Registration #5	2015-12-29	45.754 mi
Registration #6	2016-12-29	53.456 mi
Registration #7	2016-12-29	53.456 mi
Registration #8	2017-12-28	61.002 mi
Registration #9	2018-12-27	70.280 mi
Registration #10	2019-12-26	79.558 mi
Registration #11	2020-12-25	88.836 mi
Registration #12	2021-12-24	98.114 mi
Registration #13	2022-12-23	107.392 mi
Registration #14	2023-12-22	116.670 mi
Registration #15	2023-12-21	125.948 mi
Registration #16	2023-12-20	135.226 mi
Registration #17	2023-12-19	144.504 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1442 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	957553