



PEUGEOT

SFI5DSZ


report date: 2024-03-29

General information

Make	PEUGEOT
Model	HORIZON
Colour	Blue
Year of manufacture	2015
Gearbox	-

Engine & fuel consumption

Engine capacity	1.560 cc
Fuel type	Diesel
CO2 emission	115 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-07-30
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-10-28
MOT pass rate	60 %
MOT passed	6
Failed MOT tests	4
Total advice items	23
Total items failed	7

MOT #10	2023-10-19 16:25
MOT test number	724770655791
Result	✓ Passed
Next expiry date	2024-10-28
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #9	2023-10-19 09:03
MOT test number	401074543655
Result	✗ Failed
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MOT #8	2022-10-10 13:39
MOT test number	926667132075
Result	✓ Passed

**MOT #7**

2021-10-29 13:58

**MOT test number**

249213218240

**Result**

✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #6**

2021-10-29 13:58

**MOT test number**

546866486940

**Result**

✗ Failed

- Pass with rectification** Nearside Rear Seat belt anchorage loose (7.1.1 (b))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #5** 2020-10-20 15:04**MOT test number** 941758257053**Result** ✓ Passed**MOT #4** 2019-05-31 13:26**MOT test number** 732215194680**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #3** 2019-05-31 13:26**MOT test number** 635727083630**Result** ✗ Failed**Pass with rectification** Central Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #2** 2018-05-31 13:32**MOT test number** 465079388419**Result** ✓ Passed**Advice** Items removed from driver's view prior to test**MOT #1** 2018-05-31 13:32**MOT test number** 850383902147**Result** ✗ Failed**Pass with rectification** Windscreen washer not working (3.5 (a))**Advice** Items removed from driver's view prior to test



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
28 October 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	154
<b>MOT expiry date</b>	28 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >





Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-03-03
Last registration	2023-10-19
Complete history	<a href="#">See info</a>



Registration #1	2015-03-03	22 mi
Registration #2	2018-05-31	13.875 mi
Registration #3	2018-05-31	13.875 mi
Registration #4	2019-05-31	15.296 mi
Registration #5	2019-05-31	15.296 mi
Registration #6	2020-10-20	16.764 mi
Registration #7	2023-10-19	22.000 mi
Registration #8	2023-10-19	22.000 mi
Registration #9	2023-10-19	22.000 mi
Registration #10	2023-10-19	22.000 mi
Registration #11	2023-10-19	22.000 mi
Registration #12	2023-10-19	22.000 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	79%
Pedestrian	37%
Safety systems	97%
Overall rating	77%
Video	<a href="#">see crash video</a>



Additional information

Number of seats	5
Engine number	JBFR0018442