



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	IQ VVT-I IQ
Colour	White
Year of manufacture	2010
Top speed	93 mph
0 - 60 mph	15.3 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	67 BHP
Max. torque	91 Nm at 4.800 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	49.6 mpg
Consumption extra urban	68.9 mpg
Consumption combined	60.1 mpg
CO2 emission	110 g/km
CO2 label	B







Internet history

Entry 1

Date	2021-06-06
Pictures	19
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-05-18
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	13
Total items failed	8

MOT #15	2023-05-10 15:17
MOT test number	701928090561
Result	✓ Passed
Next expiry date	2024-05-18

MOT #14	2023-05-09 12:03
MOT test number	155890394145
Result	✗ Failed

- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 2.7mm (5.2.3 (e))
- Advice** Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm 1.5mm (5.2.3 (e))
- Advice** Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing perishing (5.2.3 (d) (ii))

**MOT #13** 2022-04-27 10:11**MOT test number** 562637482072**Result** ✓ Passed**Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**MOT #12** 2022-04-27 10:11**MOT test number** 444403964334**Result** ✗ Failed**Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**MOT #11** 2021-05-19 06:51**MOT test number** 426829687228**Result** ✓ Passed**MOT #10** 2021-05-19 06:51**MOT test number** 765361489968**Result** ✗ Failed**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Pass with rectification** Offside Front Headlamp aim too high (4.1.2 (a))**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Pass with rectification** Nearside Front Headlamp aim too high (4.1.2 (a))**MOT #9** 2020-09-09 14:08**MOT test number** 199783537554**Result** ✓ Passed

**MOT #8** 2019-09-10 09:27**MOT test number** 379315991393**Result** ✓ Passed**Advice** Nearside rear and offside rear tyres cracking on walls slightly**MOT #7** 2018-09-17 09:49**MOT test number** 796356014050**Result** ✓ Passed**Advice** Brake hose has slight corrosion to ferrule front and rear (1.1.12 (f) (i))**MOT #6** 2017-08-21 09:55**MOT test number** 360335126285**Result** ✓ Passed**MOT #5** 2016-08-25 08:44**MOT test number** 303919807679**Result** ✓ Passed**MOT #4** 2015-08-24 11:28**MOT test number** 711150602605**Result** ✓ Passed**MOT #3** 2015-08-24 11:28**MOT test number** 367112615439**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (1.8)**Pass with rectification** Offside Headlamp aim too low (1.8)



MOT #2	2014-08-29 11:45
MOT test number	168551844242
Result	✓ Passed
MOT #1	2013-08-05 10:02
MOT test number	528167813278
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
18 May 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	18 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	SG60HHJ
Plate since	2019-09-29
Current registration	SG60HHJ
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-09-01
Last registration	2023-05-10
Complete history	See info



Registration #1	2010-09-01	23 mi
Registration #2	2013-08-05	3.653 mi
Registration #3	2014-08-29	9.472 mi
Registration #4	2015-08-24	13.743 mi
Registration #5	2015-08-24	13.743 mi
Registration #6	2016-08-25	18.319 mi
Registration #7	2017-08-21	22.202 mi
Registration #8	2018-09-17	24.995 mi
Registration #9	2019-09-10	25.415 mi
Registration #10	2019-09-10	25.415 mi
Registration #11	2019-09-10	25.415 mi
Registration #12	2019-09-10	25.415 mi
Registration #13	2019-09-10	25.415 mi
Registration #14	2019-09-10	25.415 mi
Registration #15	2019-09-10	25.415 mi
Registration #16	2019-09-10	25.415 mi
Registration #17	2019-09-10	25.415 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	71%
Pedestrian	54%
Safety systems	86%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1680 mm
Height	1500 mm
Length	2985 mm
Wheel base	2000 mm
Kerb weight	845 kg
Max. allowed weight	1215 kg

Additional information

Fuel tank capacity	32 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	1KR1035293