



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	207 HDI ACTIVE
Colour	Black
Year of manufacture	2012
Top speed	112 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	92 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	110 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-07-01
Pictures	51
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-09-06
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	32
Total items failed	16

MOT #14	2023-09-07 10:22
MOT test number	800489138254
Result	✓ Passed
Next expiry date	2024-09-06
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge on 3mm (5.2.3 (e))
Advice	Rear exhaust heat shield loose
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Rear Exhaust mounting defective (6.1.2 (a))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge on 3mm (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge on 3mm (5.2.3 (e))

MOT #13	2022-07-22 15:37
MOT test number	124954685871
Result	✓ Passed
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #12**

2022-07-22 09:05

**MOT test number**

546799409928

**Result****✗ Failed**

- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #11**

2021-06-24 13:42

**MOT test number**

893437146481

**Result****✓ Passed****MOT #10**

2021-06-23 13:59

**MOT test number**

429767340444

**Result****✗ Failed**

- Fail** Parking brake lever defective so that it cannot be satisfactorily operated (1.1.6 (d))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

**MOT #9**

2020-07-15 09:03

**MOT test number**

166930488780

**Result****✓ Passed**

- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Front wipers deteriorated
- Advice** Coil spring corroded both rear springs (5.3.1 (b) (i))

**MOT #8** 2020-07-14 10:03**MOT test number** 423161246559**Result** ✗ Failed

- Fail** Offside Rear Position lamp not working (4.2.1 (a) (ii))
- Fail** Nearside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Brake pad(s) wearing thin fronts (1.1.13 (a) (ii))
- Fail** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Exhaust mounting defective both front and rear corroded insecure (6.1.2 (a))
- Fail** Nearside Rear Position lamp not working (4.2.1 (a) (ii))
- Fail** Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Coil spring corroded both rear springs (5.3.1 (b) (i))
- Advice** Brake disc worn, pitted or scored, but not seriously weakened both fronts (1.1.14 (a) (ii))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Front wipers deteriorated
- Fail** Offside Front Position lamp not working sidelight (4.2.1 (a) (ii))

**MOT #7** 2019-06-17 08:23**MOT test number** 117180382708**Result** ✓ Passed

- Advice** Exhaust rear hanger corroded/insecure
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #6** 2019-06-11 08:26**MOT test number** 936407146921**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Rear Seat belt not functioning as intended seat belt catch defective (7.1.2 (c))**Advice** Exhaust rear hanger corroded/insecure**MOT #5** 2018-06-19 08:35**MOT test number** 615326979550**Result** ✓ Passed**MOT #4** 2017-06-19 13:57**MOT test number** 975703339363**Result** ✓ Passed**MOT #3** 2017-06-19 12:02**MOT test number** 217149811543**Result** ✗ Failed**Fail** Rear Exhaust system not adequately supported (7.1.1)**Fail** Offside Front front brake binding (3.7.B.1)**Fail** Nearside Front front brake binding (3.7.B.1)**MOT #2** 2016-06-20 11:43**MOT test number** 230307549904**Result** ✓ Passed**Advice** Engine cover fitted.**Advice** Under shields fitted.



MOT #1	2015-06-22 09:17
MOT test number	438003775171
Result	✓ Passed
Notice	Under-trays fitted obscuring some underside components
Notice	Engine covers fitted obscuring some components in the engine bay



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
6 September 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	125
<b>MOT expiry date</b>	6 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	0
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-03-23
Last registration	2023-09-07
Complete history	<a href="#">See info</a>



Registration #1	2012-03-23	29 mi
Registration #2	2015-06-22	17.875 mi
Registration #3	2016-06-20	21.382 mi
Registration #4	2017-06-19	29.163 mi
Registration #5	2017-06-19	29.163 mi
Registration #6	2018-06-19	37.266 mi
Registration #7	2019-06-11	49.593 mi
Registration #8	2019-06-17	49.826 mi
Registration #9	2019-06-20	50.000 mi
Registration #10	2019-06-20	50.000 mi
Registration #11	2019-06-20	50.000 mi
Registration #12	2019-06-20	50.000 mi
Registration #13	2019-06-20	50.000 mi
Registration #14	2019-06-20	50.000 mi
Registration #15	2019-06-20	50.000 mi
Registration #16	2019-06-20	50.000 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	82%
Children	81%
Pedestrian	53%
Safety systems	83%
Overall rating	76%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1815 mm
Height	1498 mm
Length	4276 mm
Wheel base	2608 mm
Kerb weight	1410 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	JBEE0158928