



SHI4KWY

report date: 2024-03-29

General information

Make	CITROEN
Model	DS4 E-HDI AIRDREAM DSTYLE
Colour	Grey
Year of manufacture	2014
Top speed	118 mph
0 - 60 mph	12.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	65.7 mpg
CO2 emission	113 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-01-29
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-03-19
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	23
Total items failed	7

MOT #11	2024-03-20 17:08
---------	------------------

MOT test number	676106984625
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2025-03-19
------------------	------------

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged (5.2.3 (d) (ii))

**MOT #10**

2024-03-14 11:03

**MOT test number**

963620918958

**Result****✗ Failed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Offside Rear Tyre slightly damaged (5.2.3 (d) (ii))

**MOT #9**

2023-03-14 15:21

**MOT test number**

115140301547

**Result****✓ Passed****MOT #8**

2023-03-14 09:25

**MOT test number**

931454055033

**Result****✗ Failed**

- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Nearside Front Headlamp aim unable to be tested (4.1.2 (b))
- Minor** Front Windscreen wiper blade defective (3.4 (b) (i))
- Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MOT #7** 2022-03-02 15:26**MOT test number** 937528918705**Result** ✓ Passed

**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #6** 2021-03-15 14:23**MOT test number** 860446580647**Result** ✓ Passed

**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #5** 2020-09-24 15:17**MOT test number** 353014443126**Result** ✓ Passed

**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #4** 2019-03-27 10:50**MOT test number** 646306114801**Result** ✓ Passed**MOT #3** 2019-03-27 10:02**MOT test number** 489071253834**Result** ✗ Failed

**Fail** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**Fail** Nearside Headlamp aim too low (4.1.2 (a))

**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #2** 2018-04-11 08:51**MOT test number** 166665369011**Result** ✓ Passed



MOT #1	2017-03-10 12:34
MOT test number	576182712045
Result	✓ Passed
Advice	Nearside Rear Nail in tyre
Advice	Nearside Front Nail in tyre



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
19 March 2025

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	307
<b>MOT expiry date</b>	19 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-05-09
Last registration	2024-03-20
Complete history	<a href="#">See info</a>



Registration #1	2014-05-09	10 mi
Registration #2	2017-03-10	18.579 mi
Registration #3	2018-04-11	23.577 mi
Registration #4	2019-03-27	33.955 mi
Registration #5	2019-03-27	33.955 mi
Registration #6	2020-09-24	45.656 mi
Registration #7	2020-09-24	45.656 mi
Registration #8	2020-09-24	45.656 mi
Registration #9	2020-09-24	45.656 mi
Registration #10	2020-09-24	45.656 mi
Registration #11	2020-09-24	45.656 mi
Registration #12	2020-09-24	45.656 mi
Registration #13	2020-09-24	45.656 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	80%
Pedestrian	43%
Safety systems	97%
Overall rating	79%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1810 mm
Height	1523 mm
Length	4275 mm
Wheel base	2612 mm
Kerb weight	1320 kg
Max. allowed weight	1810 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JBFV0033073