





report date: 2024-03-29

## General information

Make	VOLVO
Model	S60 D5 R-DESIGN LUX NAV
Colour	Silver
Year of manufacture	2013
Top speed	143 mph
0 - 60 mph	7.1 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	212 BHP
Max. torque	440 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	61.4 mpg
Consumption combined	47.9 mpg
CO2 emission	154 g/km
CO2 label	G



CarCheck.co.uk page 1/11



KM63GZL report date: 2024-03-29


## Internet history

#### Entry 3

Date 2022-12-13


Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 2

Date	2022-11-14
Pictures	0
Listing price	View report

#### source: carcraft.co.uk

#### Entry 1

Date 2021-10-05

Pictures 4

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2025-01-04
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	2
Total items failed	2

MOT #8	2024-01-05 14:12
MOT test number	624791584378
Result	✓ Passed
Next expiry date	2025-01-04

MOT #7	2022-08-01 13:29
MOT test number	609545647749
Result	✓ Passed

MOT #6	2021-08-09 13:38
MOT test number	897602250324
Result	✓ Passed

MOT #5	2020-08-11 13:33
MOT test number	994313974621
Result	∠ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened x2 lipped (1.1.14 (a) (ii))

MOT #4	2019-05-08 15:26
MOT test number	501811549420
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #3 2019-05-08 15:04

**MOT test number** 401975808158

**Result** X Failed

Fail Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #2 2018-05-17 11:01

**MOT test number** 446073334639

**Result** ✓ Passed

MOT #1 2017-05-24 12:54

**MOT test number** 251466086857

**Result** ✓ Passed

**Advice** Nearside Front tyre cut on wall

CarCheck.co.uk page 4/11



report date: 2024-03-29

#### Tax & MOT check



Tax status	Valid until 1 February
Days left	277
MOT expiry date	4 January 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

#### Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



factor scincore

KM63GZL

report date: 2024-03-29

More info >

# Owner history For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report <a href="here">here</a>. More info > Plate changes See in this check if this VOLVO had different number plates. about of pliates

CarCheck.co.uk page 8/11



report date: 2024-03-29

#### Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 9/11



KM63GZL report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-11-20
Last registration	2024-01-05
Complete history	See info



Registration #1	2013-11-20	28 mi
Registration #2	2017-05-24	18.475 mi
Registration #3	2018-05-17	22.426 mi
Registration #4	2019-05-08	24.568 mi
Registration #5	2019-05-08	24.568 mi
Registration #6	2020-08-11	25.242 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		71.777 es

More info >

CarCheck.co.uk page 10/11



KM63GZL report date: 2024-03-29

Car features

50225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	***
Video	see crash video



# Dimensions & weight

Width	1865 mm
Height	1484 mm
Length	4628 mm
Wheel base	2776 mm
Kerb weight	1642 kg
Max. allowed weight	2110 kg

## Additional information

Fuel tank capacity	67 I	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5	page 11/11

Number of axles2Engine number1375745