




report date: 2024-03-28

General information

Make	VAUXHALL
Model	ANTARA SE NAV CDTI
Colour	Grey
Year of manufacture	2011
Top speed	124 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	181 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.8 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.8 mpg
CO2 emission	175 g/km
CO2 label	H





Internet history

Entry 2

Date	2024-01-23
Pictures	30
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-06-15
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-04
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	54
Total items failed	15

MOT #15	2023-09-05 09:23
MOT test number	142018512158
Result	✓ Passed
Next expiry date	2024-09-04
Advice	Nearside Front Tyre worn close to legal limit/worn on edge Outer edge (5.2.3 (e))
Advice	Rear Suspension arm corroded but not seriously weakened Both sides lower arms (5.3.3 (b) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #14**

2023-09-04 16:27

MOT test number

450372722008

Result

✗ Failed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge Outer edge (5.2.3 (e))
- Fail** Offside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Advice** Rear Suspension arm corroded but not seriously weakened Both sides lower arms (5.3.3 (b) (i))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #13

2022-08-09 10:56

MOT test number

417945821063

Result

✓ Passed

- Advice** Oil leak, but not excessive suspect n/s driveshaft (8.4.1 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing 235/55r18 (5.2.3 (d) (ii))
- Advice** Offside Rear Suspension arm attachment bracket modified but not seriously weakened Front rear trailing arm bushes (5.3.3 (c) (i))
- Advice** Rear seats not tested due to no access
- Advice** Nearside Rear Suspension arm attachment bracket modified but not seriously weakened Front rear trailing arm bushes (5.3.3 (c) (i))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Power steering pipe/hose slightly damaged Both pipes not secure to front subframe (2.1.5 (g) (i))

MOT #12

2021-06-15 09:46

MOT test number

805421582030

Result

✓ Passed

**MOT #11** 2020-07-08 14:58**MOT test number** 823026890282**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened inner (1.1.14 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10** 2020-07-06 08:43**MOT test number** 472985792872**Result** ✗ Failed**Advice** Front Direction indicator slightly discoloured both (4.4.3 (a))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened inner (1.1.14 (a) (ii))**Fail** Nearside Brake pipe excessively corroded main at rear (1.1.11 (c))**Fail** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Brake pipe excessively corroded main at rear (1.1.11 (c))**Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**MOT #9** 2019-11-12 16:55**MOT test number** 695586984460**Result** ✓ Passed**MOT #8** 2019-11-12 13:19**MOT test number** 924972317059**Result** ✗ Failed**Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))



MOT #7	2018-11-07 15:54
MOT test number	220469507881
Result	✓ Passed
Advice	Advise both front rear wishbone arm bushes minor wear
Advice	Advise oil sweat at engine area

MOT #6	2018-11-07 10:30
MOT test number	693138978659
Result	✗ Failed
Advice	Advise both front rear wishbone arm bushes minor wear
Fail	Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
Advice	Advise oil sweat at engine area



MOT #5 2017-11-25 10:10

MOT test number 905473781655

Result ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit At 2.99mm 235/55/18 (4.1.E.1)
- Advice** Rear Sub-frame corroded but not seriously weakened (2.4.G.1)
- Advice** Engine oil leak
- Advice** Offside Front Lower Suspension arm corroded but not seriously weakened (2.4.G.1)
- Advice** Offside Rear Lower Suspension arm corroded but not seriously weakened (2.4.G.1)
- Advice** Offside Front Macpherson strut corroded but not seriously weakened (2.4.G.1)
- Advice** Front Sub-frame corroded but not seriously weakened (2.4.G.1)
- Advice** Nearside Front Lower Suspension arm corroded but not seriously weakened (2.4.G.1)
- Advice** Oil leak at A/C compressor
- Advice** Nearside Rear Lower Suspension arm corroded but not seriously weakened (2.4.G.1)
- Advice** Nearside Front Macpherson strut corroded but not seriously weakened (2.4.G.1)
- Advice** Rear Brake pad(s) wearing thin Just above legal limit of 1.5mm (3.5.1g)

MOT #4 2016-12-03 11:53

MOT test number 149784798003

Result ✓ Passed

- Advice** Rear Inner Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Tyre starting to wear on inner edge 235/55/18
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt



MOT #3 2016-11-26 10:27

MOT test number 321101874593

Result ✗ Failed

- Advice** Rear Inner Brake pad(s) wearing thin (3.5.1g)
- Fail** Nearside Front Inner Tyre has ply or cords exposed Worn exposing cord 235/55/18 (4.1.D.1b)
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm 235/55/18 (4.1.E.1)
- Fail** Offside Registration plate lamp not working (1.1.C.1d)
- Fail** Nearside Front Inner Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice** Offside Rear Tyre worn close to the legal limit At 1.98mm tyre starting to crack and perish 235/55/18 (4.1.E.1)
- Advice** Offside Front Inner Tyre starting to wear 235/55/18
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #2 2015-11-21 08:36

MOT test number 741540974742

Result ✓ Passed

- Advice** Front Inner Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front Tyre worn close to the legal limit at 2.97mm also cut on side wall not into ply or cord (4.1.E.1)
- Advice** Sill covers
- Advice** Nearside Rear Tyre worn close to the legal limit at 2.51mm tyre starting to perish (4.1.E.1)
- Advice** Rear Inner Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Rear Tyre worn close to the legal limit at 3.01mm tyre starting to perish (4.1.E.1)



MOT #1	2014-11-22 10:15
MOT test number	179436824310
Result	✓ Passed
Notice	HEADLAMPS WHERE SET AT ZERO..ON THE DASH
Notice	Engine covers fitted obscuring some components in the engine bay
Notice	ALL THE BRAKE PIPES ARE PLASTIC COATED
Notice	BOTH FRONT STRUTS ARE SLIGHTLY STIFF



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
4 September 2024

Tax status	Valid until 1 January
Days left	246
MOT expiry date	4 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 SM61KBV
Plate since	2019-03-28
Current registration	 SM61KBV
Plate since	2019-03-28

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-11-30
Last registration	2023-09-05
Complete history	See info



Registration #1	2011-11-30	29 mi
Registration #2	2014-11-22	23.036 mi
Registration #3	2015-11-21	26.684 mi
Registration #4	2016-11-26	31.432 mi
Registration #5	2016-12-03	31.438 mi
Registration #6	2017-11-25	34.640 mi
Registration #7	2018-11-07	37.825 mi
Registration #8	2018-11-07	37.825 mi
Registration #9	2019-11-12	61.684 mi
Registration #10	2019-11-12	61.684 mi
Registration #11	2019-11-12	61.684 mi
Registration #12	2019-11-12	61.684 mi
Registration #13	2019-11-12	61.684 mi
Registration #14	2019-11-12	61.684 mi
Registration #15	2019-11-12	61.684 mi
Registration #16	2019-11-12	61.684 mi
Registration #17	2019-11-12	61.684 mi
Registration #18	2019-11-12	61.684 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2085 mm
Height	1747 mm
Length	4576 mm
Wheel base	2707 mm
Kerb weight	1896 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	027962KX