



RENAULT

SB06SLU


report date: 2024-03-28

General information

Make	RENAULT
Model	SCENIC EXPRESSION VVT 111 SCENIC EU4
Colour	Gold
Year of manufacture	-
Top speed	115 mph
0 - 60 mph	12.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	148 Nm at 3.750 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	29.4 mpg
Consumption extra urban	47.1 mpg
Consumption combined	38.7 mpg





MOT history



MOT #16	2022-09-20 10:52
MOT test number	600206866064
Result	✓ Passed
Next expiry date	2023-09-19

- Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Play in steering rack inner joint(s)
- Advice** Oil leak, but not excessive engine area/under tray oily (8.4.1 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Nail in tyre X2 nails
- Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened & surface slightly rusted inner (1.1.14 (a) (ii))
- Minor** Offside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge Tread depth 1.8 mm in poor condition (5.2.3 (e))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Play in steering rack inner joint(s)
- Advice** Front Registration plate deteriorated but not likely to be misread slightly cracked (0.1 (b))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened & surface slightly rusted inner (1.1.14 (a) (ii))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))

**MOT #15** 2021-09-13 14:51**MOT test number** 743965551717**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #14** 2020-09-03 12:00**MOT test number** 544563046782**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #13** 2019-09-10 15:13**MOT test number** 592920676093**Result** ✓ Passed**MOT #12** 2019-02-11 11:26**MOT test number** 384134404186**Result** ✓ Passed**MOT #11** 2018-02-22 15:47**MOT test number** 186730896257**Result** ✓ Passed**MOT #10** 2017-02-16 11:01**MOT test number** 541269332199**Result** ✓ Passed

**MOT #9** 2016-02-02 13:41**MOT test number** 998281746561**Result** ✓ Passed**MOT #8** 2015-02-10 11:32**MOT test number** 938891645087**Result** ✓ Passed

Advice Offside Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

MOT #7 2014-02-21 13:12**MOT test number** 938872854033**Result** ✓ Passed

Advice Nearside Rear Shock absorber has a light misting of oil (2.7.3)

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #6 2013-02-11 12:28**MOT test number** 508592343074**Result** ✓ Passed**MOT #5** 2013-02-11 12:28**MOT test number** 559742243085**Result** ✗ Failed

Pass with rectification Nearside Steering rack gaiter insecure (2.2.D.2d)

MOT #4 2012-02-16 14:56**MOT test number** 358137042056**Result** ✓ Passed

Advice Nearside Inner Track rod end ball joint has slight play (2.2.B.1f)

Advice Rear Brake pad(s) wearing thin (3.5.1g)



MOT #3	2011-03-01 12:09
MOT test number	755760161086
Result	✓ Passed
MOT #2	2010-03-02 12:39
MOT test number	570641760082
Result	✓ Passed
MOT #1	2009-05-21 14:29
MOT test number	841401849131
Result	✓ Passed
<div><div>Notice</div>Brakes binding at o/s/r</div> <div><div>Advice</div>Nearside Rear Tyre worn close to the legal limit (4.1.E.1)</div> <div><div>Notice</div>Rear wiper torn</div>	



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	 
Plate since	2024-03-28
Current registration	 
Plate since	2024-03-28

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2006-07-17
Last registration	2022-09-20
Complete history	See info



Registration #1	2006-07-17	12 mi
Registration #2	2009-05-21	11.871 mi
Registration #3	2010-03-02	12.650 mi
Registration #4	2011-03-01	17.558 mi
Registration #5	2012-02-16	21.956 mi
Registration #6	2013-02-11	25.746 mi
Registration #7	2014-02-21	28.802 mi
Registration #8	2015-02-10	31.996 mi
Registration #9	2016-02-20	35.217 mi
Registration #10	2017-02-20	38.438 mi
Registration #11	2018-02-20	41.659 mi
Registration #12	2019-02-20	44.880 mi
Registration #13	2020-02-20	48.101 mi
Registration #14	2021-02-20	51.322 mi
Registration #15	2022-02-20	54.543 mi
Registration #16	2023-02-20	57.764 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2007 mm
Height	1600 mm
Length	4140 mm
Wheel base	2685 mm
Kerb weight	1320 kg
Max. allowed weight	1915 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D089414