



CITROËN



FE07AZO


report date: 2024-03-28

General information

Make	CITROEN
Model	XSARA 16V SX
Colour	Red
Year of manufacture	2007
Top speed	118 mph
0 - 60 mph	11.5 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	110 BHP
Max. torque	147 Nm at 4.000 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	51.4 mpg
Consumption combined	39.2 mpg
CO2 emission	172 g/km
CO2 label	H






Internet history

Entry 1

Date	2021-12-27
Pictures	53
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-04-06
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	25
Total items failed	9

MOT #19	2024-03-26 11:18
MOT test number	590732112794
Result	✓ Passed
Next expiry date	2025-04-06
Advice	Front Inner Play in steering rack inner joint(s) n/s and o/s
Advice	Mid exhaust box outter skin corroded

MOT #18	2024-03-26 10:10
MOT test number	760223455659
Result	✗ Failed
Advice	Front Inner Play in steering rack inner joint(s) n/s and o/s
Fail	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
Advice	Mid exhaust box outter skin corroded



MOT #17

2023-04-03 10:07

MOT test number

861020467985

Result

✓ Passed

- Advice

Nearside Front Play in steering rack inner joint(s)
- Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice

Offside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))
- Advice

Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16

2023-04-03 09:02

MOT test number

761658263468

Result

✗ Failed

- Advice

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice

Nearside Front Play in steering rack inner joint(s)
- Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Offside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))
- Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice

Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail

Front Position lamp not working n/s and o/s (4.2.1 (a) (ii))

**MOT #15**

2022-03-17 11:52

MOT test number

950071822176

Result

✓ Passed

Advice Nearside Front Inner Track rod end ball joint has slight play (2.1.3 (b) (i))**Advice** Vehicle has been under sealed**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #14**

2022-03-02 13:03

MOT test number

545375276363

Result

✗ Failed

Fail Offside Front Suspension component mounting prescribed area excessively corroded significantly reducing structural strength outer sill (5.3.6 (a) (i))**Advice** Shock absorbers has a slightly worn bush both rear lower (5.3.2 (c))**Fail** Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**Fail** Emissions not tested major exhaust leak (8.2.1.2 (d))**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Fail** Exhaust emissions likely to be affected by an exhaust leak excessively leaking from back box (8.2.2.1 (b))**Advice** Middle and rear exhaust rusty**MOT #13**

2021-04-07 14:28

MOT test number

455124745665

Result

✓ Passed

**MOT #12** 2021-04-07 12:14**MOT test number** 800148768468**Result** ✗ Failed**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Rear Exhaust has a major leak of exhaust gases BOX (6.1.2 (a))**MOT #11** 2020-08-29 08:00**MOT test number** 767974653200**Result** ✓ Passed**Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**MOT #10** 2019-05-11 08:35**MOT test number** 452167180086**Result** ✓ Passed**MOT #9** 2018-05-12 09:33**MOT test number** 933400527694**Result** ✓ Passed**MOT #8** 2017-05-06 07:33**MOT test number** 607489722098**Result** ✓ Passed**Advice** Child Seat fitted not allowing full inspection of adult belt**Advice** Items removed from driver's view prior to test**MOT #7** 2016-05-18 15:08**MOT test number** 591380772415**Result** ✓ Passed



MOT #6	2015-05-23 09:52
---------------	------------------

MOT test number	296353945491
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2014-05-14 12:42
---------------	------------------

MOT test number	216144634470
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2013-05-18 08:18
---------------	------------------

MOT test number	156008733159
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2012-05-22 12:55
---------------	------------------

MOT test number	147313142114
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2011-05-26 10:29
---------------	------------------

MOT test number	775426541197
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2010-05-04 11:32
---------------	------------------

MOT test number	262944520415
------------------------	--------------

Result	✓ Passed
---------------	----------



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
6 April 2025

Tax status	Valid until 1 September
Days left	126
MOT expiry date	6 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	FE07AZO
Plate since	2019-09-28
Current registration	FE07AZO
Plate since	2019-09-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-06-01
Last registration	2024-03-26
Complete history	See info



Registration #1	2007-06-01	8 mi
Registration #2	2010-05-04	21.507 mi
Registration #3	2011-05-26	30.918 mi
Registration #4	2012-05-22	40.452 mi
Registration #5	2013-05-18	49.676 mi
Registration #6	2014-05-14	58.021 mi
Registration #7	2015-05-23	64.271 mi
Registration #8	2016-05-18	70.389 mi
Registration #9	2017-05-06	77.352 mi
Registration #10	2018-05-12	83.952 mi
Registration #11	2019-05-11	91.179 mi
Registration #12	2020-05-10	99.357 mi
Registration #13	2021-05-10	107.535 mi
Registration #14	2022-05-10	115.713 mi
Registration #15	2023-05-10	123.891 mi
Registration #16	2024-03-26	132.069 mi
Registration #17	2024-03-26	132.069 mi
Registration #18	2024-03-26	132.069 mi
Registration #19	2024-03-26	132.069 mi
Registration #20	2024-03-26	132.069 mi
Registration #21	2024-03-26	132.069 mi

More info >



Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1667 mm
Height	1521 mm
Length	3850 mm
Wheel base	2460 mm
Max. allowed weight	1597 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	FX6F3239543