





General information

Make	MAZDA
Model	CX-5 D SPORT NAV
Colour	White
Year of manufacture	2013
Top speed	139 mph
0 - 60 mph	7.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	173 BHP
Max. torque	420 Nm at 2.000 rpm
Engine capacity	2.191 сс
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	С








Internet history

Entry 2	
Date	2022-02-03
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 1

Date

Pictures

Listing price

2021-02-04

View report

10

source: autoonline.co.uk









MOT history

MOT expiry date	2024-12-02
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	17
Total items failed	2

MOT #10	2023-12-01 11:02
MOT test number	550269610987
Result	✓ Passed
Next expiry date	2024-12-02
Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement bush (5.3.4 (a) (i))	
Minor Offside Registration plate lamp inoperative in the case of multi (i))	iple lamps or light sources (4.7.1 (b)

MOT #9	2022-11-30 07:19
MOT test number	615278708787
Result	✓ Passed
MOT #8	2021-11-30 07:28
MOT test number	681506817338
Result	✓ Passed
MOT #7	2020-12-03 17:26
MOT test number	310811027849

Result

🗸 Passed





MOT #6	2020-12-03 17:26
MOT test number	587047359554
Result	× Failed
Pass with rectification the position lamps (4.7.2 (a	Nearside Rear Registration plate lamp does not illuminate simultaneously with))
Pass with rectification position lamps (4.7.2 (a))	Offside Rear Registration plate lamp does not illuminate simultaneously with the

MOT #5	2019-09-10 15:52
MOT test number	642689361610
Result	✓ Passed
Advice Offside Front Suspension arm pin or bush worn but not resulting in ex(i))	xcessive movement (5.3.4 (a)
Minor Nearside Rear Registration plate lamp inoperative in the case of multi (4.7.1 (b) (i))	ple lamps or light sources
Advice Nearside Front Suspension arm pin or bush worn but not resulting in (a) (i))	excessive movement (5.3.4

MOT #4		2019-09-10 08:37
MOT test numbe	er	563233198338
Result		🗙 Failed
DANGEROUS	Rear Brake disc in such a condition that it is seriously weakened bo	th (1.1.14 (a) (ii))
DANGEROUS	Rear Brake pad(s) less than 1.5 mm thick both (1.1.13 (a) (ii))	
Advice Offsic (i))	de Front Suspension arm pin or bush worn but not resulting in excess	ve movement (5.3.4 (a)
MAJOR Front	Windscreen wiper does not clear the windscreen effectively (3.4 (b)	(ii))
DANGEROUS	Front Brake disc in such a condition that it is seriously weakened bo	oth (1.1.14 (a) (ii))
DANGEROUS	Front Brake pad(s) less than 1.5 mm thick both (1.1.13 (a) (ii))	
MAJOR Offsic	de Front Position lamp not working (4.2.1 (a) (ii))	
Minor Nearsi (4.7.1 (b) (i))	ide Rear Registration plate lamp inoperative in the case of multiple la	mps or light sources
Advice Nears	side Front Suspension arm pin or bush worn but not resulting in exces	sive movement (5.3.4





MOT #3	2018-04-19 13:47
MOT test number	121616666487
Result	✓ Passed
Advice Brake disc worn, pitted or scored, but not seriously weakened all four (3.5.1i)	
NOT #2	2017 04 12 12 16
MOT #2	2017-04-13 12:16
MOT test number	238690452355
Result	🗸 Passed
MOT #1	2016-04-01 08:18
MOT test number	806565482888
Result	✓ Passed
Advice Brake disc worn, pitted or scored, but not seriously weakened both front (3.5.1	i)
Advice Front Brake pad(s) wearing thin (3.5.1g)	



Tax & MOT check

✓ Taxed Tax due: 1 January 2025	✓ MOT Expires: 2 December 2024
Tax status	Valid until 1 January
Days left	247
MOT expiry date	2 December 2024
Full MOT history	See MOT history
Tax calculation	

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date	F the state	
Category		LAMP
Туре		W.
Damage 2	Law .	PLL
Date	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
Category	ANG	
Туре	W	

Extra MAZDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 =





Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and a second sec	

	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-04-17
Last registration	2023-12-01
Complete history	<u>See info</u>



Registration #1	2013-04-17	9 mi
Registration #2	2016-04-01	41.471 mi
Registration #3	2017-04-13	54.953 mi
Registration #4	2018-04-19	74.546 mi
Registration #5	2019-09-10	81.327 mi
Registration #6	2019-09-10	81.327 mi
Registration #7	2020-12-03	85.672 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.707 mi
Registration #12		11.777 esi
Registration #13		11.227 mi





Safety ratings

NCAP rating	****
Adult	77%
Children	81%
Pedestrian	49%
Safety systems	71%
Overall rating	72%
Video	see crash video



Dimensions & weight	
Width	1840 mm
Height	1450 mm
Length	4865 mm
Wheel base	2830 mm
Kerb weight	1405 kg
Max. allowed weight	2055 kg
Additional information	
Fuel tank capacity	62 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Engine number	SH 30263142