





report date: 2024-03-29

General information

| Make | CITROEN |
|---------------------|------------------------------------|
| Model | BERLINGO 850 ENTERPRISE L1 BLUEHDI |
| Colour | White |
| Year of manufacture | 2018 |
| Top speed | 101 mph |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 100 BHP |
|-------------------------|---------------------|
| Max. torque | 254 Nm at 1.750 rpm |
| Engine capacity | 1.560 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 55.4 mpg |
| Consumption extra urban | 74.3 mpg |
| Consumption combined | 65.7 mpg |
| CO2 emission | 112 g/km |
| CO2 label | С |



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 2

Date 2021-06-29

Pictures 35

Listing price <u>View report</u>









source: heycar.co.uk

Entry 1

| Date | 2021-05-27 | |
|---------------|--------------------|--|
| Pictures | 1 | |
| Listing price | <u>View report</u> | |



source: autoonline.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT history

| MOT expiry date | 2024-06-22 |
|--------------------|------------|
| MOT pass rate | 67 % |
| MOT passed | 4 |
| Failed MOT tests | 2 |
| Total advice items | 10 |
| Total items failed | 1 |

| MOT #6 | 2023-06-07 10:40 |
|--|------------------|
| MOT test number | 900824222212 |
| Result | ✓ Passed |
| Next expiry date | 2024-06-22 |
| Minor Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) | |
| Advice Offside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #5 | | 2022-06-11 09:19 |
|----------|---|------------------|
| MOT test | number | 927379118216 |
| Result | | ✓ Passed |
| Minor | Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1 | .7 (g) (i)) |

| MOT #4 | 2021-06-23 08:09 |
|---|------------------|
| MOT test number | 364203779524 |
| Result | ✓ Passed |
| Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #3 2021-06-07 16:11

MOT test number 631307385473

Result X Failed

MAJOR Central Seat belt not functioning as intended (7.1.2 (c))

DANGEROUS Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

MAJOR Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))

MOT #2 2021-04-09 14:39

MOT test number 788792213401

Result \square Passed

Advice Both front tyres wearing low on edges

MOT #1 2021-04-09 14:39

MOT test number 141219111577

Result X Failed

Pass with rectification Offside Front Position lamp not working (4.2.1 (a) (ii))

Advice Both front tyres wearing low on edges

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



| Tax status | Valid until 1 November |
|------------------|------------------------|
| Days left | 185 |
| MOT expiry date | 22 June 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 39 |
|---------------------------|------------|
| Standard rate (12 months) | £ 320,00,- |
| Standard rate (6 months) | £ 176,00,- |

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

| \sim | | h:a | + |
|--------|------|-----|--------------|
| -C)V | vner | mis | \mathbf{I} |

| For how long did the current and previous owner(s) have this CITROEN? How many owne have? Check it in the premium report and see all owner registrations. Download the full r | | DEN |
|--|--|-----|
| | | |
| HARMAN CONTRACTOR CONT | | |
| *************************************** | | |
| *************************************** | | |
| ********* | | |
| *************************************** | | |
| *************************************** | | |
| | More info | > |
| Plate changes | | |
| See in this check if this CITROEN had different number plates. | | |
| Number of plates | | , |
| Current registration | NK NEW | |
| Plate since | | |
| Current registration | UK NE | |
| Plate since | | |
| | More info | > |

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| | |

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 9 |
| First mileage registration | 2018-03-31 |
| Last registration | 2023-06-07 |
| Complete history | See info |



| Registration #1 | 2018-03-31 | 29 mi |
|-----------------|------------|-----------|
| Registration #2 | 2021-04-09 | 70.242 mi |
| Registration #3 | 2021-04-09 | 70.242 mi |
| Registration #4 | | 11.777 es |
| Registration #5 | 2021-06-07 | 73.575 mi |
| Registration #6 | | 0.00 44 |
| Registration #7 | | 11.777 es |
| Registration #8 | | |
| Registration #6 | | 11.777 au |

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Safety ratings

| NCAP rating | *** | |
|----------------|-----------------|--|
| Adult | 56% | |
| Children | 74% | |
| Pedestrian | 63% | |
| Safety systems | 48% | |
| Overall rating | 59% | |
| Video | see crash video | |

Additional information

| Fuel tank capacity | 60 I |
|--------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 3 |
| Engine number | JBHB3279953 |

CarCheck.co.uk page 11/11