





report date: 2024-03-29

#### General information

| Make                | PEUGEOT           |
|---------------------|-------------------|
| Model               | 206 S             |
| Colour              | Silver            |
| Year of manufacture | -                 |
| Top speed           | 100 mph           |
| 0 - 60 mph          | 15.2 seconds      |
| Gearbox             | 4 speed automatic |

### Engine & fuel consumption

| Power                   | 75 BHP              |
|-------------------------|---------------------|
| Max. torque             | 120 Nm at 2.800 rpm |
| Cylinders               | 4                   |
| Fuel type               | Petrol              |
| Consumption city        | 29.7 mpg            |
| Consumption extra urban | 52.3 mpg            |
| Consumption combined    | 40.9 mpg            |



CarCheck.co.uk page 1/12



## Internet history

| Fn | trv   | 1 |
|----|-------|---|
|    | ILI Y | - |

| Lifety 1      |             |
|---------------|-------------|
| Date          | 2021-12-26  |
| Pictures      | 0           |
| Listing price | View report |

source: autotrader.co.uk

CarCheck.co.uk page 2/12



#### **MOT** history

MOT #182022-04-01 11:07MOT test number615258032756Result✓ PassedNext expiry date2023-03-31AdviceOil leak, but not excessive (8.4.1 (a) (i))AdviceFront Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #17

MOT test number

539085816357

Result

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Pass with rectification Nearside Front Position lamp not working (4.2.1 (a) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #16

MOT test number

Result

Advice Nearside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))

MOT #15

2020-03-05 16:26

MOT test number

140865219419

Result

✓ Passed

MOT #14

2019-03-09 09:13

MOT test number

143376317186

Result

✓ Passed

CarCheck.co.uk page 3/12



**MOT #13** 2018-03-21 14:42

MOT test number 380323449435

Result \rightarrow Passed

Advice

Nearside Play in steering rack inner joint(s) close to limit

**MOT #12** 2018-03-21 11:56

**MOT test number** 339288725876

**Result** X Failed

**Fail** Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)

Advice Nearside Play in steering rack inner joint(s) close to limit

**MOT #11** 2017-03-20 09:20

**MOT test number** 938262437565

**Result** ✓ Passed

**Advice** Nearside Play in steering rack inner joint(s)

**MOT #10** 2017-03-20 09:20

MOT test number 232876434634

Result X Failed

**Advice** Nearside Play in steering rack inner joint(s)

**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)

MOT #9 2016-03-11 12:00

**MOT test number** 721338724052

**Result** 
✓ Passed

**Advice** Offside Rear Starting to perish, 175 / 65 / 14.

**Advice** Steering system has slight free play detected at steering wheel (2.2.A.1b)

**Advice** Leak from power steering pump, (over filled).

CarCheck.co.uk page 4/12



| MOT #8  | 2015-03-09 08:54 |
|---|------------------|
| MOT test number                                       | 218058765071     |
| Result  | ✓ Passed         |
| Advice Nearside Ball joint has slight play (2.2.B.1f) |                  |

| Neurside Buil Joine Has slight play (2.2.B.11) |                  |
|--|------------------|
|  |                  |
| MOT #7   | 2014-03-15 10:51 |
| MOT test number                                | 138064174435     |
| Result   | ✓ Passed         |
|  |                  |
| MOT #6   | 2013-03-16 10:42 |
| MOT test number                                | 978835173087     |
| Result   | ✓ Passed         |
|  |                  |
| MOT #5   | 2012-03-16 16:34 |
| MOT test number                                | 948856872041     |
| Result   | ✓ Passed         |
|  |                  |
| MOT #4   | 2011-03-12 10:48 |
| MOT test number                                | 857261371059     |
| Result   | ✓ Passed         |
|  |                  |
| MOT #3   | 2010-03-24 11:59 |
| MOT test number                                | 582003180089     |
| Result   | ✓ Passed         |
|  |                  |
| MOT #2   | 2009-03-11 16:15 |
| MOT test number                                | 384330979099     |
| Result   | <b>✓</b> Passed  |

CarCheck.co.uk page 5/12



**MOT #1** 2008-03-03 11:52

**MOT test number** 412723568060

CarCheck.co.uk page 6/12



#### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="here">here</a> for the results.

| Damage 1 |  |
|----------|--|
| Date     |  |
| Category |  |
| Туре     |  |
| Damage 2 |  |
| Date     |  |
| Category |  |
| Туре     |  |



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



| O     | l- ! - 4  |
|-------|-----------|
| UWNER | nistorv   |
| Owner | ilistoi y |

| For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations. |             |
|--|-------------|
|  |             |
|  |             |
| ***************************************  |             |
|  |             |
| *******  |             |
| ***************************************  |             |
| ***************************************  |             |
|  | More info > |
| Plate changes  |             |
| See in this check if this PEUGEOT had different number plates.   |             |
| Number of plates   |             |
| Current registration   | OK SIE      |
| Plate since  |             |
| Current registration   | OK SIE      |
| Plate since  |             |
|  | More info > |

CarCheck.co.uk page 9/12



#### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
|                   |  |

**Contact info** 

More info >

CarCheck.co.uk page 10/12



## Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 20         |
| First mileage registration | 2005-03-30 |
| Last registration          | 2022-04-01 |
| Complete history           | See info   |



| Registration #1  | 2005-03-30 | 17 mi     |
|------------------|------------|-----------|
| Registration #2  | 2008-03-03 | 6.704 mi  |
| Registration #3  | 2009-03-11 | 11.029 mi |
| Registration #4  | 2010-03-24 | 17.093 mi |
| Registration #5  | 2011-03-12 | 21.698 mi |
| Registration #6  | 2012-03-16 | 27.510 mi |
| Registration #7  | 2013-03-16 | 32.770 mi |
| Registration #8  | 2014-03-15 | 37.868 mi |
| Registration #9  | 2015-03-09 | 42.559 mi |
| Registration #10 | 2016-03-11 | 50.716 mi |
| Registration #11 |            | 91.777 es |
| Registration #12 |            | D.777 es  |
| Registration #13 |            | 91.777 es |
| Registration #14 |            | 11.777 es |
| Registration #15 |            | 91.777 es |
| Registration #16 |            | 11.777 es |
| Registration #17 |            | 11.777 es |
| Registration #18 |            | 11.777 es |
| Registration #19 |            | 11.777 es |
| Registration #20 |            | 11.777 mg |

More info >

CarCheck.co.uk page 11/12



## Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

# Safety ratings

| NCAP rating | ***             |
|-------------|-----------------|
| Video       | see crash video |



# Dimensions & weight

| Width               | 1652 mm |
|---------------------|---------|
| Height              | 1433 mm |
| Length              | 3822 mm |
| Wheel base          | 2445 mm |
| Kerb weight         | 1055 kg |
| Max. allowed weight | 1480 kg |

## Additional information

| Fuel tank capacity                | 50 I                  |
|-----------------------------------|-----------------------|
| Fuel delivery                     | Multi-Point Injection |
| Number of doors                   | 3                     |
| Number of seats<br>CarCheck.co.uk | 5 page 12             |