





report date: 2024-03-28

General information

Make	BMW
Model	525 525I SE
Colour	Blue
Year of manufacture	2005
Top speed	147 mph
0 - 60 mph	8.3 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	215 BHP
Max. torque	250 Nm at 4.250 rpm
Engine capacity	2.497 сс
Cylinders	6
Fuel type	Petrol
Consumption city	22.6 mpg
Consumption extra urban	41.5 mpg
Consumption combined	31.7 mpg
CO2 emission	229 g/km
CO2 label	L



CarCheck.co.uk page 1/14



report date: 2024-03-28


Internet history

Entry 1

Date 2021-12-16

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-28

MOT history

MOT expiry date	2024-08-29
MOT pass rate	89 %
MOT passed	16
Failed MOT tests	2
Total advice items	21
Total items failed	3

MOT #18	2023-08-24 11:11
MOT test number	430235482362
Result	✓ Passed
Next expiry date	2024-08-29
Advice Front Tyre worn close to legal limit/worn on edge Both (5.2.3 (e))	
Advice Rear Handbrake has travel	

MOT #17	2022-08-30 15:30
MOT test number	309048078715
Result	✓ Passed
Advice Rear Brake pad(s) wearing thin Both (1.1.13 (a) (ii))	

MOT #16	2021-08-05 13:04
MOT test number	985128497766
Result	✓ Passed
Advice Nearside parking brake low reading Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

CarCheck.co.uk page 3/14



report date: 2024-03-28

MOT test number

Result

Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Fail

Offside Rear Brake pipe leaking on a hydraulic braking system (1.1.11 (b) (ii))

Advice

Nearside parking brake low reading

MOT #14

MOT test number

440766105216

Result

Advice Nearside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))

MOT test number

Result

Fail Exhaust hydrocarbon content after 2nd fast idle exceeds default limits (8.2.1.2 (b))

Fail Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))

CarCheck.co.uk page 4/14



report date: 2024-03-28

MOT #12	2019-09-12 10:	19
MOT test	number 9374588601	05
Result	✓ Pass	ed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Parking brake noisy	
Advice	Brake disc worn, pitted or scored, but not seriously weakened two front ,just passable (1.1.14 (a)	
Minor	Offside Front Position lamp light intensity obviously reduced (4.2.3 (a) (i))	
Advice	Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))	
Advice	Upper & lower covers fitted, some parts not visible	

MOT #11		2018-09-26 10:05
MOT test	number	195729567874
Result		✓ Passed
Advice	Upper & lower covers fitted, some parts not visible	
Advice	Nearside Child Seat fitted not allowing full inspection of adult belt	
Advice	Noise from handbrake	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened rusty (1.1.14	(a) (ii))

MOT #10	2017-10-04 12:48
MOT test number	727531054864
Result	✓ Passed
MOT #9	2016-09-20 09:53
MOT test number	219480936657
Result	✓ Passed

CarCheck.co.uk page 5/14



report date: 2024-03-28

MOT #8	2015-09-15 13:17
MOT test number	849265457066
Result	✓ Passed
MOT #7	2014-09-19 09:50
MOT test number	535712964257
Result	✓ Passed
MOT #6	2013-09-23 13:32
MOT test number	469666363210
Result	✓ Passed
MOT #5	2012-09-17 13:35
MOT test number	335131362278
Result	✓ Passed
MOT #4	2011-09-24 11:33
MOT test number	318697261292
Result	✓ Passed
MOT #3	2010-09-25 13:09
MOT test number	304568560290
Result	✓ Passed
MOT #2	2009-08-17 10:01
MOT test number	172899129279
Result	✓ Passed
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice Rear Brake pad(s) wearing thin (3.5.1g)	

CarCheck.co.uk page 6/14



report date: 2024-03-28

MOT #1 2008-08-14 09:57

MOT test number 153157628259

Result ✓ Passed

CarCheck.co.uk page 7/14





report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	29 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 8/14



report date: 2024-03-28

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-28

O	والمراجعة والمراجعة
Owner	nistorv

, ,		
For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report <u>I</u>		ve?

	More info	>
Plate changes		
See in this check if this BMW had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		3.0.0
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 11/14



VV55KZP

report date: 2024-03-28

Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2005-09-06
Last registration	2023-08-24
Complete history	See info



Registration #1	2005-09-06	19 mi
Registration #2	2008-08-14	86.555 mi
Registration #3	2009-08-17	90.575 mi
Registration #4	2010-09-25	93.420 mi
Registration #5	2011-09-24	95.032 mi
Registration #6	2012-09-17	96.353 mi
Registration #7	2013-09-23	98.342 mi
Registration #8	2014-09-19	100.072 mi
Registration #9	2015-09-15	102.280 mi
Registration #10	2016-09-20	104.382 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		
Registration #20		

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
50566	
50567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1981 mm
Height	1445 mm
Length	4805 mm
Wheel base	2830 mm
Kerb weight	1550 kg
Max. allowed weight	2185 kg

Additional information

· · · · · · · · · · · · · · · · · · ·	
Fuel tank capacity	70
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 14/14