



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	PASSAT TDI SPORT 5 STR
Colour	Grey
Year of manufacture	2009
Top speed	122 mph
0 - 60 mph	10.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	46.3 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-10-09
Pictures	19
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-28
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	30
Total items failed	9

MOT #16 2024-01-26 17:27

MOT test number 788877654903

Result ✓ Passed

Next expiry date 2025-01-28

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #15 2023-01-27 12:41

MOT test number 483271591707

Result ✓ Passed

Minor Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #14 2022-01-26 11:56

MOT test number 678375129017

Result ✓ Passed

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush has cracks (5.3.4 (a) (i))

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement rear bush has cracks (5.3.4 (a) (i))

**MOT #13**

2022-01-26 11:56

MOT test number

653566152832

Result**✗ Failed**

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush has cracks (5.3.4 (a) (i))

Pass with rectification Nearside Front Headlamp aim too low (4.1.2 (a))

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement rear bush has cracks (5.3.4 (a) (i))

Pass with rectification Rear Registration plate lamp missing in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Pass with rectification Offside Front Headlamp aim too high (4.1.2 (a))

MOT #12

2021-01-29 09:58

MOT test number

567063450396

Result**✓ Passed****MOT #11**

2019-06-20 09:58

MOT test number

611703259482

Result**✓ Passed**

Advice Offside Front Inner Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #10

2018-06-22 10:17

MOT test number

611365829966

Result**✓ Passed**

Advice Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #9** 2018-06-22 10:17**MOT test number** 153009787134**Result** ✗ Failed**Advice** Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #8** 2017-06-23 14:06**MOT test number** 352296945986**Result** ✓ Passed**Advice** O/s/r tyre punctured**Advice** N/s/r tyre has 3 punctures**MOT #7** 2016-05-10 10:07**MOT test number** 265462298150**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2015-05-11 10:40**MOT test number** 386791735140**Result** ✓ Passed**Notice** Diesel emission test but no reading recorded.**MOT #5** 2014-05-13 16:52**MOT test number** 877203734100**Result** ✓ Passed

**MOT #4**

2014-05-02 10:56

MOT test number

967732624165

Result**✗ Failed****Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Side repeater not working (1.4.A.2c)**Notice** Non obligatory mirror damaged**Fail** Offside Rear Shock absorber has a serious fluid leak (2.7.3)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #3**

2013-04-04 14:51

MOT test number

126334693429

Result**✓ Passed****Notice** Under-trays fitted obscuring some underside components**Notice** Both rear tyres worn on inner edges**MOT #2**

2012-02-13 10:41

MOT test number

386244142015

Result**✓ Passed****Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Both rear tyres going out of shape on inner edges



MOT #1	2012-02-13 10:41
MOT test number	717464442069
Result	✗ Failed
Notice	Both rear tyres going out of shape on inner edges
Pass with rectification	Nearside Rear position lamp(s) not working (1.1.A.3b)
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
28 January 2025

Tax status	Valid until 1 January
Days left	246
MOT expiry date	28 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-03-02
Last registration	2024-01-26
Complete history	See info



Registration #1	2009-03-02	24 mi
Registration #2	2012-02-13	70.939 mi
Registration #3	2013-04-04	105.866 mi
Registration #4	2014-05-02	107.984 mi
Registration #5	2014-05-13	108.678 mi
Registration #6	2015-05-11	113.269 mi
Registration #7	2016-05-10	121.291 mi
Registration #8	2017-06-23	133.781 mi
Registration #9	2018-06-22	138.007 mi
Registration #10	2019-06-22	142.233 mi
Registration #11	2020-06-22	146.459 mi
Registration #12	2021-06-22	150.685 mi
Registration #13	2022-06-22	154.911 mi
Registration #14	2023-06-22	159.137 mi
Registration #15	2024-01-26	163.363 mi
Registration #16	2024-01-26	163.363 mi
Registration #17	2024-01-26	163.363 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2066 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Kerb weight	1561 kg
Max. allowed weight	2260 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	7
Engine number	BKD C72007