



**RX65ZXN**


report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	POLO SE TSI
Colour	Black
Year of manufacture	2015
Top speed	114 mph
0 - 100 km/h	10.8 seconds
0 - 60 mph	10.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	66 kW / 90 HP / 89 BHP
Max. torque	160 Nm at 1.400 rpm
Engine capacity	1.197 cc
Cylinders	4
Fuel type	Petrol
Consumption city	47.1 mpg
Consumption extra urban	70.6 mpg
Consumption combined	60.1 mpg
CO2 emission	107 g/km
CO2 label	B






Internet history

Entry 2

Date	2021-09-11
Pictures	28
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



Entry 1

Date	2021-09-10
Pictures	28
Listing price	<a href="#">View report</a>



source: autotrader.co.uk





MOT history

MOT expiry date	2025-02-07
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	21
Total items failed	3

MOT #10	2024-02-08 11:27
---------	------------------

MOT test number	365407144983
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2025-02-07
------------------	------------

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge Also cracking and perishing (5.2.3 (e))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material connections flexi to hard line (1.1.11 (c))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #9**

2024-02-07 14:06

**MOT test number**

808973266838

**Result****✗ Failed**

**Advice** Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Fail** Nearside Rear Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Also cracking and perishing (5.2.3 (e))

**Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

**Advice** Offside Rear Brake pipe corroded, covered in grease or other material connections flexi to hard line (1.1.11 (c))

**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #8**

2022-08-30 10:27

**MOT test number**

659702053850

**Result****✓ Passed**

**Advice** Front Brake pad(s) wearing thin on the limit (1.1.13 (a) (ii))

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Rear Brake pad(s) wearing thin on the limit (1.1.13 (a) (ii))

**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened has a ridge on the disc (1.1.14 (a) (ii))

**MOT #7**

2021-09-09 12:39

**MOT test number**

419309891697

**Result****✓ Passed**

**MOT #6** 2020-10-16 09:43**MOT test number** 302370969533**Result** ✓ Passed**Advice** Undertrays fitted**MOT #5** 2019-10-05 09:10**MOT test number** 349429581533**Result** ✓ Passed**MOT #4** 2019-10-05 09:10**MOT test number** 468723537010**Result** ✗ Failed**Pass with rectification** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))**MOT #3** 2018-10-23 11:10**MOT test number** 879477715317**Result** ✓ Passed**MOT #2** 2018-09-19 08:12**MOT test number** 959181416932**Result** ✓ Passed**Advice** Engine under tray fitted**MOT #1** 2018-09-19 08:12**MOT test number** 821900835709**Result** ✗ Failed**Pass with rectification** Brake pedal anti-slip provision missing (1.1.2 (c))**Advice** Engine under tray fitted



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
7 February 2025

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	125
<b>MOT expiry date</b>	7 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<b>RX65ZXN</b>
Plate since	2019-03-28
Current registration	<b>RX65ZXN</b>
Plate since	2019-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2015-09-21
Last registration	2024-02-08
Complete history	<a href="#">See info</a>



Registration #1	2015-09-21	18 mi
Registration #2	2018-09-19	28.186 mi
Registration #3	2018-09-19	28.186 mi
Registration #4	2018-10-23	28.755 mi
Registration #5	2019-10-05	33.044 mi
Registration #6	2019-10-05	33.044 mi
Registration #7	2020-10-16	37.927 mi
Registration #8	2020-10-16	37.927 mi
Registration #9	2020-10-16	37.927 mi
Registration #10	2020-10-16	37.927 mi
Registration #11	2020-10-16	37.927 mi
Registration #12	2020-10-16	37.927 mi
Registration #13	2020-10-16	37.927 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	86%
Pedestrian	41%
Safety systems	71%
Overall rating	78%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1901 mm
Height	1462 mm
Length	3972 mm
Wheel base	2470 mm
Kerb weight	1007 kg
Max. allowed weight	1590 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5

Number of axles	2
Engine number	CJZC437240