



report date: 2024-03-29

General information

Make	FORD
Model	GALAXY GHIA TDDI
Colour	Silver
Year of manufacture	-
Top speed	124 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	150 BHP
Max. torque	310 Nm at 1.900 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	33.6 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.8 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-04
Pictures	16
Listing price	View report



source: autotrader.co.uk

**MOT history****MOT #22**

2022-01-12 16:33

MOT test number

815077186715

Result

✓ Passed

Next expiry date

2023-01-17

- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Gearbox mounting defective
- Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #21**

2022-01-11 17:01

MOT test number

218454063489

Result**✗ Failed**

- Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Gearbox mounting defective
- Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Fail** Nearside Front Anti-roll bar ball joint dust cover missing (5.3.4 (b) (ii))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #20

2021-01-18 15:31

MOT test number

709918303547

Result**✓ Passed**

- Advice** Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Nearside Front Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))



MOT #19	2020-02-25 12:38
MOT test number	527960290389
Result	✓ Passed
Advice	Rear Passenger seat(s) missing at time of test x 2

MOT #18	2020-02-25 10:16
MOT test number	228269922318
Result	✗ Failed
Fail	Nearside Rear Parking brake inoperative on one side (1.4.1 (a))
Fail	Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
Advice	Rear Passenger seat(s) missing at time of test x 2
Fail	Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #17	2019-03-01 12:54
MOT test number	320775213080
Result	✓ Passed
Minor	Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Minor	Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #16	2019-03-01 12:34
MOT test number	475174207713
Result	✗ Failed
Minor	Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Fail	Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
Fail	Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
Minor	Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #15**

2018-02-15 10:43

MOT test number

947818655393

Result

✓ Passed

Advice

Nearside Front Front constant velocity joint gaiter damaged, but preventing the ingress of dirt

(2.5.C.1a)

Advice

Nearside Front Macpherson strut has slight movement in the upper support bearing assembly

(2.5.B.1b)

Advice

Offside Front Front constant velocity joint gaiter damaged, but preventing the ingress of dirt

(2.5.C.1a)

Advice

Offside Front Macpherson strut has slight movement in the upper support bearing assembly

(2.5.B.1b)

MOT #14

2018-02-15 09:23

MOT test number

292737721626

Result

✗ Failed

Advice

Offside Front Macpherson strut has slight movement in the upper support bearing assembly

(2.5.B.1b)

Advice

Nearside Front Front constant velocity joint gaiter damaged, but preventing the ingress of dirt

(2.5.C.1a)

Advice

Nearside Front Macpherson strut has slight movement in the upper support bearing assembly

(2.5.B.1b)

Fail

Offside Rear rear brake binding (3.7.B.1)

Advice

Offside Front Front constant velocity joint gaiter damaged, but preventing the ingress of dirt

(2.5.C.1a)

MOT #13

2017-02-24 16:11

MOT test number

119130569360

Result

✓ Passed

MOT #12

2017-02-24 11:54

MOT test number

542314848816

Result

✗ Failed

Fail Central Exhaust has a major leak of exhaust gases (7.1.2)

Fail Rear Exhaust has a major leak of exhaust gases (7.1.2)



MOT #11	2016-02-19 09:44
MOT test number	248675123675
Result	✓ Passed
Advice	Exhaust has a minor leak of exhaust gases centre & rear (7.1.2)

MOT #10	2015-02-28 10:40
MOT test number	885799055013
Result	✓ Passed
Advice	Offside Front Brake hose slightly deteriorated (3.6.B.4d)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Notice	Under-trays fitted obscuring some underside components
Advice	Nearside Rear Shock absorber has a light misting of oil (2.7.3)
Notice	Passenger seat(s) missing at time of test
Advice	Nearside Front Brake hose slightly deteriorated (3.6.B.4d)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Notice	Engine covers fitted obscuring some components in the engine bay

**MOT #9** 2015-02-28 10:16**MOT test number** 778389955047**Result** ✗ Failed

- Notice** Under-trays fitted obscuring some underside components
- Advice** Offside Front Brake hose slightly deteriorated (3.6.B.4d)
- Notice** Passenger seat(s) missing at time of test
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)
- Advice** Offside Rear Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Nearside Front Brake hose slightly deteriorated (3.6.B.4d)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)

MOT #8 2014-02-17 10:41**MOT test number** 597328344014**Result** ✓ Passed

- Advice** Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)
- Advice** Nearside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)
- Advice** Offside Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

MOT #7 2013-03-04 12:38**MOT test number** 828993363005**Result** ✓ Passed

- Notice** Advise rear caliper service
- Notice** Advise cam belt

**MOT #6** 2012-03-01 13:59**MOT test number** 107911862049**Result** ✓ Passed**Notice** Advise caliper inspection rear**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Oil leak**Notice** Aux drive belt cracked**MOT #5** 2011-03-09 10:57**MOT test number** 126258161497**Result** ✗ Failed**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**MOT #4** 2011-03-09 10:57**MOT test number** 246168461002**Result** ✓ Passed**MOT #3** 2010-05-19 15:43**MOT test number** 564469230160**Result** ✓ Passed**Notice** Nail in offside front tyre**MOT #2** 2009-05-21 15:08**MOT test number** 241591149480**Result** ✓ Passed



MOT #1	2008-05-01 17:26
MOT test number	750082028143
Result	✓ Passed
<div>Notice</div> Rear tyres wearing on inner edges	



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2005-05-20
Last registration	2022-01-12
Complete history	See info



Registration #1	2005-05-20	6 mi
Registration #2	2008-05-01	32.370 mi
Registration #3	2009-05-21	43.598 mi
Registration #4	2010-05-19	51.585 mi
Registration #5	2011-03-09	54.192 mi
Registration #6	2012-03-01	63.066 mi
Registration #7	2013-03-04	68.060 mi
Registration #8	2014-02-17	76.749 mi
Registration #9	2015-02-28	90.079 mi
Registration #10	2015-02-28	90.079 mi
Registration #11	2016-02-19	99.865 mi
Registration #12	2017-02-24	110.617 mi
Registration #13	2018-02-24	121.369 mi
Registration #14	2019-02-24	132.121 mi
Registration #15	2020-02-24	142.873 mi
Registration #16	2021-02-24	153.625 mi
Registration #17	2022-02-24	164.377 mi
Registration #18	2023-02-24	175.129 mi
Registration #19	2024-02-24	185.881 mi
Registration #20	2025-02-24	196.633 mi
Registration #21	2026-02-24	207.385 mi
Registration #22	2027-02-24	218.137 mi
Registration #23	2028-02-24	228.889 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2142 mm
Height	1759 mm
Length	4641 mm
Wheel base	2835 mm
Kerb weight	1724 kg
Max. allowed weight	2510 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	5B11617