



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES
Model	VIANO CDI LONG AMBIENTE
Colour	Silver
Year of manufacture	2004
Top speed	108 mph
Gearbox	5 speed automatic

Engine & fuel consumption

Power	148 BHP
Max. torque	330 Nm at 2.000 rpm
Engine capacity	2.148 cc
Cylinders	4
Fuel type	Diesel
Consumption city	24.8 mpg
Consumption extra urban	39.2 mpg
Consumption combined	32.1 mpg
CO2 emission	232 g/km
CO2 label	L





Internet history

Entry 1

Date	2021-09-14
Pictures	20
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-05-02
MOT pass rate	73 %
MOT passed	16
Failed MOT tests	6
Total advice items	21
Total items failed	16

MOT #22	2023-05-03 11:00
MOT test number	537488274884
Result	✓ Passed
Next expiry date	2024-05-02
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #21	2023-04-27 13:46
MOT test number	580582703679
Result	✗ Failed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Nearside Front Inner Vehicle structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting sill (6.2.2 (d) (i))
Fail	Nearside Rear Brake pipe excessively corroded front to rear (1.1.11 (c))
Fail	Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Fail	Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
Fail	Offside Front Inner Vehicle structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting sill (6.2.2 (d) (i))
Fail	Offside Rear Brake pipe excessively corroded front to rear (1.1.11 (c))



MOT #20	2022-04-14 11:47
MOT test number	982198969380
Result	✓ Passed
Advice	Brake pipe corroded, covered in grease or other material ALL (1.1.11 (c))

MOT #19	2021-04-21 08:37
MOT test number	860181492625
Result	✓ Passed

MOT #18	2021-04-20 08:42
MOT test number	524487202635
Result	✗ Failed
Fail	Offside Rear Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))
Fail	Nearside Headlamp light intensity severely reduced (4.1.4 (a))
Fail	Nearside Rear Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))
Fail	Offside Headlamp light intensity severely reduced (4.1.4 (a))

MOT #17	2020-02-07 17:40
MOT test number	191013301748
Result	✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16	2019-01-21 15:42
MOT test number	940020511680
Result	✓ Passed
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #15**

2018-01-29 11:45

MOT test number

227548164843

Result

✓ Passed

Advice Front Headlamp has a product on the light source but not seriously reducing light output (1.7.5a)**Advice** Front Brake hose slightly deteriorated (3.6.B.4d)**Advice** Offside Front Anti-roll bar ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**Advice** Vehicle structure has slight corrosion (6.1.B.2)**MOT #14**

2018-01-29 11:45

MOT test number

137336584242

Result

✗ Failed

Advice Front Brake hose slightly deteriorated (3.6.B.4d)**Advice** Front Headlamp has a product on the light source but not seriously reducing light output (1.7.5a)**Advice** Offside Front Anti-roll bar ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**Advice** Vehicle structure has slight corrosion (6.1.B.2)**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #13**

2017-01-30 10:26

MOT test number

578505151043

Result

✓ Passed

MOT #12

2016-01-27 10:35

MOT test number

408495636832

Result

✓ Passed

**MOT #11** 2015-01-27 09:58**MOT test number** 657907225096**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #10** 2014-01-27 16:34**MOT test number** 658917324041**Result** ✓ Passed**MOT #9** 2013-01-28 10:24**MOT test number** 509268823096**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2012-01-31 14:23**MOT test number** 178311932445**Result** ✓ Passed**MOT #7** 2012-01-26 16:23**MOT test number** 456656122036**Result** ✗ Failed**Fail** Offside Rear Shock absorber has a serious fluid leak (2.7.3)**Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)**MOT #6** 2011-01-19 10:04**MOT test number** 699989511087**Result** ✓ Passed

**MOT #5** 2010-01-06 09:36**MOT test number** 481506100085**Result** ✓ Passed**MOT #4** 2010-01-06 09:36**MOT test number** 861686200069**Result** ✗ Failed**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**MOT #3** 2009-03-18 14:33**MOT test number** 884297579049**Result** ✓ Passed**MOT #2** 2007-10-26 12:25**MOT test number** 604779497256**Result** ✓ Passed**Notice** Near side rear lamp lens broken at lower section**MOT #1** 2007-10-26 12:25**MOT test number** 902079397259**Result** ✗ Failed**Pass with rectification** Offside Rear Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Registration plate not displaying a BSAU 145d marking (6.3.3b)**Notice** Near side rear lamp lens broken at lower section



Tax & MOT check

✓
Taxed

Tax due:
1 April 2025

✓
MOT

Expires:
2 May 2024

Tax status	Valid until 1 April
Days left	337
MOT expiry date	2 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 TV54MTV
Plate since	2024-03-28
Current registration	 TV54MTV
Plate since	2024-03-28

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2004-11-18
Last registration	2023-05-03
Complete history	See info



Registration #1	2004-11-18	17 mi
Registration #2	2007-10-26	43.986 mi
Registration #3	2009-03-18	59.288 mi
Registration #4	2010-01-06	72.759 mi
Registration #5	2011-01-19	81.090 mi
Registration #6	2012-01-26	87.163 mi
Registration #7	2012-01-31	87.190 mi
Registration #8	2013-01-28	94.705 mi
Registration #9	2014-01-27	101.901 mi
Registration #10	2015-01-27	110.894 mi
Registration #11	2016-01-27	120.137 mi
Registration #12	2016-05-20	121.277 mi
Registration #13	2016-05-20	121.277 mi
Registration #14	2016-05-20	121.277 mi
Registration #15	2016-05-20	121.277 mi
Registration #16	2016-05-20	121.277 mi
Registration #17	2016-05-20	121.277 mi
Registration #18	2016-05-20	121.277 mi
Registration #19	2016-05-20	121.277 mi
Registration #20	2016-05-20	121.277 mi
Registration #21	2016-05-20	121.277 mi
Registration #22	2016-05-20	121.277 mi

More info >



Dimensions & weight

Width	1906 mm
Height	1875 mm
Length	4993 mm
Wheel base	3200 mm
Kerb weight	2090 kg
Max. allowed weight	2940 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	8
Number of axles	2
Engine number	64698250086002